

Location: **Fort Bragg 499 E. Laurel**Bldg Name: **Site**Floor: **1**ID No: **3-8-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior northwest corner of Whipple and Laurel no curb ramps provided.</li> <li>• <i>Proposed Solution:</i> Coordinate provision of curb ramp with City of Fort Bragg.</li> </ul>	PCODE <b>EH01NT</b> ADAAG <b>4.7.1</b> CSAS <b>1127B.5.1</b> MoM <b>C.T.P.</b> O/R <b>County ADA Coordinator</b>	1	JOB	\$75	\$75	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 1-25 spaces, the number of accessible spaces is less than required by code; 1 space required</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking space with sign including a minimum of one van space.</li> </ul>	PCODE <b>EA01A</b> ADAAG <b>4.1.2(5)</b> CSAS <b>Tbl. 11B-6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 2 sec.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone amplification for hearing impaired persons not provided.</li> <li>• <i>Proposed Solution:</i> Provide telephone amplification for hearing impaired persons. To be provided by utility company.</li> </ul>	PCODE <b>IB05</b> ADAAG <b>4.31.5</b> CSAS <b>3105(d)2.1H</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1	JOB	\$0		<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door opening (32" min. clear) is more than 24" deep.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Relocate blue brochure bin to other side of column and move bookshelf towards window to provide 36" clear width.</li> </ul>	PCODE <b>ID18NT</b> ADAAG <b>4.13.5</b> CSAS <b>11B-33(a)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$550	\$550	<b>4.1</b>

Location: **Fort Bragg 499 E. Laurel**Bldg Name: **Library**Floor: **1**ID No: **3-8-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height greater than 48" to highest operable part (only front reach available).</li> <li>• <i>As-is Measurement:</i> 56"</li> <li>• <i>Proposed Solution:</i> Relocate telephone to within 48" reach (by utility company).</li> </ul>	PCODE <b>IB09</b> ADAAG <b>4.31.3</b> CSAS <b>1118B.5</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1	JOB	\$250	\$250	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Information desk or circulation counter or section not 36" max. high and min. 36" wide (CA only: top 28" to 34" high, min. 36" counter length).</li> <li>• <i>As-is Measurement:</i> 43"</li> <li>• <i>Proposed Solution:</i> Provide new accessible desk/counter section when remodeling area. Relocate or modify electrical outlets and equipment as needed. Interim: provide equivalent facilitation.</li> </ul>	PCODE <b>BE02</b> ADAAG <b>8.3</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$4,000	\$4,000	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Reach height to control or access point, where side approach is available, exceeds 54" or is less than 9".</li> <li>• <i>As-is Measurement:</i> 68"</li> <li>• <i>Proposed Solution:</i> Provide new coat hook at 48" height.</li> </ul>	PCODE <b>IE02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>

Location: **Fort Bragg 499 E. Laurel**Bldg Name: **Library**Floor: **1**ID No: **3-8-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Reach height to coat hook exceeds 48".</li> <li>• <i>As-is Measurement:</i> 68"</li> <li>• <i>Proposed Solution:</i> Provide new coat hook at 48" height.</li> </ul>	PCODE <b>IE02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$100	\$100	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Room with audible smoke alarm does not provide visual signal (strobe).</li> <li>• <i>Proposed Solution:</i> Provide combination visual / audible signal device. As an interim solution, advise staff to follow county emergency procedures regarding the evacuation of people with disabilities.</li> </ul>	PCODE <b>IC05A</b> ADAAG <b>4.28.3</b> CSAS <b>1114B.2.4</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$500	\$500	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 52"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair accessible route, at a door with both latch and closer, width of level and clear area at door push side does not extend 12" min. past the strike side edge.</li> <li>• <i>As-is Measurement:</i> 6"</li> <li>• <i>Proposed Solution:</i> Keep door fully open (90°) during business hours. Provide door operator when altering area.</li> </ul>	PCODE <b>ID09C</b> ADAAG <b>4.13.6</b> CSAS <b>Fig. 11B-26A(a)</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$2,500	\$2,500	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 2 sec.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>4.1</b>

Location: **Fort Bragg 499 E. Laurel**Bldg Name: **Library**Floor: **1**ID No: **3-8-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Reach height to coat hook exceeds 48".</li> <li>• <i>As-is Measurement:</i> 66"</li> <li>• <i>Proposed Solution:</i> Provide new coat hook at 48" height.</li> </ul>	PCODE <b>IE02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Clear floor space, 30" x 48" in front of fixture, extending 19" max. under the lavatory, not provided (CA only: Less than 18" from side wall to centerline of lavatory).</li> <li>• <i>As-is Measurement:</i> 28" x 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing lavatory.</li> </ul>	PCODE <b>WD01A</b> ADAAG <b>4.19.3</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</li> <li>• <i>As-is Measurement:</i> 17"</li> <li>• <i>Proposed Solution:</i> Provide new concrete ramp with handrails [slope more than 1:20 (5.0%) needed].</li> </ul>	PCODE <b>EB01A</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>General Service Director</b>	96	SF	\$100	\$9,600	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>4.1</b>

Location: **Covelo 76301 Main Street**Bldg Name: **Main**Floor: **1**ID No: **2-4-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$125	\$250	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Attorney/litigant table does not provide accessible seating space.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Modify table to provide accessible seating space.</li> </ul>	PCODE <b>JA08</b> ADAAG <b>11.2.1(5)</b> CSAS <b>3103A(c)2F(iv)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$400	\$400	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29.5"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 41"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>4.1</b>

Location: **Covelo 76301 Main Street**Bldg Name: **Main**Floor: **1**ID No: **2-4-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 43" x 76"</li> <li>• <i>Proposed Solution:</i> Remodel area to provide single-occupant accessible restroom. Increase overall room dimensions and relocate water heater. Alternative: Construct addition to existing building.</li> </ul>	PCODE <b>WA01</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>General Service Director</b>	1	JOB	\$15,000	\$15,000	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates abrupt change in level exceeding 1/2" in accessible route.</li> <li>• <i>As-is Measurement:</i> 2"</li> <li>• <i>Proposed Solution:</i> Remove, replace or repair area of pavement sufficient to correct abrupt change in level. Interim solution: Provide sign as itemized.</li> </ul>	PCODE <b>EF03</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	20	SF	\$21	\$420	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible parking space does not have 5' x 18' access aisle (van accessible aisle 8' x 18').</li> <li>• <i>Proposed Solution:</i> Modify parking space (s) to create accessible space by restriping.</li> </ul>	PCODE <b>EA02B</b> ADAAG <b>4.6.3</b> CSAS <b>1129B.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$200	\$400	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$175	\$350	<b>6.1</b>

Location: **Fort Bragg 790 S. Franklin**Bldg Name: **Site**Floor: **1**ID No: **3-7-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone: Clear floor space, 30" wide x 48" out from wall, not provided.</li> <li>• <i>Proposed Solution:</i> Contact telephone company to provide accessible telephone.</li> </ul>	PCODE <b>IB01NT</b> ADAAG <b>4.31.2</b> CSAS <b>1117B.2.2</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB			<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface of required maneuvering clearance at door slopes more than 1/4":12" (2.0%).</li> <li>• <i>As-is Measurement:</i> 6.5%</li> <li>• <i>Proposed Solution:</i> Modify surface slope at door. Interim solution: provide door bell for assistance.</li> </ul>	PCODE <b>ID11NT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>General Service Director</b>	160	SF	\$25	\$4,000	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface of required maneuvering clearance at door slopes more than 1/4":12" (2.0%).</li> <li>• <i>As-is Measurement:</i> 6.5%</li> <li>• <i>Proposed Solution:</i> Modify surface slope at door. Interim solution: provide door bell for assistance.</li> </ul>	PCODE <b>ID11NT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>General Service Director</b>	160	SF	\$25	\$4,000	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No van parking provided (one in every 8 accessible spaces, but not less than one. 8' wide access aisle, 98" height clearance).</li> <li>• <i>Proposed Solution:</i> Provide van parking space(s) by restriping; provide van sign.</li> </ul>	PCODE <b>EA07</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Cross slope more than 1/4":12" (2%).</li> <li>• <i>As-is Measurement:</i> 8%</li> <li>• <i>Proposed Solution:</i> Coordinate with City of Fort Bragg and modify cross slope.</li> </ul>	PCODE <b>EF07NT</b> ADAAG <b>4.3.7</b> CSAS <b>1133B.7.1.3</b> MoM <b>C.T.P.</b> O/R <b>County ADA Coordinator</b>	50	SF	\$12	\$600	<b>6.1</b>

Location: **Fort Bragg 790 S. Franklin**Bldg Name: **Site**Floor: **1**ID No: **3-7-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 12.8%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new curb ramp.</li> </ul>	PCODE <b>EH02A</b> ADAAG <b>4.7.2</b> CSAS <b>1127B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,500	\$2,500	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 11 Lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 41"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No visual smoke alarm.</li> <li>• <i>Proposed Solution:</i> Provide combination visual / audible signal device connected to existing fire alarm system. As an interim solution, advise staff to follow county emergency procedures regarding the evacuation of people with disabilities.</li> </ul>	PCODE <b>IC05NT</b> ADAAG <b>4.1.3(14) &amp; 4.28.3</b> CSAS <b>1114B.2.4</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$1,300	\$1,300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Corridor, for occupant load less than 10, less than 36" wide due to file cabinet.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Remove or relocate furniture and storage items.</li> </ul>	PCODE <b>IH03A</b> ADAAG <b>4.3.3</b> CSAS <b>3305(b)1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>1.1</b>



Location: **Fort Bragg 790 S. Franklin**

Bldg Name: **Mental Health**

Floor: **1**

ID No: **3-7-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No portable assistive listening system provided for small meeting room.</li> <li>• <i>Proposed Solution:</i> Provide portable assistive listening system, to be shared with other facilities.</li> </ul>	PCODE <b>GI01DREF</b> ADAAG <b>4.1.3 (19) (b)</b> MoM <b>Purchase and Policy</b> O/R <b>County ADA Coordinator</b>		REF			<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>6.1</b>

Location: **Fort Bragg 790 S. Franklin**Bldg Name: **Mental Health**Floor: **1**ID No: **3-7-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Provide new door closer.</li> </ul>	PCODE <b>WB05BNT</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$200	\$200	<b>2.1</b>

Location: **Fort Bragg 790 S. Franklin**

Bldg Name: **Mental Health**

Floor: **1**

ID No: **3-7-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Remove knob and latch. Provide u-pull locking device (without latch) and kick plate.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$350	\$350	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 27"x12"x26"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles not accessible or more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 48"</li> <li>• <i>Proposed Solution:</i> Provide or relocate specific restroom accessories.</li> </ul>	PCODE <b>WG01</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115.B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$150	\$300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 58"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>6.1</b>

Location: **Fort Bragg 790 S. Franklin**Bldg Name: **Mental Health**Floor: **1**ID No: **3-7-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 20.5"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE <b>WB02B</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Provide new door closer.</li> </ul>	PCODE <b>WB05BNT</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$200	\$200	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Remove knob and latch. Provide u-pull locking device (without latch) and kick plate.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$350	\$350	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 27"x12"x26"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>6.1</b>

Location: **Fort Bragg 790 S. Franklin**

Bldg Name: **Mental Health**

Floor: **1**

ID No: **3-7-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles not accessible or more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 48"</li> <li>• <i>Proposed Solution:</i> Provide or relocate specific restroom accessories.</li> </ul>	PCODE <b>WG01</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115.B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$150	\$300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 58"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No portable assistive listening system provided for small meeting room.</li> <li>• <i>Proposed Solution:</i> Provide portable assistive listening system, to be shared with other facilities.</li> </ul>	PCODE <b>GI01DREF</b> ADAAG <b>4.1.3 (19) (b)</b> MoM <b>Purchase and Policy</b> O/R <b>County ADA Coordinator</b>		REF			<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>6.1</b>

Location: **Fort Bragg 790 S. Franklin**Bldg Name: **WIC, 4-H**Floor: **1**ID No: **3-7-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles not accessible or more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 53"</li> <li>• <i>Proposed Solution:</i> Provide or relocate specific restroom accessories.</li> </ul>	PCODE <b>WG01</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115.B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$150	\$300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 58"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 32" from side of water closet to far side of stall wall or 28" to adjacent fixture.</li> <li>• <i>As-is Measurement:</i> 15"</li> <li>• <i>Proposed Solution:</i> Remove urinal, plug and cap. Relocate stall partition.</li> </ul>	PCODE <b>WB01NT</b> ADAAG <b>Fig. 28c</b> CSAS <b>1115B.7.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 21"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE <b>WB02B</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>6.1</b>

Location: **Fort Bragg 790 S. Franklin**Bldg Name: **WIC, 4-H**Floor: **1**ID No: **3-7-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Adjust closer.</li> </ul>	PCODE <b>WB05B</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock). Hardware on outside.</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05CNT</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not code compliant.</li> <li>• <i>Proposed Solution:</i> Relocate side grab bars and provide new back grab bar.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 27" x 12" x 28"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Locking requires twisting.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 6 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards and advise staff to keep door fully open (90°) during business hours.</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>6.1</b>

Location: **Fort Bragg 790 S. Franklin**Bldg Name: **WIC, 4-H**Floor: **1**ID No: **3-7-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>As-is Measurement:</i> 3"</li> <li>• <i>Proposed Solution:</i> Advise staff to keep door fully open (90°) during business hours.</li> </ul>	PCODE <b>ID14ANT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair accessible route, at a door with both latch and closer, width of level and clear area at door push side does not extend 12" min. past the strike side edge.</li> <li>• <i>As-is Measurement:</i> 5"</li> <li>• <i>Proposed Solution:</i> Remove doorstopper and advise staff to keep door unlatched during business hours.</li> </ul>	PCODE <b>ID09ANT</b> ADAAG <b>4.13.6</b> CSAS <b>Fig. 11B-26A(a)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>6.1</b>



Location: **Fort Bragg 499 E. Laurel**Bldg Name: **Site**Floor: **1**ID No: **3-8-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface of required maneuvering clearance at door slopes more than 1/4":12" (2.0%).</li> <li>• <i>As-is Measurement:</i> 4.6%</li> <li>• <i>Proposed Solution:</i> Demolish sloped concrete walk and provide new with compliant landing. Interim solution: Provide service bell to call for assistance.</li> </ul>	PCODE <b>ID11NT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,600	\$3,600	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$120	\$120	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$120	\$120	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No accessible street parking</li> <li>• <i>Proposed Solution:</i> Provide one accessible parking space on Laurel Street. Coordinate work with City of Fort Bragg.</li> </ul>	PCODE <b>EA01A</b> ADAAG <b>4.1.2(5)</b> CSAS <b>Tbl. 11B-6</b> MoM <b>C.T.P.</b> O/R <b>County ADA Coordinator</b>	1	JOB	\$300	\$300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Provide or adjust hinge closer.</li> </ul>	PCODE <b>WB05BNT</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Locking device requires twisting.</li> <li>• <i>Proposed Solution:</i> Provide accessible locking mechanism (flip-latch ok).</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$100	\$100	<b>2.1</b>

Location: **Fort Bragg 360 Harrison Avenue**Bldg Name: **Veterans Memorial**Floor: **1**ID No: **3-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No permanently installed assistive listening system provided for smaller assembly area (accommodating 50 to 200 persons).</li> <li>• <i>Proposed Solution:</i> County program is one on one.</li> </ul>	PCODE <b>G101AREF</b> ADAAG <b>4.1.3 (19) (b)</b> MoM <b>E. F.</b> O/R <b>County ADA Coordinator</b>		REF			<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Panic bars hard to operate.</li> <li>• <i>Proposed Solution:</i> Adjust panic bars and closers.</li> </ul>	PCODE <b>ID03NT</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$40	\$40	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No van parking provided (one in every 8 accessible spaces, but not less than one. 8' wide access aisle, 98" height clearance).</li> <li>• <i>Proposed Solution:</i> Provide van parking space(s) by restriping; provide van sign.</li> </ul>	PCODE <b>EA07</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No curb ramp available where an accessible route crosses a curb.</li> <li>• <i>Proposed Solution:</i> Contact City of Willits to coordinate provision of accessible path of travel from public transportation to facilities.</li> </ul>	PCODE <b>EH01NT</b> ADAAG <b>4.7.1</b> CSAS <b>1127B.5.1</b> MoM <b>C.T.P.</b> O/R <b>County ADA Coordinator</b>	1	JOB	\$75	\$75	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Cross slope more than 1/4":12" (2%).</li> <li>• <i>Proposed Solution:</i> Contact City of Willits to coordinate provision of accessible path of travel from public transportation to facilities.</li> </ul>	PCODE <b>EF07NT</b> ADAAG <b>4.3.7</b> CSAS <b>1133B.7.1.3</b> MoM <b>C.T.P.</b> O/R <b>County ADA Coordinator</b>	1	JOB	\$75	\$75	<b>3.2</b>

Location: **Willits 390 E. Commercial Street**Bldg Name: **Library**Floor: **1**ID No: **10-21-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Book deposit handle or deposit slot mounted higher than 54" above floor or walkway where side approach is possible.</li> <li>• <i>As-is Measurement:</i> 56"</li> <li>• <i>Proposed Solution:</i> Modify return policy for people using wheelchairs.</li> </ul>	PCODE <b>BE04NT</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.5</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 55"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>3.2</b>

Location: **Willits 390 E. Commercial Street**Bldg Name: **Library**Floor: **1**ID No: **10-21-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SCD: 40"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 48"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>3.2</b>

Location: **Willits 390 E. Commercial Street**Bldg Name: **Library**Floor: **1**ID No: **10-21-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Kitchenette sink rim higher than 34" above floor.</li> <li>• <i>Proposed Solution:</i> Remodel sink cabinet to lower sink.</li> </ul>	PCODE <b>IN06</b> ADAAG <b>4.24.2</b> CSAS <b>1117B.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,850	\$1,850	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Kitchenette sink faucet controls not accessible.</li> <li>• <i>Proposed Solution:</i> Provide accessible sink faucet controls.</li> </ul>	PCODE <b>IN07</b> ADAAG <b>4.24.7</b> CSAS <b>1508.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Study carrels or tables: Less than 5% have accessible height (28" to 34") and 27" clear knee space.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Provide accessible study carrel or worktable unit.</li> </ul>	PCODE <b>BE03</b> ADAAG <b>8.2</b> CSAS <b>1103B.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Department Head</b>	1	JOB	\$800	\$800	<b>3.2</b>

Location: **Willits 390 E. Commercial Street**Bldg Name: **Library**Floor: **1**ID No: **10-21-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Information desk or circulation counter or section not 36" max. high and min. 36" wide (CA only: top 28" to 34" high, min. 36" counter length).</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Provide new accessible desk/counter section when remodeling area. Relocate or modify electrical outlets and equipment as needed. Interim: provide equivalent facilitation.</li> </ul>	PCODE <b>BE02</b> ADAAG <b>8.3</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$4,000	\$4,000	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No van parking provided (one in every 8 accessible spaces, but not less than one. 8' wide access aisle, 98" height clearance).</li> <li>• <i>Proposed Solution:</i> Relocate one accessible parking stall to east row.</li> </ul>	PCODE <b>EA07NT</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$700	\$700	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Slope greater than 1:20 (5.0%), and walk does not comply with requirements for ramps.</li> <li>• <i>As-is Measurement:</i> 11%</li> <li>• <i>Proposed Solution:</i> Modify walk/sidewalk slope to 1:20 or less.</li> </ul>	PCODE <b>EF01</b> ADAAG <b>4.8.1</b> CSAS <b>1133B.7.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	40	SF	\$45	\$1,800	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Water collects on walk/sidewalk.</li> <li>• <i>Proposed Solution:</i> Fix gutter of canopy.</li> </ul>	PCODE <b>EF11NT</b> ADAAG <b>4.9.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$100	\$100	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk less than 36" wide.</li> <li>• <i>Proposed Solution:</i> Trim vegetation.</li> </ul>	PCODE <b>EF08ANT</b> ADAAG <b>4.3.3</b> CSAS <b>1133B.7.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>5.1</b>

Location: **Fort Bragg 120 W. Fir Street**Bldg Name: **Site**Floor: **1**ID No: **3-24-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directions posted at inaccessible entrance.</li> <li>• <i>Proposed Solution:</i> Install directional signage.</li> </ul>	PCODE <b>SA18</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 41"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03NT</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$500	\$1,000	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Information brochure bins mounted above accessible height.</li> <li>• <i>Proposed Solution:</i> Provide assistance or relocate at 48" max height.</li> </ul>	PCODE <b>IN06NT</b> ADAAG <b>4.2.5 &amp; 6</b> CSAS <b>1118B.5 &amp; 6</b> MoM <b>P. A. (In-house)</b> O/R <b>Department Head</b>	1	JOB	\$0		<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>

Location: **Fort Bragg 120 W. Fir Street**Bldg Name: **Public Health**Floor: **1**ID No: **3-24-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>As-is Measurement:</i> 4"</li> <li>• <i>Proposed Solution:</i> Interim solution: Keep door fully open (90°) during business hours.</li> </ul>	PCODE <b>ID14NT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$0		<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No signs at non-accessible exits directing persons to an accessible exit of the building.</li> <li>• <i>Proposed Solution:</i> Provide directional signage to indicate route to the nearest accessible exit.</li> </ul>	PCODE <b>SA14NT</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$230	\$230	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SCD: 51"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No signs at non-accessible exits directing persons to an accessible exit of the building.</li> <li>• <i>Proposed Solution:</i> Provide directional signage to indicate route to the nearest accessible exit.</li> </ul>	PCODE <b>SA14NT</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$230	\$230	<b>5.1</b>



Location: **Fort Bragg 120 W. Fir Street**Bldg Name: **Public Health**Floor: **1**ID No: **3-24-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No signs at non-accessible exits directing persons to an accessible exit of the building.</li> <li>• <i>Proposed Solution:</i> Provide directional signage to indicate route to the nearest accessible exit.</li> </ul>	PCODE <b>SA14NT</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$230	\$230	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 57"x43"</li> <li>• <i>Proposed Solution:</i> Accessible restroom is provided. Convert Women's into unisex restroom.</li> </ul>	PCODE <b>WA0IREF</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>		REF			<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at non-accessible room or space directing persons to an accessible that provides the same or equivalent service.</li> <li>• <i>Proposed Solution:</i> Provide directional sign to accessible restroom.</li> </ul>	PCODE <b>SA19</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at non-accessible room or space directing persons to an accessible that provides the same or equivalent service.</li> <li>• <i>Proposed Solution:</i> Provide directional sign to accessible restroom.</li> </ul>	PCODE <b>SA19</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at non-accessible room or space directing persons to an accessible that provides the same or equivalent service.</li> <li>• <i>Proposed Solution:</i> Provide directional sign to accessible restroom.</li> </ul>	PCODE <b>SA19</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>2.1</b>

Location: **Willits 189 N. Main Street**Bldg Name: **Site**Floor: **1**ID No: **10-25-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 1-25 spaces, the number of accessible spaces is less than required by code; 1 space required</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking space with sign including a minimum of one van space.</li> </ul>	PCODE <b>EA01A</b> ADAAG <b>4.1.2(5)</b> CSAS <b>Tbl. 11B-6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Water collects on walk/sidewalk.</li> <li>• <i>Proposed Solution:</i> Fill and compress potholes to provide alternative route for item 2.</li> </ul>	PCODE <b>EF11NT</b> ADAAG <b>4.9.6</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	50	SF	\$15	\$750	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Paved area has excessively rough, irregular surface.</li> <li>• <i>Proposed Solution:</i> Repave area to provide smooth surface for path of travel.</li> </ul>	PCODE <b>EF10AREF</b> ADAAG <b>4.5.1</b> CSAS <b>1133B.7.1</b>		REF			<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Tiled walkway has grid openings wider than 1/2".</li> <li>• <i>Proposed Solution:</i> Remove, replace or repair area of pavement sufficient to correct abrupt change in level. Interim: alternative route is provided. See item 1.</li> </ul>	PCODE <b>EF03NT</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	120	SF	\$21	\$2,520	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign by inaccessible route directing persons to an accessible route.</li> <li>• <i>Proposed Solution:</i> Provide directional sign.</li> </ul>	PCODE <b>SA20</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>7.1</b>

Location: **Willits 189 N. Main Street**Bldg Name: **Site**Floor: **1**ID No: **10-25-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates abrupt change in level exceeding 1/2" in accessible route.</li> <li>• <i>As-is Measurement:</i> 0.5"</li> <li>• <i>Proposed Solution:</i> Remove, replace or repair area of pavement sufficient to correct abrupt change in level.</li> </ul>	PCODE <b>EF03REF</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b>		REF			<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access to basement cafeteria. (Indoor lift not possible).</li> <li>• <i>As-is Measurement:</i> 82"</li> <li>• <i>Proposed Solution:</i> Provide new concrete ramp with handrails [slope more than 1:20 (5.0%) needed] or driveway for shuttle.</li> </ul>	PCODE <b>EB01ANT</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	420	SF	\$100	\$42,000	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 20 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 61"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone amplification for hearing impaired persons not provided.</li> <li>• <i>Proposed Solution:</i> Provide telephone amplification for hearing impaired persons. To be provided by utility company.</li> </ul>	PCODE <b>IB05</b> ADAAG <b>4.31.5</b> CSAS <b>3105(d)2.1H</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1		\$0		<b>7.1</b>

Location: **Willits 189 N. Main Street**Bldg Name: **Main**Floor: **1**ID No: **10-25-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Multiple accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 78" x 106"</li> <li>• <i>Proposed Solution:</i> Convert multi accommodation to single accommodation.</li> </ul>	PCODE <b>WA01AREF</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.1</b>		REF			<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Install lever handle hardware without latch. Provide accessible locking device (flip-latch ok) when converting restroom into single accommodation.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door opening less than 32" clear (CA only: ...or less than 34" at side entry door).</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Remove existing partition and convert facility into single accommodation. Remodel floor and walls as needed.</li> </ul>	PCODE <b>WB05ANT</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 60"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>7.1</b>

Location: **Willits 189 N. Main Street**Bldg Name: **Main**Floor: **1**ID No: **10-25-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 43"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 57"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01AREF</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b>		REF			<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 36"</li> <li>• <i>Proposed Solution:</i> Remove existing partition and convert facility into single accommodation.</li> </ul>	PCODE <b>WB06REF</b> ADAAG <b>4.17.3</b>		REF			<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$80	\$80	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Front approach: At pull side, door does not have clear and level maneuvering space measuring door width plus 18" x 60" (CA only: exterior door width plus 24").</li> <li>• <i>Proposed Solution:</i> Remove privacy partition. Patch walls and floor as needed.</li> </ul>	PCODE <b>ID23A</b> ADAAG <b>Fig. 25(a)</b> CSAS <b>11B-26A(a)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>2.1</b>

Location: **Willits 189 N. Main Street**Bldg Name: **Main**Floor: **1**ID No: **10-25-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 0.75"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles not accessible or more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 60"</li> <li>• <i>Proposed Solution:</i> Provide specific restroom</li> </ul>	PCODE <b>WG01</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115.B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 60" x 106"</li> <li>• <i>Proposed Solution:</i> Convert facility to provide accessible single-occupancy restroom.</li> </ul>	PCODE <b>WA0IREF</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b>		REF			7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges and trim frame.</li> </ul>	PCODE <b>ID01NT</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Install lever handle hardware without latch. Provide accessible locking device (flip-latch ok) when converting restroom into single accommodation.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	2.1

Location: **Willits 189 N. Main Street**Bldg Name: **Main**Floor: **1**ID No: **10-25-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 37"</li> <li>• <i>Proposed Solution:</i> Remove partition.</li> </ul>	PCODE <b>WB06REF</b> ADAAG <b>4.17.3</b>		REF			<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door opening less than 32" clear (CA only: ...or less than 34" at side entry door).</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Remove stall. Remodel floor and walls as needed.</li> </ul>	PCODE <b>WB05A</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$80	\$80	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 27.5"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>7.1</b>

Location: **Willits 189 N. Main Street**Bldg Name: **Main**Floor: **1**ID No: **10-25-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 52"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stage, enclosed and unenclosed platform, backstage areas or orchestra pit not accessible.</li> <li>• <i>As-is Measurement:</i> 10"</li> <li>• <i>Proposed Solution:</i> Construct ramp to raised platforms. Interim solution: Provide portable ramp.</li> </ul>	PCODE <b>GC01B</b> ADAAG <b>4.33.5</b> CSAS <b>1104B.3.10</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	10	LF	\$400	\$4,000	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Pair of doors on accessible route has less than 32" clear opening width with one leaf open 90°.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, unequal width door leafs in existing frame for pair of doors.</li> </ul>	PCODE <b>ID08A</b> ADAAG <b>4.13.4</b> CSAS <b>1133B.2.3.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 0.5"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>7.1</b>



Location: **Willits 189 N. Main Street**Bldg Name: **Main**Floor: **Bsmt**ID No: **10-25-1-0**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> CA only: At exterior door on wheelchair-accessible route, width of level and clear area at door swing side does not extend 24" past the strike side edge.</li> <li>• <i>As-is Measurement:</i> 5"</li> <li>• <i>Proposed Solution:</i> Change door swing, coordinate with proposed exterior ramp.</li> </ul>	PCODE <b>ID10</b> CSAS <b>11B-26A(a)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$460	\$460	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign by inaccessible route directing persons to an accessible route.</li> <li>• <i>Proposed Solution:</i> Provide directional sign at bottom.</li> </ul>	PCODE <b>SA20NT</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$170	\$170	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible parking space has slope greater than 1/4":12" (2%).</li> <li>• <i>As-is Measurement:</i> 4%</li> <li>• <i>Proposed Solution:</i> Relocate both stalls to west end of A-2 parking lot and provide new curb ramp.</li> </ul>	PCODE <b>EA05NT</b> ADAAG <b>4.6.3</b> CSAS <b>1129B.4.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$1,500	\$3,000	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible parking space(s) not located close to the nearest possible entrance on an accessible route.</li> <li>• <i>Proposed Solution:</i> Relocate accessible parking space(s).</li> </ul>	PCODE <b>EA06REF</b> ADAAG <b>4.6.2</b> CSAS <b>1129B.1</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Van sign installed at wrong stall.</li> <li>• <i>Proposed Solution:</i> Switch sign to adjacent stall.</li> </ul>	PCODE <b>EA04BREF</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b>		REF			<b>8.1</b>

Location: Ukiah 860 N. Bush Street

Bldg Name: Site

Floor: 1

ID No: 9-28-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directional signage provided to accessible entrance at existing sign.</li> <li>• <i>Proposed Solution:</i> Indicate direction (right) to guide visitors using wheelchairs to accessible main entrance.</li> </ul>	PCODE SA01NT ADAAG 35.163(b) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$230	\$230	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Built-up curb ramp projects into traffic lane.</li> <li>• <i>Proposed Solution:</i> Paint curb ramp.</li> </ul>	PCODE EH06NT ADAAG 4.7.6 CSAS 1127B.5.1 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$500	\$500	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Van sign installed at wrong stall.</li> <li>• <i>Proposed Solution:</i> Switch sign to adjacent stall.</li> </ul>	PCODE EA04B ADAAG 4.6.4 CSAS 1129B.5 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$175	\$175	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: No flared sides provided.</li> <li>• <i>Proposed Solution:</i> Provide 10% sloped asphalt flares.</li> </ul>	PCODE EH05ANT ADAAG 4.7.5 CSAS 1127B.5.3 MoM P. A. (Contractor) O/R Manager B&G 2	1	JOB	\$250	\$250	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage at bottom of ramp sufficient to guide persons to accessible entrances.</li> </ul>	PCODE SA01 ADAAG 35.163(b) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$120	\$120	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at inaccessible ramp directing persons to an accessible route.</li> <li>• <i>Proposed Solution:</i> Provide sign at top of ramp stating "Too Steep!" include a sign directing persons to an accessible route.</li> </ul>	PCODE SA22 ADAAG 35.163(b) MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$150	\$150	8.1

Location: Ukiah 860 N. Bush Street

Bldg Name: Site

Floor: 1

ID No: 9-28-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage at bottom of stairs sufficient to guide persons to accessible entrances.</li> </ul>	PCODE SA01 ADAAG 35.163(b) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$120	\$120	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE SA01 ADAAG 35.163(b) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$120	\$120	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At fire-pull: reach height for front approach to control or access point over an obstruction with 29" min. knee clearance and 25" max. deep exceeds 44".</li> <li>• <i>As-is Measurement:</i> 50"</li> <li>• <i>Proposed Solution:</i> Relocate sign-in table.</li> </ul>	PCODE IE01ANT ADAAG Fig. 5(b) CSAS Tbl. 11B-5C(b) MoM P. A. (In-house) O/R Department Head	1	JOB	\$75	\$75	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE SA12 ADAAG 4.1.2(7)(c) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	1.1

Location: **Ukiah 860 N. Bush Street**

Bldg Name: **Administration**

Floor: **1**

ID No: **9-28-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign designating a permanent room or space does not include Grade 2 Braille.</li> <li>• <i>Proposed Solution:</i> Provide new compliant signage including California Grade 2 Braille.</li> </ul>	PCODE <b>SA07A</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign with the international symbol of accessibility at inaccessible restroom.</li> <li>• <i>Proposed Solution:</i> Remove misleading sign.</li> </ul>	PCODE <b>SA11NT</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at non-accessible room or space directing persons to an accessible that provides the same or equivalent service.</li> <li>• <i>Proposed Solution:</i> Provide directional sign to accessible restrooms at front lobby.</li> </ul>	PCODE <b>SA19NT</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$90	\$90	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign with the international symbol of accessibility at inaccessible restroom.</li> <li>• <i>Proposed Solution:</i> Remove misleading sign.</li> </ul>	PCODE <b>SA11NT</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at non-accessible room or space directing persons to an accessible that provides the same or equivalent service.</li> <li>• <i>Proposed Solution:</i> Provide directional sign to accessible restrooms at front lobby.</li> </ul>	PCODE <b>SA19NT</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$90	\$90	<b>2.1</b>

Location: Ukiah 860 N. Bush Street

Bldg Name: Administration

Floor: 1

ID No: 9-28-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 18 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>2.1</b>

Location: Ukiah 860 N. Bush Street

Bldg Name: Administration

Floor: 1

ID No: 9-28-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>Proposed Solution:</i> At this location, the program does not include services to persons in wheelchairs. Remodel restroom as needed when services are offered to persons in wheelchairs or when facility is being altered or renovated. Provide directional sign to indicate</li> </ul>	PCODE <b>WA01</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$90	\$90	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Shower does not comply with ADAAG 4.21.</li> <li>• <i>Proposed Solution:</i> At this location, the program does not include services to persons in wheelchairs. Remodel restroom as needed when services are offered to persons in wheelchairs or when facility is being altered or renovated.</li> </ul>	PCODE <b>WF01REF</b> ADAAG <b>4.21.2</b> CSAS <b>1115B.6.2</b>		REF			8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 18 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	2.1

Location: **Ukiah 860 N. Bush Street**

Bldg Name: **Administration**

Floor: **1**

ID No: **9-28-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<p>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</p> <p>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</p>	<p>PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b></p>	1	JOB	\$600	\$600	<b>8.1</b>
	<p>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</p> <p>• <i>Proposed Solution:</i> At this location, the program does not include services to persons in wheelchairs. Remodel restroom as needed when services are offered to persons in wheelchairs or when facility is being altered or renovated. Provide directional sign to indicate</p>	<p>PCODE <b>WA0INT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b></p>	1	JOB	\$90	\$90	<b>2.1</b>
	<p>• <i>As-Built Description:</i> Signage: No "Tow Away" sign at parking lot entrance (required in CA only).</p> <p>• <i>Proposed Solution:</i> Coordinate provision with City of Ukiah (see also facility report # 364).</p>	<p>PCODE <b>EA04CREF</b> CSAS <b>1129B.5</b> MoM <b>C.T.P.</b> O/R <b>County ADA Coordinator</b></p>		REF			<b>5.1</b>
	<p>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility on right door.</p> <p>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</p>	<p>PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b></p>	1	JOB	\$25	\$25	<b>5.1</b>
	<p>• <i>As-Built Description:</i> At push side of framed glass or panel door on accessible route, bottom 10" does not have a smooth, uninterrupted surface (required in CA only).</p> <p>• <i>Proposed Solution:</i> As an interim solution, provide 10" min. "kick plate" covering width of door on both sides of door leaf.</p>	<p>PCODE <b>ID06NT</b> CSAS <b>1133B.2.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b></p>	1	JOB	\$90	\$90	<b>1.1</b>

Location: **Ukiah 175 S. School Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-31-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directions posted at inaccessible entrance.</li> <li>• <i>Proposed Solution:</i> Provide sign directing people to accessible entrance on School Street.</li> </ul>	PCODE <b>SA18</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to toilet or bathing facility identified with California signage on door leaf not identified with ADAAG compliant signage.</li> <li>• <i>Proposed Solution:</i> Provide ADAAG compliant sign mounted 5' high on center on nearest adjacent wall, on latch side if a single door (located not to cause a Braille reader to stand within the door swing).</li> </ul>	PCODE <b>SA11A</b> ADAAG <b>4.1.2(7)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$90	\$90	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	3.1



Location: **Ukiah 841 Low Gap Road**Bldg Name: **Main**Floor: **1**ID No: **9-32-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Overhead clearance less than 80" above finished floor.</li> <li>• <i>As-is Measurement:</i> 55"</li> <li>• <i>Proposed Solution:</i> Hang metal chain from wall cabinet to mark low overhead area.</li> </ul>	PCODE <b>EG01A</b> ADAAG <b>4.4.2</b> CSAS <b>1121B.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Reach height to control or access point, where only forward approach is available, exceeds 48 or is less than 15".</li> <li>• <i>As-is Measurement:</i> 64"</li> <li>• <i>Proposed Solution:</i> Provide additional coat hook at 48" height.</li> </ul>	PCODE <b>IE01NT</b> ADAAG <b>4.2.5</b> CSAS <b>1118B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Rear grab bar less than 36" long.</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide accessible rear grab bar.</li> </ul>	PCODE <b>WB07B</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar starts more than 12" from back wall.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Relocate existing grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 26.5"</li> <li>• <i>Proposed Solution:</i> Remove lavatory counter and door closer. Provide new accessible lavatory fixture.</li> </ul>	PCODE <b>WD03AREF</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b>		REF			<b>9.1</b>

Location: **Ukiah 841 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-32-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 50"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side approach: less than 54" clear space perpendicular to closed door with closer or 48" without closer at swing side (CA only: ... 60").</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Remove lavatory counter and door closer. Provide new accessible lavatory fixture.</li> </ul>	PCODE <b>ID15FNT</b> ADAAG <b>Fig. 25</b> CSAS <b>1133B.2.4.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,400	\$2,400	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to toilet or bathing facility identified with California signage on door leaf not identified with ADAAG compliant signage.</li> <li>• <i>Proposed Solution:</i> Provide ADAAG compliant sign mounted 5' high on center on nearest adjacent wall, on latch side if a single door (located not to cause a Braille reader to stand within the door swing).</li> </ul>	PCODE <b>SA11A</b> ADAAG <b>4.1.2(7)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$90	\$90	<b>9.1</b>

Location: **Ukiah 841 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-32-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Reach height to control or access point, where only forward approach is available, exceeds 48 or is less than 15".</li> <li>• <i>As-is Measurement:</i> 60"</li> <li>• <i>Proposed Solution:</i> Provide additional coat hook at 48" height.</li> </ul>	PCODE <b>IE01NT</b> ADAAG <b>4.2.5</b> CSAS <b>1118B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Rear grab bar less than 36" long.</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide accessible rear grab bar.</li> </ul>	PCODE <b>WB07B</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 26"</li> <li>• <i>Proposed Solution:</i> Provide or relocate accessible side grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 26"</li> <li>• <i>Proposed Solution:</i> Remove lavatory counter and door closer. Provide new accessible lavatory fixture.</li> </ul>	PCODE <b>WD03AREF</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b>		REF			<b>9.1</b>

Location: **Ukiah 841 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-32-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 46"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side approach: less than 54" clear space perpendicular to closed door with closer or 48" without closer at swing side (CA only: ... 60").</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Remove lavatory counter and door closer. Provide new accessible lavatory fixture.</li> </ul>	PCODE <b>ID15FNT</b> ADAAG <b>Fig. 25</b> CSAS <b>1133B.2.4.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,400	\$2,400	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Van parking provided at wrong side of 8' access aisle.</li> <li>• <i>Proposed Solution:</i> Remove symbol on pavement and relocate sign on post to left side of aisle. Apply symbol on pavement.</li> </ul>	PCODE <b>EA07NT</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface of required maneuvering clearance at door slopes more than 1/4":12" (2.0%).</li> <li>• <i>As-is Measurement:</i> 4%</li> <li>• <i>Proposed Solution:</i> Modify surface slope at door.</li> </ul>	PCODE <b>ID11NT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	128	SF	\$20	\$2,560	<b>9.1</b>

Location: Ukiah 841 Low Gap Road

Bldg Name: Site

Floor: 1

ID No: 9-32-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<p>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</p> <p>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</p>	<p>PCODE SA12</p> <p>ADAAG 4.1.2(7)(c)</p> <p>CSAS 1117B.5.7</p> <p>MoM P. A. (In-house)</p> <p>O/R Manager B&amp;G 1</p>	1	JOB	\$25	\$25	9.1
	<p>• <i>As-Built Description:</i> No visitor parking provided at facility.</p> <p>• <i>Proposed Solution:</i> Provide accessible parking on street at main entrance. Paint red curb blue and provide signage "Solid Waste Division - Accessible Visitor Parking Only - 30 min Limit - Parking in Both Directions Allowed"</p>	<p>PCODE EA06NT</p> <p>ADAAG 4.6.2</p> <p>CSAS 1129B.1</p> <p>MoM P. A. (In-house)</p> <p>O/R General Service Director</p>	1	JOB	\$350	\$350	1.1
	<p>• <i>As-Built Description:</i> No sign by inaccessible route directing persons to an accessible route.</p> <p>• <i>Proposed Solution:</i> Provide directional sign.</p>	<p>PCODE SA20</p> <p>ADAAG 35.163(b)</p> <p>MoM P. A. (In-house)</p> <p>O/R Manager B&amp;G 1</p>	1	JOB	\$100	\$100	9.1
	<p>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</p> <p>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</p>	<p>PCODE SA12</p> <p>ADAAG 4.1.2(7)(c)</p> <p>CSAS 1117B.5.7</p> <p>MoM P. A. (In-house)</p> <p>O/R Manager B&amp;G 1</p>	1	JOB	\$50	\$50	9.1
	<p>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</p> <p>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</p>	<p>PCODE ID07</p> <p>ADAAG 4.13.9</p> <p>CSAS 1133B.2.5.1</p> <p>MoM P. A. (In-house)</p> <p>O/R Manager B&amp;G 2</p>	1	JOB	\$125	\$125	9.1

Location: **Ukiah 559 Low Gap Road**Bldg Name: **Portables**Floor: **1**ID No: **9-34-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface of required maneuvering clearance at door slopes more than 1/4":12" (2.0%).</li> <li>• <i>As-is Measurement:</i> 5.5%</li> <li>• <i>Proposed Solution:</i> Provide power-assisted door operator. Interim solution: Provide door bell to call for assistance at accessible location.</li> </ul>	PCODE <b>ID11NT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$5,000	\$5,000	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Otherwise compliant sign identifying permanent room or space not mounted 5' high to center on nearest adjacent wall, on latch side if a single door (located not to cause a Braille reader to stand within the door</li> <li>• <i>Proposed Solution:</i> Relocate existing sign.</li> </ul>	PCODE <b>SA07</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Floor-mounted closer (internal). Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Disable floor-mounted closing mechanism and install new, door-mounted closer.</li> </ul>	PCODE <b>ID03B</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>10.1</b>

Location: **Ukiah 880 N. Bush Street**

Bldg Name: **Public Health Annex**

Floor: **1**

ID No: **9-35-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li><i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>10.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li><i>As-is Measurement:</i> 0.5"</li> <li><i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>10.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Door lock or latch more than 48" above the floor (CA only: 30" to 44").</li> <li><i>As-is Measurement:</i> 60"</li> <li><i>Proposed Solution:</i> Relocate or replace existing</li> </ul>	PCODE <b>ID17</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>10.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li><i>As-is Measurement:</i> 9 lbs.</li> <li><i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>3.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li><i>As-is Measurement:</i> 28.5"</li> <li><i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>10.1</b>

Location: Ukiah 880 N. Bush Street

Bldg Name: Public Health Annex

Floor: 1

ID No: 9-35-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 44"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 43"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	3.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 32" from side of water closet to far side of stall wall or 28" to adjacent fixture.</li> <li>• <i>As-is Measurement:</i> 14"</li> <li>• <i>Proposed Solution:</i> Remove adjacent fixture and stall partitions. Remodel restroom as needed.</li> </ul>	PCODE <b>WB01ANT</b> ADAAG <b>Fig. 28c</b> CSAS <b>1115B.7.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	3.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 15"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	10.1



Location: **Ukiah 880 N. Bush Street**

Bldg Name: **Public Health Annex**

Floor: **1**

ID No: **9-35-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 63"x135"</li> <li>• <i>Proposed Solution:</i> Change to staff restroom and provide signage indicating the availability of an accessible public restroom to the left. Relocate baby changing station.</li> </ul>	PCODE <b>WA01NT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$250	\$250	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Remove van sign at non-van parking.</li> </ul>	PCODE <b>EA04BNT</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$315	\$315	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 10%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new curb ramp.</li> </ul>	PCODE <b>EH02A</b> ADAAG <b>4.7.2</b> CSAS <b>1127B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,500	\$2,500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope not steep but greater than 1:20 (5.0 %) without handrails.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Provide steel handrails for ramp.</li> </ul>	PCODE <b>EB03</b> ADAAG <b>4.8.1*</b> CSAS <b>1133B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	75	LF	\$75	\$5,625	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone amplification for hearing impaired persons not provided.</li> <li>• <i>Proposed Solution:</i> Provide telephone amplification for hearing impaired persons. To be provided by utility company.</li> </ul>	PCODE <b>IB05</b> ADAAG <b>4.31.5</b> CSAS <b>3105(d)2.1H</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1		\$0		<b>9.1</b>

Location: **Ukiah 890 N. Bush Street**Bldg Name: **Site**Floor: **1**ID No: **9-36-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 55"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$120	\$120	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Floor-mounted closer (internal). Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Disable floor-mounted closing mechanism and install new, door-mounted closer.</li> </ul>	PCODE <b>ID03B</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>1.1</b>

Location: Ukiah 890 N. Bush Street

Bldg Name: Public Health Office

Floor: 1

ID No: 9-36-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE SA11 ADAAG 4.1.2(7)(d) CSAS 1117B.5.9 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$45	\$45	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Notch out vanity header board.</li> </ul>	PCODE WD03ANT ADAAG 4.19.2 CSAS 1504.2.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$150	\$150	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 32" from side of water closet to far side of stall wall or 28" to adjacent fixture.</li> <li>• <i>As-is Measurement:</i> 13"</li> <li>• <i>Proposed Solution:</i> Remove half-high partition wall. Remodel wall and floor as needed.</li> </ul>	PCODE WB01NT ADAAG Fig. 28c CSAS 1115B.7.3 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$600	\$600	3.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE WB10 ADAAG 4.16.5 & 4.27.4 CSAS 1502.0 MoM P. A. (Contractor) O/R Manager B&G 2	1	JOB	\$500	\$500	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	9.1

Location: Ukiah 890 N. Bush Street

Bldg Name: Public Health Office

Floor: 1

ID No: 9-36-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	9.1

Location: **Ukiah 890 N. Bush Street**Bldg Name: **Public Health Office**Floor: **1**ID No: **9-36-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone: Clear floor space, 30" wide x 48" out from wall, not provided.</li> <li>• <i>Proposed Solution:</i> Provide clear space in front of telephone, 30" wide x 48" out from wall.</li> </ul>	PCODE <b>IB01NT</b> ADAAG <b>4.31.2</b> CSAS <b>1117B.2.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 56"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (Contractor)</b> O/R <b>Department Head</b>	1	JOB	\$250	\$250	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 11%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new curb ramp.</li> </ul>	PCODE <b>EH02A</b> ADAAG <b>4.7.2</b> CSAS <b>1127B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,500	\$2,500	<b>5.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Site**

Floor: **1**

ID No: **9-39-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At shared parking lot with 101-150 spaces, the number of accessible spaces is less than required by code; 5 spaces required.</li> <li>• <i>As-is Measurement:</i> 125 T</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking spaces with signs including a minimum of one van space.</li> </ul>	PCODE <b>EA01ENT</b> ADAAG <b>4.1.2(5)*</b> CSAS <b>Tbl. 11B-6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$300	\$600	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Remount counter shelf. Patch wall.</li> </ul>	PCODE <b>IN03NT</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Jail Administration**

Floor: **1**

ID No: **9-39-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At push side of framed glass or panel door on accessible route, bottom 10" does not have a smooth, uninterrupted surface (required in CA only).</li> <li>• <i>Proposed Solution:</i> Remove door stopper and mail drop box.</li> </ul>	PCODE <b>ID06NT</b> CSAS <b>1133B.2.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$75	\$75	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 16 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> After-Hours-Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 65"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Business-Hours-Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 66"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>As-is Measurement:</i> 9"</li> <li>• <i>Proposed Solution:</i> Remove or relocate furniture or storage items.</li> </ul>	PCODE <b>ID14A</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Department Head</b>	1	JOB	\$50	\$50	2.1

Location: **Willits 125 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-44-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Rear grab bar less than 36" long.</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide accessible rear grab bar.</li> </ul>	PCODE <b>WB07B</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Self-closing faucet at accessible lavatory does not remain open for at least 10 seconds.</li> <li>• <i>As-is Measurement:</i> 4 sec</li> <li>• <i>Proposed Solution:</i> Adjust self-closing faucet at accessible lavatory.</li> </ul>	PCODE <b>WD07</b> ADAAG <b>4.19.5</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28.5"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Furniture protrudes into clear and level space.</li> <li>• <i>Proposed Solution:</i> Inform staff to relocate furniture to next room on an as needed basis.</li> </ul>	PCODE <b>WDNT</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 47"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>4.1</b>



Location: **Willits 125 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-44-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Kitchenette sink faucet controls not accessible.</li> <li>• <i>Proposed Solution:</i> Provide accessible sink faucet controls.</li> </ul>	PCODE <b>IN07</b> ADAAG <b>4.24.7</b> CSAS <b>1508.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Kitchenette sink rim higher than 34" above floor.</li> <li>• <i>As-is Measurement:</i> 36"</li> <li>• <i>Proposed Solution:</i> Remodel sink cabinet to lower sink.</li> </ul>	PCODE <b>IN06</b> ADAAG <b>4.24.2</b> CSAS <b>1117B.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,850	\$1,850	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign designating a permanent room or space does not include Grade 2 Braille.</li> <li>• <i>Proposed Solution:</i> Provide new compliant signage including California Grade 2 Braille.</li> </ul>	PCODE <b>SA07A</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone amplification for hearing impaired persons not provided.</li> <li>• <i>Proposed Solution:</i> Provide telephone amplification for hearing impaired persons. To be provided by utility company.</li> </ul>	PCODE <b>IB05</b> ADAAG <b>4.31.5</b> CSAS <b>3105(d)2.1H</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1		\$0		<b>4.1</b>

Location: **Willits 125 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-44-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Outside call button not accessible.</li> <li>• <i>As-is Measurement:</i> 60"</li> <li>• <i>Proposed Solution:</i> Provide additional call button and speaker-phone at 40" height.</li> </ul>	PCODE <b>IE02NT</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Jury box does not have at least one accessible wheelchair space within box area.</li> <li>• <i>Proposed Solution:</i> Remove fixed seats and/or modify seating area to provide required wheelchair space; provide readily removable seating.</li> </ul>	PCODE <b>JA02</b> ADAAG <b>11.2.1(2)</b> CSAS <b>3103A(C)2F(IV)</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible route to jury box not provided.</li> <li>• <i>As-is Measurement:</i> 8"</li> <li>• <i>Proposed Solution:</i> Provide ramp to jury box level.</li> </ul>	PCODE <b>JA02A</b> ADAAG <b>11.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	8	LF	\$200	\$1,600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible route to jury box not provided.</li> <li>• <i>As-is Measurement:</i> 3"</li> <li>• <i>Proposed Solution:</i> Enlarge or clear accessible route to jury box.</li> </ul>	PCODE <b>JA02C</b> ADAAG <b>11.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Witness stand does not have at least one accessible wheelchair space within witness area.</li> <li>• <i>Proposed Solution:</i> Modify witness stand to provide proper knee clearance.</li> </ul>	PCODE <b>JA03NT</b> ADAAG <b>11.2.1(2)</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$800	\$800	<b>4.1</b>

Location: **Willits 125 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-44-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Fixed seating area for spectators or the press does not have adequate wheelchair space.</li> <li>• <i>As-is Measurement:</i> 54"</li> <li>• <i>Proposed Solution:</i> Remove fixed seats from locations needed to provide wheelchair spaces; modify area as needed.</li> </ul>	PCODE <b>JA04</b> ADAAG <b>11.2.1(3)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	0	JOB	\$500		<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Attorney and litigant table does not provide accessible seating space.</li> <li>• <i>Proposed Solution:</i> Modify table to provide accessible seating space.</li> </ul>	PCODE <b>JA08</b> ADAAG <b>11.2.1(5)</b> CSAS <b>3103A(c)2F(iv)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$400	\$800	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Designated accessible holding cell not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide sign that shows international symbol at accessible holding cell entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>Proposed Solution:</i> Provide 48" long accessible side grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No rear grab bar provided.</li> <li>• <i>Proposed Solution:</i> Provide rear grab bar.</li> </ul>	PCODE <b>WB07FNT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$340	\$340	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new accessible unit.</li> </ul>	PCODE <b>WD03ANT</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,000	\$2,000	<b>4.1</b>

Location: **Willits 125 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-44-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$125	\$250	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone amplification for hearing impaired persons not provided.</li> <li>• <i>Proposed Solution:</i> Provide telephone amplification for hearing impaired persons. To be provided by utility company.</li> </ul>	PCODE <b>IB05</b> ADAAG <b>4.31.5</b> CSAS <b>3105(d)2.1H</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1		\$0		<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Call buttons in lobby / hall not centered 3'-6" above floor.</li> <li>• <i>As-is Measurement:</i> 37"</li> <li>• <i>Proposed Solution:</i> Provide new or relocate elevator call buttons to 3'-6" above floor at exterior landing.</li> </ul>	PCODE <b>IK09</b> ADAAG <b>4.10.3</b> CSAS <b>5103 (d.1) 8.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	FLR	\$450	\$450	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Otherwise compliant sign identifying permanent room or space not mounted 5' high to center on nearest adjacent wall, on latch side if a single door (located not to cause a Braille reader to stand within the door)</li> <li>• <i>As-is Measurement:</i> 64"</li> <li>• <i>Proposed Solution:</i> Relocate existing sign.</li> </ul>	PCODE <b>SA07</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	4	JOB	\$25	\$100	<b>4.1</b>

Location: **Willits 125 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-44-1-2**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign designating a permanent room or space does not include Grade 2 Braille.</li> <li>• <i>Proposed Solution:</i> Provide new compliant signage including California Grade 2 Braille.</li> </ul>	PCODE <b>SA07A</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	4	JOB	\$45	\$180	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>As-is Measurement:</i> 16.5"</li> <li>• <i>Proposed Solution:</i> Change door swing.</li> </ul>	PCODE <b>ID14</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$460	\$460	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 45"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Fixture rim or counter height more than 34" above floor.</li> <li>• <i>As-is Measurement:</i> 35"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD02A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Modify vanity to accessible height.</li> </ul>	PCODE <b>WD03ANT</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>4.1</b>

Location: **Willits 125 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-44-1-2**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Self-closing faucet at accessible lavatory does not remain open for at least 10 seconds.</li> <li>• <i>As-is Measurement:</i> 5 sec</li> <li>• <i>Proposed Solution:</i> Adjust self-closing faucet at accessible lavatory.</li> </ul>	PCODE <b>WD07</b> ADAAG <b>4.19.5</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Urinal flush control lever more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>As-is Measurement:</i> 47"</li> <li>• <i>Proposed Solution:</i> Provide accessible urinal flush control.</li> </ul>	PCODE <b>WE03</b> ADAAG <b>4.18.4</b> CSAS <b>1503.2 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accessible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" or more than 19" from floor.</li> <li>• <i>As-is Measurement:</i> 19.5"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet.</li> </ul>	PCODE <b>WB08</b> ADAAG <b>4.16.3</b> CSAS <b>1502 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,400	\$1,400	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Rear grab bar less than 36" long.</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide accessible rear grab bar.</li> </ul>	PCODE <b>WB07B</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>4.1</b>

Location: **Willits 125 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-44-1-2**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Seat cover dispenser directly above rear grab bar.</li> <li>• <i>Proposed Solution:</i> Relocate seat cover dispenser.</li> </ul>	PCODE <b>WG01ANT</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>As-is Measurement:</i> 16.5"</li> <li>• <i>Proposed Solution:</i> Change door swing.</li> </ul>	PCODE <b>ID14</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$460	\$460	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 45"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Fixture rim or counter height more than 34" above floor.</li> <li>• <i>As-is Measurement:</i> 35"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD02A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Modify vanity to accessible height.</li> </ul>	PCODE <b>WD03ANT</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>4.1</b>

Location: **Willits 125 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-44-1-2**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Self-closing faucet at accessible lavatory does not remain open for at least 10 seconds.</li> <li>• <i>As-is Measurement:</i> 5 sec</li> <li>• <i>Proposed Solution:</i> Adjust self-closing faucet at accessible lavatory.</li> </ul>	PCODE <b>WD07</b> ADAAG <b>4.19.5</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accessible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" or more than 19" from floor.</li> <li>• <i>As-is Measurement:</i> 19.5"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet.</li> </ul>	PCODE <b>WB08</b> ADAAG <b>4.16.3</b> CSAS <b>1502 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,400	\$1,400	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Rear grab bar less than 36" long.</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide accessible rear grab bar.</li> </ul>	PCODE <b>WB07B</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Seat cover dispenser directly above rear grab bar.</li> <li>• <i>Proposed Solution:</i> Relocate seat cover dispenser.</li> </ul>	PCODE <b>WG01ANT</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	<b>2.1</b>



Location: **Willits 125 E. Commercial Street**Bldg Name: **Site**Floor: **1**ID No: **10-44-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No van parking provided (one in every 8 accessible spaces, but not less than one. 8' wide access aisle, 98" height clearance).</li> <li>• <i>Proposed Solution:</i> Provide van parking space(s) by restriping; provide van sign.</li> </ul>	PCODE <b>EA07</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates vertical change in level between 1/4" and 1/2" in accessible route.</li> <li>• <i>As-is Measurement:</i> 0.5"</li> <li>• <i>Proposed Solution:</i> Grind or fill pavement dislocation to create beveled transition.</li> </ul>	PCODE <b>EF03A</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	4	SF	\$21	\$84	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible parking space does not have 5' x 18' access aisle (van accessible aisle 8' x 18').</li> <li>• <i>As-is Measurement:</i> 4' aisle</li> <li>• <i>Proposed Solution:</i> Modify parking space (s) to create accessible space by restriping.</li> </ul>	PCODE <b>EA02B</b> ADAAG <b>4.6.3</b> CSAS <b>1129B.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$200	\$400	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Insufficient number of accessible holding cells provided.</li> <li>• <i>Proposed Solution:</i> Provide at least two percent, but not less than one, accessible holding cells in a facility. Interim: use med-observation cell as designated wheelchair accessible holding cell instead.</li> </ul>	PCODE <b>DC01NT</b> ADAAG <b>12.4.1</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$12,000	\$12,000	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet in designated accessible holding cell is not fully accessible.</li> <li>• <i>Proposed Solution:</i> Remodel institutional toilet to be accessible.</li> </ul>	PCODE <b>DC05NT</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,000	\$3,000	<b>2.1</b>

Location: **Ukiah 975 Low Gap Road**

Bldg Name: **Detention Facility # 2**

Floor: **1**

ID No: **9-45-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible holding cell is not fully accessible.</li> <li>• <i>Proposed Solution:</i> Remodel cell to be fully accessible.</li> </ul>	PCODE <b>DC05NT</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,000	\$3,000	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Minimum of one wheelchair seating space at fixed table not provided.</li> <li>• <i>Proposed Solution:</i> Remove one built-in seat from institutional metal table.</li> </ul>	PCODE <b>DD05</b> ADAAG <b>12.5.2 (6)</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$550	\$550	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Shower in designated accessible holding cell is not accessible.</li> <li>• <i>Proposed Solution:</i> Remodel institutional shower to be accessible.</li> </ul>	PCODE <b>DC03NT</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$5,000	\$5,000	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Shower in designated accessible holding cell is not accessible.</li> <li>• <i>Proposed Solution:</i> Remodel institutional shower to be accessible.</li> </ul>	PCODE <b>DC03NT</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$5,000	\$5,000	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Minimum of one wheelchair seating space at fixed table not provided.</li> <li>• <i>Proposed Solution:</i> Remove one built-in seat from institutional metal table.</li> </ul>	PCODE <b>DD05</b> ADAAG <b>12.5.2 (6)</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$550	\$550	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible holding cell is not fully accessible.</li> <li>• <i>Proposed Solution:</i> Remodel cell to be fully accessible.</li> </ul>	PCODE <b>DC05NT</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,000	\$3,000	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible holding cell is not fully accessible.</li> <li>• <i>Proposed Solution:</i> Remodel cell to be fully accessible.</li> </ul>	PCODE <b>DC05NT</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,000	\$3,000	<b>2.1</b>

Location: **Ukiah 975 Low Gap Road**

Bldg Name: **Detention Facility # 2**

Floor: **1**

ID No: **9-45-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Minimum of one wheelchair seating space at fixed table not provided.</li> <li>• <i>Proposed Solution:</i> Remove one built-in seat from institutional metal table.</li> </ul>	PCODE <b>DD05</b> ADAAG <b>12.5.2 (6)</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$550	\$550	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Shower in designated accessible holding cell is not accessible.</li> <li>• <i>Proposed Solution:</i> Remodel institutional shower to be accessible.</li> </ul>	PCODE <b>DC03NT</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$5,000	\$5,000	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door to common restroom.</li> <li>• <i>As-is Measurement:</i> 20 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Minimum of one wheelchair seating space at fixed table not provided.</li> <li>• <i>Proposed Solution:</i> Remove one built-in seat from institutional metal table.</li> </ul>	PCODE <b>DD05</b> ADAAG <b>12.5.2 (6)</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$550	\$550	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Shower in designated accessible holding cell is not accessible.</li> <li>• <i>Proposed Solution:</i> Remodel institutional shower to be accessible.</li> </ul>	PCODE <b>DC03NT</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$5,000	\$5,000	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide new, 48" wide wood ramp with handrails [slope more than 1:20 (5.0%) needed]. Interim: program modification.</li> </ul>	PCODE <b>EB01B</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	37	LF	\$210	\$7,770	<b>3.1</b>

Location: Ukiah 860 N. Bush Street

Bldg Name: Site

Floor: 1

ID No: 9-49-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	11	LF	\$95	\$1,045	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No van parking provided (one in every 8 accessible spaces, but not less than one. 8' wide access aisle, 98" height clearance).</li> <li>• <i>Proposed Solution:</i> Check Facility Report #36 for all parking and site issues.</li> </ul>	PCODE <b>EA07REF</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b>		REF			
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Landing not as wide as the ramp run leading to it.</li> <li>• <i>Proposed Solution:</i> Demolish existing landing and provide new level landing.</li> </ul>	PCODE <b>EB06</b> ADAAG <b>4.8.4(1)</b> CSAS <b>1133B.5.4.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	100	SF	\$45	\$4,500	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: No curb (2" minimum height) or wheel guide (centered approx. 3" above surface of ramp) at sides of ramp.</li> <li>• <i>Proposed Solution:</i> Provide 2" minimum curb or wheel guide.</li> </ul>	PCODE <b>EB14</b> ADAAG <b>4.8.7</b> CSAS <b>1133B.5.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	17	LF	\$10	\$170	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED0INT</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	6	LF	\$10	\$60	<b>8.1</b>

Location: **Covelo Airport Road**

Bldg Name: **Community Center**

Floor: **1**

ID No: **2-227-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 23"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE <b>WB02B</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate partition to create 60"-wide stall. Relocate urinal and plumbing.</li> </ul>	PCODE <b>WB06NT</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>8.1</b>

Location: **Covelo Airport Road**

Bldg Name: **Community Center**

Floor: **1**

ID No: **2-227-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 60"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 57"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>8.1</b>

Location: **Covelo Airport Road**

Bldg Name: **Community Center**

Floor: **1**

ID No: **2-227-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 60"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 57"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Fixture rim or counter height more than 34" above floor.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD02A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>8.1</b>

Location: **Covelo Airport Road**

Bldg Name: **Site**

Floor: **1**

ID No: **2-227-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 26-50 spaces, the number of accessible spaces is less than required by code; 2 spaces required.</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking spaces with signs including a minimum of one van space.</li> </ul>	PCODE <b>EA01B</b> ADAAG <b>4.1.2(5)*</b> CSAS <b>Tbl. 11B-6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$300	\$600	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 20%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp with handrails.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	44	SF	\$100	\$4,400	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 1-25 spaces, the number of accessible spaces is less than required by code; 1 space required</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking space with sign including a minimum of one van space. Apply stripping on 1/4" gravel.</li> </ul>	PCODE <b>EA01A</b> ADAAG <b>4.1.2(5)</b> CSAS <b>Tbl. 11B-6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 10%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp with handrails.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	120	SF	\$100	\$12,000	<b>4.1</b>



Location: **Leggett Drive Thru Tree Road**

Bldg Name: **Modular**

Floor: **1**

ID No: **6-313-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$125	\$250	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Attorney and litigant table does not provide accessible seating space.</li> <li>• <i>As-is Measurement:</i> 26.5"</li> <li>• <i>Proposed Solution:</i> Modify table to provide accessible seating space.</li> </ul>	PCODE <b>JA08</b> ADAAG <b>11.2.1(5)</b> CSAS <b>3103A(c)2F(iv)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No assistive listening system provided for courtroom or other assembly area requiring communication security.</li> <li>• <i>Proposed Solution:</i> Share with other facilities.</li> </ul>	PCODE <b>G101CREF</b> ADAAG <b>4.1.3 (19) (b)</b> MoM <b>Purchase and Policy</b> O/R <b>County ADA Coordinator</b>		REF			<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation. Interim solution: Provide writing board.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage. Include phone number.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>

Location: **Leggett Drive Thru Tree Road**

Bldg Name: **Dome**

Floor: **1**

ID No: **6-313-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Pull-side of door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide "U-pull" or other accessible hardware.</li> </ul>	PCODE <b>ID07B</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Pair of doors on accessible route has less than 32" clear opening width with one leaf open 90°.</li> <li>• <i>As-is Measurement:</i> 29"</li> <li>• <i>Proposed Solution:</i> Provide new, unequal width door leafs in existing frame for pair of doors. Interim solution: Keep door fully open (90°) during business hours.</li> </ul>	PCODE <b>ID08A</b> ADAAG <b>4.13.4</b> CSAS <b>1133B.2.3.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>4.1</b>

Location: **Leggett Drive Thru Tree Road**

Bldg Name: **Dome**

Floor: **1**

ID No: **6-313-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 3"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Paper towel dispenser not at an accessible location.</li> <li>• <i>Proposed Solution:</i> Relocate paper towel dispenser to accessible location.</li> </ul>	PCODE <b>WG01ANT</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Adjust closer.</li> </ul>	PCODE <b>WB05B</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>

Location: **Leggett Drive Thru Tree Road**

Bldg Name: **Dome**

Floor: **1**

ID No: **6-313-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 3"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 55"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Adjust closer.</li> </ul>	PCODE <b>WB05B</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>

Location: **Leggett Drive Thru Tree Road**

Bldg Name: **Dome**

Floor: **1**

ID No: **6-313-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>Proposed Solution:</i> Turn mirror 90°.</li> </ul>	PCODE <b>WG03NT</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$75	\$75	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No van parking provided (one in every 8 accessible spaces, but not less than one. 8' wide access aisle, 98" height clearance).</li> <li>• <i>Proposed Solution:</i> Provide van parking space(s) by restriping; provide van sign.</li> </ul>	PCODE <b>EA07</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Crossing of vehicular traffic lane not marked as crosswalk.</li> <li>• <i>Proposed Solution:</i> Paint diagonal stripping at back of accessible parking space.</li> </ul>	PCODE <b>EA09ANT</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	10	LF	\$30	\$300	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Landing less than 60" long.</li> <li>• <i>As-is Measurement:</i> 55"</li> <li>• <i>Proposed Solution:</i> Modify ramp landing.</li> </ul>	PCODE <b>EB07</b> ADAAG <b>4.8.4(2)</b> CSAS <b>1133B.5.4.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	10	SF	\$45	\$450	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	42	LF	\$95	\$3,990	<b>8.1</b>

Location: **Willits 1784/1788 S. Main Street**Bldg Name: **Site**Floor: **1**ID No: **10-321-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Pavement dislocation creates abrupt change in level exceeding 1/2" in ramp.</li> <li>• <i>As-is Measurement:</i> 0.5"</li> <li>• <i>Proposed Solution:</i> Remove, replace or repair area of pavement sufficient to correct abrupt change in level.</li> </ul>	PCODE <b>EB04</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	5	SF	\$9	\$45	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates vertical change in level between 1/4" and 1/2" in accessible route.</li> <li>• <i>As-is Measurement:</i> 0.5"</li> <li>• <i>Proposed Solution:</i> Grind or fill pavement dislocation to create beveled transition.</li> </ul>	PCODE <b>EF03A</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	4	SF	\$21	\$84	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Pavement dislocation creates abrupt change in level exceeding 1/2" in ramp.</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Remove, replace or repair area of pavement sufficient to correct abrupt change in level.</li> </ul>	PCODE <b>EB04</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	5	SF	\$9	\$45	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Landing less than 60" long.</li> <li>• <i>Proposed Solution:</i> Modify ramp landing.</li> </ul>	PCODE <b>EB07</b> ADAAG <b>4.8.4(2)</b> CSAS <b>1133B.5.4.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	10	SF	\$45	\$450	<b>8.1</b>

Location: **Willits 1784/1788 S. Main Street** Bldg Name: **Site** Floor: **1** ID No: **10-321-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	36	LF	\$95	\$3,420	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$120	\$120	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$120	\$120	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 22%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp with handrails.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	85	SF	\$100	\$8,500	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Public entrance not accessible to disabled persons.</li> <li>• <i>Proposed Solution:</i> Install door bell at accessible location.</li> </ul>	PCODE <b>ID04NT</b> ADAAG <b>4.14.1</b> CSAS <b>1134B.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB			<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign designating a permanent room or space does not include Grade 2 Braille.</li> <li>• <i>Proposed Solution:</i> Provide new compliant signage including California Grade 2 Braille.</li> </ul>	PCODE <b>SA07ANT</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$90	\$90	<b>7.1</b>

Location: **Ukiah 419-M Talmage Road**Bldg Name: **Suite M**Floor: **1**ID No: **9-345-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 44"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 60" diameter or T-shaped space provided for wheelchair turns.</li> <li>• <i>As-is Measurement:</i> 57"</li> <li>• <i>Proposed Solution:</i> Move counter and gate.</li> </ul>	PCODE <b>IN04NT</b> ADAAG <b>4.2.3</b> CSAS <b>1118B.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 49"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 22"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet and relocate plumbing.</li> </ul>	PCODE <b>WB02A</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,600	\$4,600	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 50"</li> <li>• <i>Proposed Solution:</i> Relocate side grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Rear grab bar less than 36" long.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Provide accessible rear grab bar.</li> </ul>	PCODE <b>WB07B</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>7.1</b>



Location: **Ukiah 419-M Talmage Road**Bldg Name: **Suite M**Floor: **1**ID No: **9-345-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Pull force at accessible lavatory faucet exceeds 5 Lbs.</li> <li>• <i>Proposed Solution:</i> Adjust pull force at accessible lavatory faucet to 5 lbs max.</li> </ul>	PCODE <b>WD07A</b> ADAAG <b>4.19.5</b> CSAS <b>1504.2..1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Corridor, for occupant load less than 10, less than 36" wide.</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Remove or relocate furniture and storage items.</li> </ul>	PCODE <b>IH03A</b> ADAAG <b>4.3.3</b> CSAS <b>3305(b)1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$175	\$175	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible parking space has slope greater than 1/4":12" (2%).</li> <li>• <i>As-is Measurement:</i> 5%</li> <li>• <i>Proposed Solution:</i> Modify slope at accessible parking space.</li> </ul>	PCODE <b>EA05NT</b> ADAAG <b>4.6.3</b> CSAS <b>1129B.4.4</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,500	\$2,500	<b>7.1</b>

Location: Ukiah 419-M Talmage Road

Bldg Name: Site

Floor: 1

ID No: 9-345-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 10%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp with handrails.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	40	SF	\$100	\$4,000	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign by inaccessible route directing persons to an accessible route.</li> <li>• <i>Proposed Solution:</i> Provide directional sign.</li> </ul>	PCODE <b>SA20</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 15%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp with handrails.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	180	SF	\$45	\$8,100	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>Proposed Solution:</i> Install door bell for assistance and provide handrailing.</li> </ul>	PCODE <b>EB02NT</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$175	\$175	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Several sidewalk sections and curb ramps serving this location aren't compliant.</li> <li>• <i>Proposed Solution:</i> Contact City of Fort Bragg to coordinate barrier removal project.</li> </ul>	PCODE <b>EF07NT</b> ADAAG <b>4.3.7</b> CSAS <b>1133B.7.1.3</b> MoM <b>C.T.P.</b> O/R <b>County ADA Coordinator</b>	1	JOB	\$50	\$50	<b>9.1</b>

Location: **Fort Bragg 306 Redwood Avenue**

Bldg Name: **Office Complex**

Floor: **1**

ID No: **3-359**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation. Interim: provide clipboard.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>

Location: **Fort Bragg 306 Redwood Avenue**Bldg Name: **Office Complex**Floor: **1**ID No: **3-359**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>Proposed Solution:</i> Provide signage to direct clients to accessible restroom.</li> </ul>	PCODE <b>WA01NT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>Proposed Solution:</i> Provide signage to direct clients to accessible restroom.</li> </ul>	PCODE <b>WA01NT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>9.1</b>

Location: **Fort Bragg 306 Redwood Avenue**

Bldg Name: **Office Complex**

Floor: **1**

ID No: **3-359**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 9 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet and relocate plumbing.</li> </ul>	PCODE <b>WB02A</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,600	\$4,600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>9.1</b>

Location: **Fort Bragg 306 Redwood Avenue**Bldg Name: **Office Complex**Floor: **1**ID No: **3-359**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 49"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Rear grab bar too short.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Provide rear grab bar.</li> </ul>	PCODE <b>WB07FNT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$340	\$340	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Remove partition. Patch floor and walls as needed.</li> </ul>	PCODE <b>WB06NT</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 9 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>

Location: **Fort Bragg 306 Redwood Avenue**Bldg Name: **Office Complex**Floor: **1**ID No: **3-359**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet and relocate plumbing.</li> </ul>	PCODE <b>WB02A</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,600	\$4,600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 49"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Rear grab bar too short.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Provide rear grab bar.</li> </ul>	PCODE <b>WB07FNT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$340	\$340	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Remove partition. Patch floor and walls as needed.</li> </ul>	PCODE <b>WB06NT</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>3.1</b>

Location: **Laytonville 44400 Willits Road** Bldg Name: **Site** Floor: **1** ID No: **5-380-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 9.7%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp with handrails.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	60	SF	\$100	\$6,000	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface at swing side of door slopes more than 1:12.</li> <li>• <i>Proposed Solution:</i> Modify surface slope at door. Interim: assistance.</li> </ul>	PCODE <b>ID11NT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	80	SF	\$12	\$960	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards. Interim solution: Keep door fully open (90°) during business hours.</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>3.1</b>



Location: **Willits 390 E. Commercial Street**Bldg Name: **Site**Floor: **1**ID No: **10-21-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp does not have side flares.</li> <li>• <i>Proposed Solution:</i> Provide new side flares with 1:10 max. slope.</li> </ul>	PCODE <b>EH05ANT</b> ADAAG <b>4.7.5</b> CSAS <b>1127B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 47"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>As-is Measurement:</i> 14"</li> <li>• <i>Proposed Solution:</i> Change door swing.</li> </ul>	PCODE <b>ID14</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$460	\$460	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware. Interim solution: Schedule client visits in accessible meeting room if needed.</li> </ul>	PCODE <b>ID0INT</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware. Interim solution: Schedule client visits in accessible meeting room if needed.</li> </ul>	PCODE <b>ID0INT</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>8.1</b>

Location: **Laytonville 44400 Willits Road**Bldg Name: **Hardwood Hall**Floor: **1**ID No: **5-380-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Adjust closer.</li> </ul>	PCODE <b>WB05B</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 36"</li> <li>• <i>Proposed Solution:</i> Provide or relocate accessible side grab bar.</li> </ul>	PCODE <b>WB07A</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SCD: 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone: Clear floor space, 30" wide x 48" out from wall, not provided.</li> <li>• <i>Proposed Solution:</i> Move telephone 14" forward.</li> </ul>	PCODE <b>IB01NT</b> ADAAG <b>4.31.2</b> CSAS <b>1117B.2.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone amplification for hearing impaired persons not provided.</li> <li>• <i>Proposed Solution:</i> Provide telephone amplification for hearing impaired persons. To be provided by utility company.</li> </ul>	PCODE <b>IB05</b> ADAAG <b>4.31.5</b> CSAS <b>3105(d)2.1H</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1		\$0		<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height greater than 48" to highest operable part (only front reach available).</li> <li>• <i>As-is Measurement:</i> 54"</li> <li>• <i>Proposed Solution:</i> Relocate telephone to within 48" reach.</li> </ul>	PCODE <b>IB09REF</b> ADAAG <b>4.31.3</b> CSAS <b>3105(d)2.1F</b>		REF			<b>3.2</b>

Location: **Ukiah 105 N. Main Street**Bldg Name: **Site**Floor: **1**ID No: **9-29-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Book deposit handle or deposit slot mounted higher than 54" above floor or walkway where side approach is possible.</li> <li>• <i>As-is Measurement:</i> 57"</li> <li>• <i>Proposed Solution:</i> Modify/remount book deposit unit at accessible height. Interim solution: Modify return policy for people using wheelchairs.</li> </ul>	PCODE <b>BE04</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.5</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,000	\$3,000	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates abrupt change in level exceeding 1/2" in accessible route.</li> <li>• <i>As-is Measurement:</i> 0.5"</li> <li>• <i>Proposed Solution:</i> Fill in two missing tiles.</li> </ul>	PCODE <b>EF03NT</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Cross slope more than 1/4":12" (2%).</li> <li>• <i>As-is Measurement:</i> 7%</li> <li>• <i>Proposed Solution:</i> Modify cross slope.</li> </ul>	PCODE <b>EF07NT</b> ADAAG <b>4.3.7</b> CSAS <b>1133B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	50	SF	\$45	\$2,250	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Cross slope more than 1/4":12" (2%).</li> <li>• <i>As-is Measurement:</i> 9%</li> <li>• <i>Proposed Solution:</i> Modify cross slope.</li> </ul>	PCODE <b>EF07NT</b> ADAAG <b>4.3.7</b> CSAS <b>1133B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	50	SF	\$45	\$2,250	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Deactivate existing closer and provide new door closer adjusted to accessible standards.</li> </ul>	PCODE <b>ID03ANT</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$425	\$425	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Doormat hinders access for disabled persons.</li> <li>• <i>Proposed Solution:</i> Attach door mat to floor surface or remove unneeded door mat.</li> </ul>	PCODE <b>ID05A</b> ADAAG <b>4.5.3</b> CSAS <b>1124B.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$75	\$75	<b>3.2</b>

Location: Ukiah 105 N. Main Street

Bldg Name: Main

Floor: 1

ID No: 9-29-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE SA12 ADAAG 4.1.2(7)(c) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	3.2
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> "Ring Bell for Service" on top of 41 inches high counter.</li> <li>• <i>As-is Measurement:</i> 41"</li> <li>• <i>Proposed Solution:</i> Lower bell onto side table or shelf.</li> </ul>	PCODE BE02NT ADAAG 8.3 CSAS 1122B.4 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$150	\$150	3.2
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 43"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE WG03 ADAAG 4.19.6 CSAS 1115B.9.1.2 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$75	\$75	3.2
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 3" deep</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE WD03 ADAAG 4.19.2 CSAS 1504.2.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$3,400	\$3,400	3.2
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE WD05REF ADAAG 4.19.4 CSAS 1504.2.2		REF			3.2
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE WD06REF ADAAG 4.19.5 CSAS 1504.1.3		REF			3.2

Location: **Ukiah 105 N. Main Street**Bldg Name: **Main**Floor: **1**ID No: **9-29-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 36"</li> <li>• <i>Proposed Solution:</i> Convert restroom into single accommodation. Remove partition, and stall door. Provide new stall door at wall opening. Remodel floor and walls as needed.</li> </ul>	PCODE <b>WB06NT</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bar clearance not 1-1/2" from wall.</li> <li>• <i>As-is Measurement:</i> 2.5"</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07E</b> ADAAG <b>4.26.2</b> CSAS <b>1115B.8.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05CREF</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b>		REF			<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> In single occupancy restroom less than 18" from centerline of water closet to another fixture (CA only: 28" from edge of water closet to edge of another fixture).</li> <li>• <i>As-is Measurement:</i> 17"</li> <li>• <i>Proposed Solution:</i> Remove urinal and remodel wall as needed. Provide accessible door locking device on restroom entry door.</li> </ul>	PCODE <b>WB09NT</b> ADAAG <b>Fig. 28</b> CSAS <b>Fig. 11B-1A</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Fixture mounted with rim more than 17" above floor.</li> <li>• <i>Proposed Solution:</i> Remove urinal.</li> </ul>	PCODE <b>WE02AREF</b> ADAAG <b>4.18.2</b> CSAS <b>1503.2 C.P.C.</b>		REF			<b>3.2</b>

Location: **Ukiah 105 N. Main Street**Bldg Name: **Main**Floor: **1**ID No: **9-29-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 43"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 3" deep</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06REF</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b>		REF			<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 2</li> <li>• <i>Proposed Solution:</i> Convert restroom into single accommodation. Remove partitions, stall doors, and one watercloset. Provide new stall door at wall opening. Remodel floor and walls as needed.</li> </ul>	PCODE <b>WB06NT</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>1.2</b>

Location: Ukiah 105 N. Main Street

Bldg Name: Main

Floor: 1

ID No: 9-29-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bar clearance not 1-1/2" from wall.</li> <li>• <i>As-is Measurement:</i> 2.5"</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07E</b> ADAAG <b>4.26.2</b> CSAS <b>1115B.8.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	1.2
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accessible hardware.</li> </ul>	PCODE <b>WB05CREF</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b>		REF			3.2
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> In single occupancy restroom less than 18" from centerline of water closet to another fixture (CA only: 28" from edge of water closet to edge of another fixture).</li> <li>• <i>As-is Measurement:</i> 17"</li> <li>• <i>Proposed Solution:</i> Provide new, accessible fixture. Remodel restroom as needed.</li> </ul>	PCODE <b>WB09REF</b> ADAAG <b>Fig. 28</b> CSAS <b>Fig. 11B-1A</b>		REF			3.2
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Parallel street parking is not accessible.</li> <li>• <i>Proposed Solution:</i> Provide accessible street parking space, including striping, signage, and curb ramp. Coordinate with City of Ukiah.</li> </ul>	PCODE <b>EA02A</b> ADAAG <b>4.6.1</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1	JOB	\$2,500	\$2,500	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible side entrance.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$120	\$240	1.1

Location: **Ukiah 280 E. Standley Street**

Bldg Name: **Site**

Floor: **1**

ID No: **9-333-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li><i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	1.1
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li><i>As-is Measurement:</i> 8 lbs.</li> <li><i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	2.1
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Clear passageway in restroom not provided.</li> <li><i>As-is Measurement:</i> 30"</li> <li><i>Proposed Solution:</i> Remove or relocate furniture or storage items.</li> </ul>	PCODE <b>WC03ANT</b> CSAS <b>Fig.No.31-1B</b> MoM <b>P. A. (In-house)</b> O/R <b>Department Head</b>	1	JOB	\$50	\$50	2.1
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li><i>As-is Measurement:</i> PTD: 53"</li> <li><i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	5.1
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Latch approach: At pull side, door does not have clear and level maneuvering space measuring door width plus 24" x 48" or 54" if door has closer (CA only: door width plus 24" x 60").</li> <li><i>As-is Measurement:</i> 38"</li> <li><i>Proposed Solution:</i> Change door swing.</li> </ul>	PCODE <b>ID27</b> ADAAG <b>Fig. 25(c)</b> CSAS <b>11B-26A(c)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	5.1



Location: **Ukiah 280 E. Standley Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-333-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Clear floor space, 30" x 48" in front of fixture, extending 19" max. under the lavatory, not provided (CA only: Less than 18" from side wall to centerline of lavatory).</li> <li>• <i>As-is Measurement:</i> 13"</li> <li>• <i>Proposed Solution:</i> Relocate existing lavatory.</li> </ul>	PCODE <b>WD01A</b> ADAAG <b>4.19.3</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing riser seat too high.</li> <li>• <i>As-is Measurement:</i> 21"</li> <li>• <i>Proposed Solution:</i> Remove riser toilet seat to provide 17"-19" seating height.</li> </ul>	PCODE <b>WB08ANT</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 47"</li> <li>• <i>Proposed Solution:</i> Relocate grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$300	\$300	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>5.1</b>

Location: **Ukiah 280 E. Standley Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-333-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 49"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to 48" highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 53"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Latch approach: At pull side, door does not have clear and level maneuvering space measuring door width plus 24" x 48" or 54" if door has closer (CA only: door width plus 24" x 60").</li> <li>• <i>As-is Measurement:</i> 38"</li> <li>• <i>Proposed Solution:</i> Change door swing.</li> </ul>	PCODE <b>ID27</b> ADAAG <b>Fig. 25(c)</b> CSAS <b>11B-26A(c)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	5.1

Location: **Ukiah 280 E. Standley Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-333-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Clear floor space, 30" x 48" in front of fixture, extending 19" max. under the lavatory, not provided (CA only: Less than 18" from side wall to centerline of lavatory).</li> <li>• <i>As-is Measurement:</i> 13"</li> <li>• <i>Proposed Solution:</i> Relocate existing lavatory.</li> </ul>	PCODE <b>WD01A</b> ADAAG <b>4.19.3</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing riser seat too high.</li> <li>• <i>As-is Measurement:</i> 21"</li> <li>• <i>Proposed Solution:</i> Remove riser toilet seat to provide 17"-19" seating height.</li> </ul>	PCODE <b>WB08ANT</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$80	\$80	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 47"</li> <li>• <i>Proposed Solution:</i> Relocate grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$300	\$300	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 49"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>5.1</b>

Location: **Ukiah 280 E. Standley Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-333-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Floor-mounted closer (internal). Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Disable floor-mounted closing mechanism and install new, door-mounted closer.</li> </ul>	PCODE <b>ID03B</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Floor-mounted closer (internal). Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Disable floor-mounted closing mechanism and install new, door-mounted closer.</li> </ul>	PCODE <b>ID03B</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At push side of framed glass or panel door on accessible route, bottom 10" does not have a smooth, uninterrupted surface (required in CA only).</li> <li>• <i>Proposed Solution:</i> Provide 10" min. "kick plate" covering width of door when altering area.</li> </ul>	PCODE <b>ID06</b> CSAS <b>1133B.2.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$90	\$90	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible public entrance locked and unattended.</li> <li>• <i>Proposed Solution:</i> Provide door bell outside of accessible side entrance to call for staff.</li> </ul>	PCODE <b>ID04NT</b> ADAAG <b>4.14.1</b> CSAS <b>1134B.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>

Location: **Covelo 76508 Covelo Road**

Bldg Name: **Library**

Floor: **1**

ID No: **2-336-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> CA only: Book shelves are more than 54" maximum height.</li> <li>• <i>As-is Measurement:</i> 70"</li> <li>• <i>Proposed Solution:</i> Provide attendant when needed.</li> </ul>	PCODE <b>BD01A</b> CSAS <b>1106B.4.3</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$0		<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Recommended only: Accessible non-fixed table or desk (top 28" to 34" high; knee space at least 27" high x 19" deep x 30" wide) not provided.</li> <li>• <i>As-is Measurement:</i> 26"</li> <li>• <i>Proposed Solution:</i> Provide table or desk with accessible dimensions when purchasing new furniture.</li> </ul>	PCODE <b>IN02A</b> ADAAG <b>4.32.3 &amp; .4</b> MoM <b>P. A. (In-house)</b> O/R <b>Department Head</b>	1	JOB	\$1,600	\$1,600	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 48" clear space perpendicular to closed door at side opposite swing.</li> <li>• <i>As-is Measurement:</i> 45"</li> <li>• <i>Proposed Solution:</i> Remove or relocate storage items or furniture.</li> </ul>	PCODE <b>ID16A</b> ADAAG <b>4.13.6*</b> CSAS <b>3304 (i.1) 2B</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>2.1</b>

Location: **Covelo 76508 Covelo Road**

Bldg Name: **Library**

Floor: **1**

ID No: **2-336-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet and relocate plumbing or fur side wall.</li> </ul>	PCODE <b>WB02A</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,600	\$4,600	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Clear floor space, 30" x 48" in front of fixture, extending 19" max. under the lavatory, not provided (CA only): Less than 18" from side wall to centerline of lavatory.</li> <li>• <i>As-is Measurement:</i> 10"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD01</b> ADAAG <b>4.19.3</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 54"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>3.2</b>

Location: **Covelo 76508 Covelo Road**

Bldg Name: **Library**

Floor: **1**

ID No: **2-336-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 32" from side of water closet to far side of stall wall or 28" to adjacent fixture.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Relocate or turn shelf.</li> </ul>	PCODE <b>WB01NT</b> ADAAG <b>Fig. 28c</b> CSAS <b>1115B.7.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 27"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>10.1</b>

Location: **Ukiah 306 E. Gobbi Street**Bldg Name: **Main**Floor: **1**ID No: **9-343-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Water heater under lavatory.</li> <li>• <i>Proposed Solution:</i> Relocate water heater to provide clear space.</li> </ul>	PCODE <b>WD</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2 C.P.C.</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1	JOB	\$3,400	\$3,400	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 48"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 53"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Corridor, for occupant load less than 10, less than 36" wide.</li> <li>• <i>As-is Measurement:</i> 31"</li> <li>• <i>Proposed Solution:</i> Remove or relocate furniture and storage items.</li> </ul>	PCODE <b>IH03A</b> ADAAG <b>4.3.3</b> CSAS <b>3305(b)1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>



Location: **Ukiah 306 E. Gobbi Street**Bldg Name: **Main**Floor: **1**ID No: **9-343-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No van parking provided (one in every 8 accessible spaces, but not less than one. 8' wide access aisle, 98" height clearance).</li> <li>• <i>Proposed Solution:</i> Provide van parking space(s) by restriping; provide van sign at existing access aisle.</li> </ul>	PCODE <b>EA07</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Parallel street parking is not accessible.</li> <li>• <i>As-is Measurement:</i> 10.5%</li> <li>• <i>Proposed Solution:</i> Alternative route exists. Provide accessible parking when altering area.</li> </ul>	PCODE <b>EA02A</b> ADAAG <b>4.6.1</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$2,500	\$2,500	<b>10.1</b>

Location: Ukiah 631 S. Orchard Avenue

Bldg Name: Site

Floor: 1

ID No: 9-363-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE ED01 ADAAG 4.8.5 & 4.9.4 CSAS 1133B.4.1 & B.5.5.1 MoM P. A. (Contractor) O/R Manager B&G 2	50	LF	\$95	\$4,750	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface of required maneuvering clearance at door slopes more than 1/4":12" (2.0%).</li> <li>• <i>As-is Measurement:</i> 3%</li> <li>• <i>Proposed Solution:</i> Modify surface slope at door.</li> </ul>	PCODE ID11 ADAAG 4.13.6 CSAS 1133B.2.4 MoM P. A. (Contractor) O/R Manager B&G 2	25	SF	\$25	\$625	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Floor-mounted closer (internal). Excessive force required to open door and/or door closing time of less than 3 seconds (Note: there is andoor bell installed)</li> <li>• <i>As-is Measurement:</i> 20 lbs.</li> <li>• <i>Proposed Solution:</i> Disable floor-mounted closing mechanism and install new, door-mounted closer. Interim Solution: lower door bell to 48" and install signage.</li> </ul>	PCODE ID03B ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 2	2	JOB	\$500	\$1,000	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Floor-mounted closer (internal). Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 20 lbs.</li> <li>• <i>Proposed Solution:</i> Disable floor-mounted closing mechanism and install new, door-mounted closer.</li> </ul>	PCODE ID03B ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 2	2	JOB	\$500	\$1,000	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation. Interim: clipboard is provided.</li> </ul>	PCODE IN03 ADAAG 7.2(3) CSAS 1122B.4 MoM E. F. O/R Department Head	1	JOB	\$75	\$75	10.1

Location: **Ukiah 631 S. Orchard Avenue**

Bldg Name: **Main**

Floor: **1**

ID No: **9-363-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 17 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>Proposed Solution:</i> Remove or relocate furniture or storage items.</li> </ul>	PCODE <b>ID14A</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At facility with a fire alarm system, visual signal (strobe) not provided at required type of common use area.</li> <li>• <i>Proposed Solution:</i> Provide combination visual / audible signal device connected to existing fire alarm system. As an interim solution, advise staff to follow county emergency procedures rearding the evacuation of people with disabilities.</li> </ul>	PCODE <b>IC05</b> ADAAG <b>4.1.3(14) &amp; 4.28.3</b> CSAS <b>1114B.2.4</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$1,300	\$1,300	10.1

Location: Ukiah 631 S. Orchard Avenue

Bldg Name: Main

Floor: 1

ID No: 9-363-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair accessible route, at door with both latch and closer, width of level and clear area at door push side does not extend 12" min. past the strike side edge.</li> <li>• <i>As-is Measurement:</i> 4"</li> <li>• <i>Proposed Solution:</i> Remove door closer.</li> </ul>	PCODE ID09NT ADAAG 4.13.6 CSAS Fig. 11B-26A(a) MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$100	\$100	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 13 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 13 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	2	JOB	\$25	\$50	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Otherwise compliant sign identifying permanent room or space not mounted 5' high to center on nearest adjacent wall, on latch side if a single door (located not to cause a Braille reader to stand within the door)</li> <li>• <i>Proposed Solution:</i> Relocate existing sign.</li> </ul>	PCODE SA07 ADAAG 4.30.6 CSAS 1117B.5.9 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	10.1

Location: Ukiah 631 S. Orchard Avenue

Bldg Name: Main

Floor: 1

ID No: 9-363-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 14 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	2	JOB	\$25	\$50	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 18 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	2	JOB	\$25	\$50	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Adjust closer.</li> </ul>	PCODE WB05B ADAAG 4.22.4 CSAS 1115B.7.1.4 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$100	\$100	3.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28.75"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE WD03A ADAAG 4.19.2 CSAS 1504.2.1 MoM P. A. (In-house) O/R Manager B&G 2	3	JOB	\$900	\$2,700	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 17 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	2	JOB	\$25	\$50	3.1

Location: Ukiah 631 S. Orchard Avenue

Bldg Name: Main

Floor: 1

ID No: 9-363-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28.5"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	3	JOB	\$900	\$2,700	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 17 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 20 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 88"x60"</li> <li>• <i>Proposed Solution:</i> Provide signage directing people to accessible restrooms.</li> </ul>	PCODE <b>WA01NT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$90	\$90	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>Proposed Solution:</i> Provide signage directing people to accessible restrooms.</li> </ul>	PCODE <b>WA01NT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$90	\$90	<b>3.1</b>

Location: **Ukiah 631 S. Orchard Avenue**

Bldg Name: **Main**

Floor: **1**

ID No: **9-363-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 16 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 59"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation. Interim: provide clipboard.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No van parking provided (one in every 8 accessible spaces, but not less than one. 8' wide access aisle, 98" height clearance).</li> <li>• <i>Proposed Solution:</i> Provide van parking space(s) by restriping; provide van sign. Coordinate provision with property owner.</li> </ul>	PCODE <b>EA07NT</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Disabled persons must wheel or walk behind parked car(s) other than their own.</li> <li>• <i>Proposed Solution:</i> Relocate parking and provide curb ramp to accessible route.</li> </ul>	PCODE <b>EA03</b> ADAAG <b>Fig.9</b> CSAS <b>1129B.4.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$730	\$730	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	1.1

Location: Willits 1726-D South Main Street

Bldg Name: Public Health

Floor: 1

ID No: 10-362-1-

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Clear floor space is not 30" x 48" minimum at all switches, outlets and other controls.</li> <li>• <i>Proposed Solution:</i> Relocate existing furniture/obstructions to provide clearance in front of electrical switch and water closet.</li> </ul>	PCODE <b>IC06A</b> ADAAG <b>4.1.2(12) &amp; [4.1.3(13)]</b> MoM <b>P. A. (In-house)</b> O/R <b>Department Head</b>	1	JOB	\$50	\$50	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 19.5"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE <b>WB02B</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Clear floor space, 30" x 48" in front of fixture, extending 19" max. under the lavatory, not provided (CA only: Less than 18" from side wall to centerline of lavatory).</li> <li>• <i>As-is Measurement:</i> 15"</li> <li>• <i>Proposed Solution:</i> Relocate existing lavatory.</li> </ul>	PCODE <b>WD01A</b> ADAAG <b>4.19.3</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>10.1</b>



Location: **Willits 1726-D South Main Street**Bldg Name: **Public Health**Floor: **1**ID No: **10-362-1-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 50"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SCD: 56"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware at emergency exit.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>

Location: Ukiah 189/199 S. School Street &amp; 170 W.

Bldg Name: Site

Floor: 1

ID No: 9-364-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions. Coordinate with landlord.</li> </ul>	PCODE ED01 ADAAG 4.8.5 & 4.9.4 CSAS 1133B.4.1 & B.5.5.1 MoM C.T.P. O/R Manager B&G 2	10	LF	\$95	\$950	4.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No signs at non-accessible entrances directing persons to an accessible entrance of the building.</li> <li>• <i>Proposed Solution:</i> Provide large font, directional signage to indicate route to the accessible entrance on School Street.</li> </ul>	PCODE SA14 ADAAG 4.1.2(7)(c) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$120	\$120	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE SA12 ADAAG 4.1.2(7)(c) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	4.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE IN03 ADAAG 7.2(3) CSAS 1122B.4 MoM E. F. O/R Department Head	1	JOB	\$150	\$150	4.1

Location: **Ukiah 199 S. School Street**Bldg Name: **Main**Floor: **1**ID No: **9-364-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door opening (32" min. clear) is more than 24" deep.</li> <li>• <i>As-is Measurement:</i> 30.5"</li> <li>• <i>Proposed Solution:</i> Relocate shelves.</li> </ul>	PCODE <b>ID18NT</b> ADAAG <b>4.13.5</b> CSAS <b>11B-33(a)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$550	\$550	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 48" clear space perpendicular to closed door at side opposite swing.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Relocate refrigerator to kitchen nook.</li> </ul>	PCODE <b>ID16ANT</b> ADAAG <b>4.13.6*</b> CSAS <b>3304 (i.1) 2B</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Adjust closer.</li> </ul>	PCODE <b>WB05B</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>4.1</b>

Location: Ukiah 199 S. School Street

Bldg Name: Main

Floor: 1

ID No: 9-364-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SCD: 58"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 49"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>4.1</b>

Location: Ukiah 199 S. School Street

Bldg Name: Main

Floor: 1

ID No: 9-364-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE SA11 ADAAG 4.1.2(7)(d) CSAS 1117B.5.9 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$45	\$45	4.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 66" x 48"</li> <li>• <i>Proposed Solution:</i> Wheelchair accessible restroom is provided in Public Defender's offices. Advise staff to provide assistance.</li> </ul>	PCODE WA01REF ADAAG 4.22 CSAS 1115B.7.2 MoM E. F. O/R Department Head		REF			4.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE WD06 ADAAG 4.19.5 CSAS 1504.1.3 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$600	\$600	4.1

Location: Ukiah 199 S. School Street

Bldg Name: Main

Floor: 1

ID No: 9-364-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 66" x 48"</li> <li>• <i>Proposed Solution:</i> Wheelchair accessible restroom is provided in Public Defender's offices. Advise staff to provide assistance.</li> </ul>	PCODE <b>WA0IREF</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>E. F.</b> O/R <b>Department Head</b>		REF			<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door binding.</li> <li>• <i>Proposed Solution:</i> Rehang door or adjust floor.</li> </ul>	PCODE <b>ID03NT</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Clear floor space at elevator call buttons is not provided.</li> <li>• <i>As-is Measurement:</i> 38"</li> <li>• <i>Proposed Solution:</i> Relocate storage boxes.</li> </ul>	PCODE <b>IC06ANT</b> ADAAG <b>4.1.2(12) &amp; [4.1.3(13)]</b> <small>2.1.4 2.7.21</small> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$50	\$50	<b>4.1</b>

Location: **Ukiah 199 S. School Street**Bldg Name: **Main**Floor: **1**ID No: **9-364-1-2**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	8	LF	\$95	\$760	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Cross slope more than 1/4":12" (2%).</li> <li>• <i>As-is Measurement:</i> 5%</li> <li>• <i>Proposed Solution:</i> Coordinate repair with City of Fort Bragg.</li> </ul>	PCODE <b>EF07NT</b> ADAAG <b>4.3.7</b> CSAS <b>1133B.7.1.3</b> MoM <b>C.T.P.</b> O/R <b>County ADA Coordinator</b>	80	SF	\$12	\$960	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	<b>1.1</b>

Location: **Fort Bragg 825 S. Franklin Street**Bldg Name: **Main**Floor: **1**ID No: **3-365-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 41"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign designating a permanent room or space does not include Grade 2 Braille.</li> <li>• <i>Proposed Solution:</i> Provide new compliant signage including California Grade 2 Braille.</li> </ul>	PCODE <b>SA07A</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	15	JOB	\$45	\$675	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Protruding fire extinguisher box more than 4" from wall, when bottom of object more than 27" or less than 80" above finished floor.</li> <li>• <i>As-is Measurement:</i> 7"</li> <li>• <i>Proposed Solution:</i> Remove/relocate fire extinguisher box. Patch existing surface.</li> </ul>	PCODE <b>EG04</b> ADAAG <b>4.4.1</b> CSAS <b>1121B.1</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	2	JOB	\$100	\$200	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Recommended only: Accessible non-fixed table or desk (top 28" to 34" high; knee space at least 27" high x 19" deep x 30" wide) not provided.</li> <li>• <i>As-is Measurement:</i> 26.5"</li> <li>• <i>Proposed Solution:</i> Provide table or desk with accessible dimensions when purchasing new furniture.</li> </ul>	PCODE <b>IN02A</b> ADAAG <b>4.32.3 &amp; .4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$1,600	\$1,600	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$45	\$135	<b>10.1</b>



Location: **Fort Bragg 825 S. Franklin Street**Bldg Name: **Main**Floor: **1**ID No: **3-365-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i>     SCD: 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>E. F.</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$50	\$150	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i>     SD: 44"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>E. F.</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$50	\$150	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet paper dispenser not continuous paper flow type.</li> <li>• <i>Proposed Solution:</i> Provide continuous-flow toilet paper dispenser.</li> </ul>	PCODE <b>WG02A</b> ADAAG <b>4.16.6</b> CSAS <b>1115B.9.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$75	\$75	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i>     47"</li> <li>• <i>Proposed Solution:</i> Relocate grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$300	\$900	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</li> <li>• <i>As-is Measurement:</i>     16"</li> <li>• <i>Proposed Solution:</i> Consider relocating the program to an accessible facility or provide new concrete ramp with handrails [slope more than 1:20 (5.0%) needed]. Interim solution: Advise staff to conduct house visits if needed.</li> </ul>	PCODE <b>EB01A</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	64	SF	\$100	\$6,400	<b>10.1</b>

Location: **Willits 713 S. Main Street #1A**Bldg Name: **Site**Floor: **1**ID No: **10-373-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> No walk / sidewalk provided to connect accessible facilities or elements that are on the same site.</li> <li><i>Proposed Solution:</i> Provide paved path from city sidewalk to new proposed ramp.</li> </ul>	PCODE <b>EF13NT</b> ADAAG <b>4.3.2</b> CSAS <b>1114B.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	60	LF	\$45	\$2,700	<b>10.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li><i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	10	LF	\$95	\$950	<b>10.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Door inaccessible due to threshold or step at door more than 1" high, up to 6" high.</li> <li><i>As-is Measurement:</i> 2.5"</li> <li><i>Proposed Solution:</i> Install wooden deck on top of concrete patio. Coordinate work with new proposed ramp.</li> </ul>	PCODE <b>ID02ANT</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	60	SF	\$12	\$720	<b>10.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li><i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> No directions posted at inaccessible entrance.</li> <li><i>Proposed Solution:</i> Post sign (large font) with telephone number in accessible location.</li> </ul>	PCODE <b>SA18NT</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$90	\$90	<b>1.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li><i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>

Location: **Willits 713 S. Main Street #1A**

Bldg Name: **Main**

Floor: **1**

ID No: **10-373-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 91" x 43"</li> <li>• <i>Proposed Solution:</i> Remodel area to provide single-occupant accessible restroom or relocate program.</li> </ul>	PCODE <b>WA01</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$12,000	\$12,000	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</li> <li>• <i>As-is Measurement:</i> 31"</li> <li>• <i>Proposed Solution:</i> Consider relocating the program to an accessible facility or demolish brick deck and stairs and provide new concrete ramp with handrails. Interim solution: Advise staff to conduct house visits if needed.</li> </ul>	PCODE <b>EB01ANT</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	250	SF	\$100	\$25,000	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door inaccessible due to threshold or step at door more than 1" high, up to 6" high.</li> <li>• <i>As-is Measurement:</i> 6"</li> <li>• <i>Proposed Solution:</i> Remove existing paving at door and provide landing with edge ramping as needed.</li> </ul>	PCODE <b>ID02AREF</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b>		REF			<b>8.1</b>

Location: **Willits 72 W. Commercial Avenue**

Bldg Name: **Main**

Floor: **1**

ID No: **10-374-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 90"x75"</li> <li>• <i>Proposed Solution:</i> Remodel area to provide single-occupant accessible restroom.</li> </ul>	PCODE <b>WA01</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$12,000	\$12,000	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01REF</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b>		REF			<b>8.1</b>

Location: **Willits 72 W. Commercial Avenue**

Bldg Name: **Main**

Floor: **1**

ID No: **10-374-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Water closet not accessible.</li> <li>• <i>Proposed Solution:</i> Provide accessible water closet and toilet compartment. Remodel partitions, reroute plumbing and HVAC systems, repair tiled surfaces, patch finishes to match and repaint as needed. Provide accessible accessories and grab bars.</li> </ul>	PCODE <b>WBREF</b> ADAAG <b>4.17</b> CSAS <b>1115B.7.1</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>Proposed Solution:</i> Provide wheelchair clearance space in restroom.</li> </ul>	PCODE <b>WC01REF</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory/sink not accessible.</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel partitions, reroute plumbing and HVAC systems, repair tiled surfaces, patch finishes to match and repaint as needed. Provide accessible mirror and soap dispenser.</li> </ul>	PCODE <b>WDREF</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2 C.P.C.</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 36"x81"</li> <li>• <i>Proposed Solution:</i> Remodel area to provide single-occupant accessible restroom. Coordinate remodel with that of bathroom.</li> </ul>	PCODE <b>WA01NT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$12,000	\$12,000	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>8.1</b>

Location: **Willits 72 W. Commercial Avenue**Bldg Name: **Garage**Floor: **1**ID No: **10-374-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign (large font) to provide direction to or information about the alternative location, including a telephone number missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage large enough to be seen from parking lot to direct people to accessible program location at 1788 S. Main Street.</li> </ul>	PCODE <b>SA09NT</b> ADAAG <b>4.1.3 (16) (b)</b> CSAS <b>1117B.5.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible van parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant van parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$175	\$175	4.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope not steep but greater than 1:20 (5.0 %) without handrails.</li> <li>• <i>As-is Measurement:</i> 7%</li> <li>• <i>Proposed Solution:</i> Provide steel handrails for ramp.</li> </ul>	PCODE <b>EB03</b> ADAAG <b>4.8.1*</b> CSAS <b>1133B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	64	LF	\$75	\$4,800	4.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope not steep but greater than 1:20 (5.0 %) without handrails.</li> <li>• <i>As-is Measurement:</i> 8.1%</li> <li>• <i>Proposed Solution:</i> Provide steel handrails for ramp.</li> </ul>	PCODE <b>EB03</b> ADAAG <b>4.8.1*</b> CSAS <b>1133B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	36	JOB	\$75	\$2,700	4.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone amplification for hearing impaired persons not provided.</li> <li>• <i>Proposed Solution:</i> Provide telephone amplification for hearing impaired persons. To be provided by utility company. MoM: contact third party.</li> </ul>	PCODE <b>IB05</b> ADAAG <b>4.31.5</b> CSAS <b>3105(d)2.1H</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	1		\$0		4.1

Location: **Fort Bragg 700 S. Franklin Street**Bldg Name: **Justice Center**Floor: **1**ID No: **3-10-1-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open doors.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closers to accessible standards.</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 20"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE <b>WB02B</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	4.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Adjust closer.</li> </ul>	PCODE <b>WB05B</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	2.1

Location: **Fort Bragg 720 S. Franklin Street**Bldg Name: **Justice Center**Floor: **1**ID No: **3-10-1-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Adjust closer.</li> </ul>	PCODE <b>WB05B</b> ADAAG <b>4.22.4</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>



Location: **Fort Bragg 720 S. Franklin Street**Bldg Name: **Justice Center**Floor: **1**ID No: **3-10-1-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Kitchenette sink rim higher than 34" above floor.</li> <li>• <i>As-is Measurement:</i> 36"</li> <li>• <i>Proposed Solution:</i> Remodel sink cabinet to lower sink.</li> </ul>	PCODE <b>IN06</b> ADAAG <b>4.24.2</b> CSAS <b>1117B.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>General Service Director</b>	1	JOB	\$1,850	\$1,850	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 42"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>4.1</b>

Location: **Fort Bragg 720 S. Franklin Street**Bldg Name: **Justice Center**Floor: **1**ID No: **3-10-1-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet in designated accessible holding cell does not comply with ADAAG 4.22.</li> <li>• <i>Proposed Solution:</i> Advise staff to relocate detainees in wheelchairs to accessible county holding cell.</li> </ul>	PCODE <b>DC05</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Jury box does not have at least one accessible wheelchair space within box area.</li> <li>• <i>Proposed Solution:</i> Remove fixed seats and/or modify seating area to provide required wheelchair space; provide readily removable seating.</li> </ul>	PCODE <b>JA02</b> ADAAG <b>11.2.1(2)</b> CSAS <b>3103A(C)2F(IV)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Witness stand does not have at least one accessible wheelchair space within witness area.</li> <li>• <i>As-is Measurement:</i> 25"</li> <li>• <i>Proposed Solution:</i> Modify witness stand to provide 27" knee clearance.</li> </ul>	PCODE <b>JA03NT</b> ADAAG <b>11.2.1(2)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$800	\$800	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet in designated accessible holding cell does not comply with ADAAG 4.22.</li> <li>• <i>Proposed Solution:</i> Remodel institutional toilet to be accessible. Interim solution: Use accessible staff restroom.</li> </ul>	PCODE <b>DC05</b> ADAAG <b>12.5.2</b> CSAS <b>1105B.3.5.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$12,000	\$12,000	<b>4.1</b>

Location: **Fort Bragg 720 S. Franklin Street**Bldg Name: **Justice Center**Floor: **1**ID No: **3-10-1-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Public Counter (Seated Service): Accessible section not provided (knee space min. 27" high x 19" deep x 30" wide, top 28" to 34" high, min. 36" counter wide).</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Retrofit existing counter to provide accessible auxiliary counter or table. Interim solution: Provide clipboard.</li> </ul>	PCODE <b>IN03A</b> ADAAG <b>4.32.3 &amp; 4</b> CSAS <b>1122B.3 &amp; 4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,200	\$1,200	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SA13</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 60" diameter or T-shaped space provided for wheelchair turns.</li> <li>• <i>Proposed Solution:</i> Remove or relocate storage items or furniture. Interim solution: Relocate meetings to accessible room if needed.</li> </ul>	PCODE <b>IN04A</b> ADAAG <b>4.2.3</b> CSAS <b>1118B.3</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$50	\$50	<b>4.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door inaccessible due to threshold or step at door more than 1" high, up to 6" high.</li> <li>• <i>As-is Measurement:</i> 2"</li> <li>• <i>Proposed Solution:</i> Remove existing paving at door and provide landing with edge ramping as needed.</li> </ul>	PCODE <b>ID02A</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	48	SF	\$12	\$576	<b>1.1</b>

Location: **Boonville 14470 Highway 128**Bldg Name: **Main**Floor: **1**ID No: **1-2-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door inaccessible due to threshold or step at door more than 1" high, up to 6" high.</li> <li>• <i>As-is Measurement:</i> 2"</li> <li>• <i>Proposed Solution:</i> Remove existing paving at door and provide landing with edge ramping as needed.</li> </ul>	PCODE <b>ID02A</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	48	SF	\$12	\$576	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 45"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>

Location: **Boonville 14470 Highway 128**Bldg Name: **Main**Floor: **1**ID No: **1-2-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Self-closing faucet at accessible lavatory does not remain open for at least 10 seconds.</li> <li>• <i>Proposed Solution:</i> Replace self-closing faucet at accessible lavatory.</li> </ul>	PCODE <b>WD07A</b> ADAAG <b>4.19.5</b> CSAS <b>1504.2..1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 44"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>7.1</b>

Location: **Boonville 14470 Highway 128**Bldg Name: **Main**Floor: **1**ID No: **1-2-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Self-closing faucet at accessible lavatory does not remain open for at least 10 seconds.</li> <li>• <i>Proposed Solution:</i> Replace self-closing faucet at accessible lavatory.</li> </ul>	PCODE <b>WD07A</b> ADAAG <b>4.19.5</b> CSAS <b>1504.2..1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> CA only: In single-accommodation restroom less than 48" in front of water closet provided.</li> <li>• <i>Proposed Solution:</i> Remove storage cabinet to provide at least 48" in front of water closet.</li> </ul>	PCODE <b>WB03A</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>7.1</b>

Location: **Boonville 14470 Highway 128**Bldg Name: **Site**Floor: **1**ID No: **1-2-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$120	\$120	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$175	\$175	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Walkway at accessible path less than 36" wide due to over growth of tree branches blocking the pathway.</li> <li>• <i>Proposed Solution:</i> Trim tree branches to provide accessible path to the back entry ramp of the facility.</li> </ul>	PCODE <b>EF08ANT</b> ADAAG <b>4.3.3</b> CSAS <b>1133B.7.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> This residential type, 2-story building is not accessible to people with mobility impairments due to its location at a hilly site.</li> <li>• <i>Proposed Solution:</i> Consider relocating the program to an accessible facility or advise staff to conduct house visits if needed.</li> </ul>	PCODE <b>ID04NT</b> ADAAG <b>4.14.1</b> CSAS <b>1134B.2.1</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	<b>1.1</b>

Location: **Point Arena 255 Main Street #4**Bldg Name: **Site**Floor: **1**ID No: **8-375-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 1-25 spaces, the number of accessible spaces is less than required by code; 1 space required</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking space with sign including a minimum of one van space (see facility report # 372).</li> </ul>	PCODE <b>EA01AREF</b> ADAAG <b>4.1.2(5)</b> CSAS <b>Tbl. 11B-6</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 1-25 spaces, the number of accessible spaces is less than required by code; 1 space required</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking space with sign including a minimum of one van space (see facility report # 372).</li> </ul>	PCODE <b>EA01AREF</b> ADAAG <b>4.1.2(5)</b> CSAS <b>Tbl. 11B-6</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</li> <li>• <i>As-is Measurement:</i> 5.5"</li> <li>• <i>Proposed Solution:</i> Provide small portable ramp or conduct meeting in an accessible location if needed.</li> </ul>	PCODE <b>EB01BNT</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 29%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new curb ramp. Coordinate provision with Public Works Department.</li> </ul>	PCODE <b>EH02A</b> ADAAG <b>4.7.2</b> CSAS <b>1127B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,500	\$2,500	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>1.1</b>



Location: **Point Arena 138 Main Street**Bldg Name: **Main**Floor: **1**ID No: **8-367-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$120	\$120	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 12.8%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp with handrails.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	250	SF	\$45	\$11,250	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01REF</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b>		REF			<b>6.1</b>

Location: Ukiah 293 Seminary Avenue

Bldg Name: Site

Floor: 1

ID No: 9-40-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Walkway at accessible path less than 36" wide due to the overgrowth of tree branches.</li> <li>• <i>Proposed Solution:</i> Enlarge width of walk to 36" by trimming tree branches to provide accessible path to the main ramp.</li> </ul>	PCODE <b>EF08A</b> ADAAG <b>4.3.3</b> CSAS <b>1133B.7.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new curb ramp. Coordinate with the City of Ukiah.</li> </ul>	PCODE <b>EH02ANT</b> ADAAG <b>4.7.2</b> CSAS <b>1127B.5.3</b> MoM <b>C.T.P.</b> O/R <b>County ADA Coordinator</b>	1	JOB	\$75	\$75	6.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel. + 6"</li> <li>• <i>Proposed Solution:</i> Provide small portable ramp.</li> </ul>	PCODE <b>EB01BNT</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	6.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	6.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door is not accessible due to binding.</li> <li>• <i>Proposed Solution:</i> Remount or reframe door binding.</li> </ul>	PCODE <b>ID03NT</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>Proposed Solution:</i> Remove existing stall. Remodel floor and walls as needed.</li> </ul>	PCODE <b>WC01</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$300	\$300	2.1

Location: Ukiah 293 Seminary Avenue

Bldg Name: Main

Floor: 1

ID No: 9-40-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Front approach: At pull side, door does not have clear and level maneuvering space measuring door width plus 18" x 60" (CA only: exterior door width plus 24").</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Change door swing.</li> </ul>	PCODE <b>ID23</b> ADAAG <b>Fig. 25(a)</b> CSAS <b>11B-26A(a)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory/sink not accessible.</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel partitions, reroute plumbing and HVAC systems, repair tiled surfaces, patch finishes to match and repaint as needed. Provide accessible mirror and soap dispenser.</li> </ul>	PCODE <b>WD</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No locking device on door is provided.</li> <li>• <i>Proposed Solution:</i> Provide accessible locking device at restroom door.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$75	\$75	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 44"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" or more than 19" from floor.</li> <li>• <i>As-is Measurement:</i> 20"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet.</li> </ul>	PCODE <b>WB08</b> ADAAG <b>4.16.3</b> CSAS <b>1502 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,400	\$1,400	<b>6.1</b>

Location: Ukiah 293 Seminary Avenue

Bldg Name: Main

Floor: 1

ID No: 9-40-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone: Clear floor space, 30" wide x 48" out from wall, not provided.</li> <li>• <i>Proposed Solution:</i> Remove or relocate cabinet.</li> </ul>	PCODE <b>IB01NT</b> ADAAG <b>4.31.2</b> CSAS <b>1117B.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>As-is Measurement:</i> 48"</li> <li>• <i>Proposed Solution:</i> Remove two existing lavatories and provide one new accessible lavatory with wheelchair clearance.</li> </ul>	PCODE <b>WC01NT</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,200	\$1,200	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" or more than 19" from floor.</li> <li>• <i>As-is Measurement:</i> 20"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet.</li> </ul>	PCODE <b>WB08</b> ADAAG <b>4.16.3</b> CSAS <b>1502 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,400	\$1,400	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10.5 lbs</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$120	\$120	<b>1.1</b>

Location: Ukiah 327 N. State Street #205

Bldg Name: Site

Floor: 1

ID No: 9-377-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE ED01 ADAAG 4.8.5 & 4.9.4 CSAS 1133B.4.1 & B.5.5.1 MoM P. A. (Contractor) O/R Manager B&G 2	27	LF	\$95	\$2,565	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE SA12 ADAAG 4.1.2(7)(c) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE SA01 ADAAG 35.163(b) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$120	\$120	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE WD05 ADAAG 4.19.4 CSAS 1504.2.2 MoM C.T.P. O/R Manager B&G 1	1	JOB	\$100	\$100	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SCD: 53"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE WG01A ADAAG 28 CFR 35.133(a) CSAS 1115B.9.2 MoM C.T.P. O/R Manager B&G 1	3	JOB	\$50	\$150	9.1

Location: Ukiah 327 N. State Street #205

Bldg Name: Main

Floor: 1

ID No: 9-377-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 49"</li> <li>• <i>Proposed Solution:</i> Provide new accessible stall (alternate stalls 36" x 69" or 48" x 69" not recommended). Coordinate provision with landlord.</li> </ul>	PCODE <b>WB06</b> ADAAG <b>4.17.3</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Fixture mounted with rim more than 17" above floor.</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WE02A</b> ADAAG <b>4.18.2</b> CSAS <b>1503.2 C.P.C.</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>9.1</b>

Location: Ukiah 327 N. State Street #205

Bldg Name: Main

Floor: 1

ID No: 9-377-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SCD: 53"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$50	\$150	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 49"</li> <li>• <i>Proposed Solution:</i> Provide new accessible stall (alternate stalls 36" x 69" or 48" x 69" not recommended).</li> </ul>	PCODE <b>WB06</b> ADAAG <b>4.17.3</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>

Location: **Point Arena 255 Main Street #3**Bldg Name: **Main**Floor: **2**ID No: **8-372-1-2**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</li> <li>• <i>As-is Measurement:</i> 14"</li> <li>• <i>Proposed Solution:</i> Provide new, 48" wide wood ramp with handrails [slope more than 1:20 (5.0%) needed]. Coordinate with curb ramp.</li> </ul>	PCODE <b>EB01B</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	28	LF	\$210	\$5,880	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 12%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new curb ramp. Coordinate with main ramp.</li> </ul>	PCODE <b>EH02A</b> ADAAG <b>4.7.2</b> CSAS <b>1127B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,700	\$2,700	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: International symbol of accessibility (36" square, in white on blue) is not painted on the pavement near the rear end of the parking space (required in CA only).</li> <li>• <i>Proposed Solution:</i> Apply symbol on parking space pavement when altering area.</li> </ul>	PCODE <b>EA04A</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$120	\$120	<b>6.1</b>



Location: **Hopland 110 Feliz Creek Road**Bldg Name: **Site**Floor: **1**ID No: **4-13-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$175	\$175	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Required in CA only: identification symbol centered 60" high on sanitary facility door not provided (women: 12" ø circle, men: 12" triangle, unisex: combined symbol).</li> <li>• <i>Proposed Solution:</i> Provide properly mounted sanitary facility symbol when altering area. If wheelchair accessible, include international symbol of accessibility on sign.</li> </ul>	PCODE <b>SA15</b> CSAS <b>1115B.5</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>

Location: **Hopland 110 Feliz Creek Road**Bldg Name: **Veterans Memorial**Floor: **1**ID No: **4-13-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair turning space: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>Proposed Solution:</i> Convert to unisex restroom until Men's is fully remodeld. Remove one water closet and existing partitions to provide clearance. Provide new partitions, and remodel as needed</li> </ul>	PCODE <b>WC0INT</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,500	\$2,500	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles not accessible or more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 59"</li> <li>• <i>Proposed Solution:</i> Provide specific restroom</li> </ul>	PCODE <b>WG01</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115.B.9.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$100	\$200	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide access to dias.</li> <li>• <i>As-is Measurement:</i> 13"</li> <li>• <i>Proposed Solution:</i> Install wood ramp with handrails. Interim solution: Provide a portable ramp.</li> </ul>	PCODE <b>EB01B</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>6.1</b>

Location: **Hopland 110 Feliz Creek Road**Bldg Name: **Veterans Memorial**Floor: **1**ID No: **4-13-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 64"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>6.1</b>

Location: **Hopland 110 Feliz Creek Road**Bldg Name: **Veterans Memorial**Floor: **1**ID No: **4-13-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Water closet not accessible due to insufficient wheelchair clearance.</li> <li>• <i>Proposed Solution:</i> Remove two existing urinals and one existing stall and provide new accessible water closet with 60" diameter wheelchair clearance. provide new partition and remodel restroom as needed.</li> </ul>	PCODE <b>WC01NT</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,900	\$4,900	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 59"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$175	\$175	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: Less than 48" level space at top and 1:12 flared sides not provided.</li> <li>• <i>As-is Measurement:</i> 2"</li> <li>• <i>Proposed Solution:</i> Provide new curb ramp from pavement area to ground floor. Interim solution: Bevel transition with asphalt.</li> </ul>	PCODE <b>EH05C</b> ADAAG <b>4.7.5; Fig.12(a)</b> CSAS <b>1127B.5.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	45	SF	\$45	\$2,025	<b>6.1</b>

Location: **Point Arena 24000 S. Highway 1**Bldg Name: **Site**Floor: **1**ID No: **8-20-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1.25"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$200	\$400	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1.25</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	4	JOB	\$200	\$800	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Water closet not accessible.</li> <li>• <i>Proposed Solution:</i> Remove two existing urinals and provide one new accessible water closet. Remodel partitions, reroute plumbing and HVAC systems, repair tiled surfaces, patch finishes to match and repaint as needed. Provide accessible accessories.</li> </ul>	PCODE <b>WBNT</b> ADAAG <b>4.17</b> CSAS <b>1115B.7.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$5,000	\$5,000	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 48"</li> <li>• <i>Proposed Solution:</i> Remove existing stall.</li> </ul>	PCODE <b>WB06</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$400	\$400	<b>6.1</b>

Location: **Point Arena 24000 S. Highway 1**Bldg Name: **Main**Floor: **1**ID No: **8-20-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28.5"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 45"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 46"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Required in CA only: identification symbol centered 60" high on sanitary facility door not provided (women: 12" ø circle, men: 12" triangle, unisex: combined symbol).</li> <li>• <i>Proposed Solution:</i> Provide properly mounted sanitary facility symbol when altering area. If wheelchair accessible, include international symbol of accessibility on sign.</li> </ul>	PCODE <b>SA15</b> CSAS <b>1115B.5</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>2.1</b>

Location: **Point Arena 24000 S. Highway 1**Bldg Name: **Main**Floor: **1**ID No: **8-20-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>As-is Measurement:</i> 102" x 114"</li> <li>• <i>Proposed Solution:</i> As an interim solution until the Men's is fully accessible, remodel Women's restroom and convert into unisex. Provide signage.</li> </ul>	PCODE <b>WC01</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 0"</li> <li>• <i>Proposed Solution:</i> Remove counter and sink. Provide new accessible lavatory and new plumbing. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Water closet not accessible.</li> <li>• <i>Proposed Solution:</i> Remove both water closets and provide one new accessible water closet. Reroute plumbing and remodel as needed.</li> </ul>	PCODE <b>WBNT</b> ADAAG <b>4.17</b> CSAS <b>1115B.7.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$5,000	\$5,000	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 43"</li> <li>• <i>Proposed Solution:</i> Remove existing stall.</li> </ul>	PCODE <b>WB06</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 27"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>

Location: **Point Arena 24000 S. Highway 1**

Bldg Name: **Main**

Floor: **1**

ID No: **8-20-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<p>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles not accessible or more than 40" from floor to highest operating slot or control.</p> <p>• <i>As-is Measurement:</i> SD: 55"</p> <p>• <i>Proposed Solution:</i> Provide specific restroom</p>	<p>PCODE <b>WG01</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115.B.9.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b></p>	1	JOB	\$100	\$100	<b>2.1</b>
	<p>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</p> <p>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</p>	<p>PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b></p>	1	JOB	\$45	\$45	<b>2.1</b>
	<p>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</p> <p>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</p>	<p>PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b></p>	1	JOB	\$125	\$125	<b>10.1</b>
	<p>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</p> <p>• <i>As-is Measurement:</i> 4"</p> <p>• <i>Proposed Solution:</i> Provide a small wood ramp at main entrance of the airport office to provide a wheelchair access.</p>	<p>PCODE <b>EB01BNT</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b></p>	1	JOB	\$385	\$385	<b>1.1</b>
	<p>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</p> <p>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</p>	<p>PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b></p>	1	JOB	\$25	\$25	<b>10.1</b>



Location: **Little River 43001 Airport Road** Bldg Name: **Site** Floor: **1** ID No: **7-16-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$175	\$350	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrances to provide direction to accessible entrances is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$120	\$120	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone desk is not compliant due to height of more than 34".</li> <li>• <i>Proposed Solution:</i> Relocate telephone desk to accessible height.</li> </ul>	PCODE <b>IB10ANT</b> ADAAG <b>4.1.3(17)(d)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07REF</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b>		REF			
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Paved area has excessively rough, irregular surface.</li> <li>• <i>Proposed Solution:</i> Repave area to provide smooth surface for path of travel.</li> </ul>	PCODE <b>EF10A</b> ADAAG <b>4.5.1</b> CSAS <b>1133B.7.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	35	SF	\$6	\$210	5.1

Location: **Ukiah 585 Low Gap Road**

Bldg Name: **Site**

Floor: **1**

ID No: **9-33-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Signage: International symbol of accessibility (36" square, in white on blue) is not painted on the pavement near the rear end of the parking space (required in CA only).</li> <li><i>Proposed Solution:</i> Apply symbol on parking space pavement when altering area.</li> </ul>	PCODE <b>EA04A</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$120	\$120	<b>5.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li><i>As-is Measurement:</i> 16 lbs.</li> <li><i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li><i>As-is Measurement:</i> 1"</li> <li><i>Proposed Solution:</i> Provide new or modify existing threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02NT</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>1.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li><i>As-is Measurement:</i> 31.5"</li> <li><i>Proposed Solution:</i> Remove existing stall to provide wheelchair clearance in the restroom.</li> </ul>	PCODE <b>WB06NT</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li><i>As-is Measurement:</i> 26"</li> <li><i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>

Location: **Ukiah 585 Low Gap Road**

Bldg Name: **Administration Building**

Floor: **1**

ID No: **9-33-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 49"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 49"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Urinal not accessible due to wheelchair clearance.</li> <li>• <i>As-is Measurement:</i> Height: 23"</li> <li>• <i>Proposed Solution:</i> Remove existing urinal and its stall to provide wheelchair clearance in the restroom.</li> </ul>	PCODE <b>WENT</b> ADAAG <b>4.18</b> CSAS <b>1503.2 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$700	\$700	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>

Location: **Ukiah 585 Low Gap Road**

Bldg Name: **Administration Building**

Floor: **1**

ID No: **9-33-**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 45"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>5.1</b>

Location: Ukiah 585 Low Gap Road

Bldg Name: Administration Building

Floor: 1

ID No: 9-33-

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	2	JOB	\$25	\$50	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1.25"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE ID02 ADAAG 4.13.8 CSAS 1133B.2.4.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$200	\$200	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wall- and post-mounted cantilevered units: Knee space not provided at drinking fountain (27" high, 8" deep, 30" wide from front of drinking fountain). Unit in good condition.</li> <li>• <i>As-is Measurement:</i> 38"</li> <li>• <i>Proposed Solution:</i> Remount fountain at accessible height.</li> </ul>	PCODE IA02A ADAAG 4.15.5(1) CSAS 1507.3.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$1,200	\$1,200	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 57"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE IB02 ADAAG 4.2.6 CSAS 1118B.6 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$250	\$250	5.1

Location: **Ukiah 585 Low Gap Road**

Bldg Name: **Cell Building #1**

Floor: **1**

ID No: **9-33-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 54"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> The bottom of the control area less than 38" or top more than 48" above the shower floor, or area not within 18" of the front of the shower (CA only: center line of controls not at 40" [+/-1"]).</li> <li>• <i>As-is Measurement:</i> 70"</li> <li>• <i>Proposed Solution:</i> Provide new, or relocate, shower controls.</li> </ul>	PCODE <b>WF12</b> ADAAG <b>4.27.3</b> CSAS <b>1115B.6.2.4.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$800	\$800	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 50"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>5.1</b>

Location: **Ukiah 585 Low Gap Road**

Bldg Name: **Cell Building #1**

Floor: **1**

ID No: **9-33-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> The bottom of the control area less than 38" or top more than 48" above the shower floor, or area not within 18" of the front of the shower (CA only: center line of controls not at 40" [+/-1"]).</li> <li>• <i>As-is Measurement:</i> 72"</li> <li>• <i>Proposed Solution:</i> Provide new, or relocate, shower controls.</li> </ul>	PCODE <b>WF12</b> ADAAG <b>4.27.3</b> CSAS <b>1115B.6.2.4.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$800	\$800	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Fixture mounted with rim more than 17" above floor.</li> <li>• <i>As-is Measurement:</i> 23"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WE02A</b> ADAAG <b>4.18.2</b> CSAS <b>1503.2 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1.5"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	1.1

Location: **Ukiah 585 Low Gap Road**

Bldg Name: **Cell Building #1**

Floor: **1**

ID No: **9-33-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wall- and post-mounted cantilevered units: Knee space not provided at drinking fountain (27" high, 8" deep, 30" wide from front of drinking fountain). Unit in good condition.</li> <li>• <i>As-is Measurement:</i> 38"</li> <li>• <i>Proposed Solution:</i> Remount fountain at accessible height.</li> </ul>	PCODE <b>IA02A</b> ADAAG <b>4.15.5(1)</b> CSAS <b>1507.3.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,200	\$1,200	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 63"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07NT</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$500	\$500	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 59"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1.5"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>1.1</b>



Location: **Ukiah 585 Low Gap Road**

Bldg Name: **Classroom Building**

Floor: **1**

ID No: **9-33-4-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1.5"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair space at sink not provided.</li> <li>• <i>Proposed Solution:</i> Modify cabinet to provide wheelchair space.</li> </ul>	PCODE <b>CF01</b> ADAAG <b>4.3.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,400	\$1,400	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 56"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Remodel area to provide single-occupant accessible restroom. Consider relocating program to an accessible location.</li> </ul>	PCODE <b>WA0INT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$17,000	\$17,000	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides.</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	14	LF	\$95	\$1,330	<b>8.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Jail Programs**

Floor: **1**

ID No: **9-48-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Provide new door closer adjusted to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03A</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	6.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	6.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 55"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Drinking fountain bubbler more than 36" above floor; unit in poor condition.</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Provide new, accessible fountain.</li> </ul>	PCODE <b>IA03B</b> ADAAG <b>4.15.2</b> CSAS <b>1507.3.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,000	\$2,000	10.1

Location: **Ukiah 931 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-43-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Telephone mounting height more than 54" to highest operable part of phone (side reach approach available).</li> <li>• <i>As-is Measurement:</i> 61"</li> <li>• <i>Proposed Solution:</i> Lower telephone enclosure and phone.</li> </ul>	PCODE <b>IB02</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 9.5 lbs.</li> <li>• <i>Proposed Solution:</i> Provide new door closer adjusted to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03A</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	2.1

Location: **Ukiah 931 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-43-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 60"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 56"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>

Location: **Ukiah 931 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-43-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 55"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 36"</li> <li>• <i>Proposed Solution:</i> Provide new 48" long accessible side grab bar.</li> </ul>	PCODE <b>WB07A</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 46"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$50	\$150	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Front edge of lavatory or counter less than 17" from wall.</li> <li>• <i>As-is Measurement:</i> 13"</li> <li>• <i>Proposed Solution:</i> Situating front edge of lavatory or counter 17" from wall. Reroute plumbing.</li> </ul>	PCODE <b>WD09</b> ADAAG <b>Fig. 31</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,100	\$2,100	<b>10.1</b>

Location: **Little River 43001 Airport Road** Bldg Name: **Main** Floor: **1** ID No: **7-16-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" or more than 19" from floor.</li> <li>• <i>As-is Measurement:</i> 20"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet.</li> </ul>	PCODE <b>WB08</b> ADAAG <b>4.16.3</b> CSAS <b>1502 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,400	\$1,400	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 9 lbs.</li> <li>• <i>Proposed Solution:</i> Provide new door closer adjusted to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03A</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29.5"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>General Service Director</b>	1	JOB	\$2,600	\$2,600	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No locking device is provided.</li> <li>• <i>Proposed Solution:</i> Provide accessible locking device when converting restroom into single accommodation use.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$250	\$250	<b>2.1</b>

Location: **Fort Bragg 790 S. Franklin**Bldg Name: **Enviro & Planning**Floor: **1**ID No: **3-7-3-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 44"</li> <li>• <i>Proposed Solution:</i> Remove stall partition. Patch walls and floor. Convert restroom into single accommodation use</li> </ul>	PCODE <b>WB06NT</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No rear grab bar provided.</li> <li>• <i>Proposed Solution:</i> Relocate right grab bar to back wall.</li> </ul>	PCODE <b>WB07NT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 27" x 12" x</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles not accessible or more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 57"</li> <li>• <i>Proposed Solution:</i> Provide or relocate specific restroom accessories.</li> </ul>	PCODE <b>WG01</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115.B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$150	\$300	<b>6.1</b>

Location: **Fort Bragg 790 S. Franklin**

Bldg Name: **Enviro & Planning**

Floor: **1**

ID No: **3-7-3-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 60"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No locking device is provided.</li> <li>• <i>Proposed Solution:</i> Provide accessible locking device when converting restroom into single accommodation use.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$250	\$250	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>Proposed Solution:</i> Remove partition and water closet at smaller stall. Relocate partition of accessible stall to provide 64" min. width. Patch walls and floor.</li> </ul>	PCODE <b>WB06NT</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No rear grab bar provided.</li> <li>• <i>Proposed Solution:</i> Relocate right grab bar to back wall.</li> </ul>	PCODE <b>WB07FNT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 27" x 12" x</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>6.1</b>



Location: **Fort Bragg 790 S. Franklin**

Bldg Name: **Enviro & Planning**

Floor: **1**

ID No: **3-7-3-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles not accessible or more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 57"</li> <li>• <i>Proposed Solution:</i> Provide or relocate specific restroom accessories.</li> </ul>	PCODE <b>WG01</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115.B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$150	\$300	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 60"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 22"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE <b>WB02B</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Public Counter (Seated Service): Accessible section not provided (knee space min. 27" high x 19" deep x 30" wide, top 28" to 34" high, min. 36" counter wide).</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Retrofit existing counter to provide accessible auxiliary counter or table. Interim solution: Provide clipboard.</li> </ul>	PCODE <b>IN03A</b> ADAAG <b>4.32.3 &amp; 4</b> CSAS <b>1122B.3 &amp; 4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,200	\$1,200	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Paved area has excessively rough, irregular surface.</li> <li>• <i>Proposed Solution:</i> Repave area to provide smooth surface for path of travel. (Start at ramp in front of portable restroom to outdoor seating area).</li> </ul>	PCODE <b>EF10ANT</b> ADAAG <b>4.5.1</b> CSAS <b>1133B.7.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	180	SF	\$6	\$1,080	<b>10.1</b>

Location: **Little River 43001 Airport Road**

Bldg Name: **Site**

Floor: **1**

ID No: **7-17-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> For parking and all other exterior site issues, see facility report # 16 (Little River Airport Terminal).</li> </ul>	PCODE <b>EA04BREF</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b>		REF			
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible parking space(s) not located close to the nearest possible entrance on an accessible route.</li> <li>• <i>Proposed Solution:</i> Provide stripping, signage, and curb ramp (type C) at crossing.</li> </ul>	PCODE <b>EA06</b> ADAAG <b>4.6.2</b> CSAS <b>1129B.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,000	\$2,000	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Slope greater than 1:20 (5.0%), and walk does not comply with requirements for ramps.</li> <li>• <i>Proposed Solution:</i> Modify walk/sidewalk slope to 1:20 or less. Not necessary if parking in front is provided.</li> </ul>	PCODE <b>EF01NT</b> ADAAG <b>4.8.1</b> CSAS <b>1133B.7.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	20	SF	\$45	\$900	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Slope greater than 1:20 (5.0%), and walk does not comply with requirements for ramps.</li> <li>• <i>As-is Measurement:</i> 0.5"</li> <li>• <i>Proposed Solution:</i> Modify walk/sidewalk slope to 1:20 or less. Not necessary if parking in front is provided. Not necessary if parking in front is provided.</li> </ul>	PCODE <b>EF01NT</b> ADAAG <b>4.8.1</b> CSAS <b>1133B.7.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	7	SF	\$45	\$315	<b>7.1</b>

Location: **Willits 400 E. Commercial Street**Bldg Name: **Site**Floor: **1**ID No: **10-22-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates vertical change in level between 1/4" and 1/2" in accessible route.</li> <li>• <i>As-is Measurement:</i> 0.5"</li> <li>• <i>Proposed Solution:</i> Grind or fill pavement dislocation to create beveled transition.</li> </ul>	PCODE <b>EF03A</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	7	SF	\$21	\$147	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</li> <li>• <i>As-is Measurement:</i> 7"</li> <li>• <i>Proposed Solution:</i> Provide new concrete ramp with handrails [slope more than 1:20 (5.0%) needed].</li> </ul>	PCODE <b>EB01A</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	28	SF	\$100	\$2,800	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation at water-meter panel creates abrupt change in level exceeding 1/2" in accessible route.</li> <li>• <i>Proposed Solution:</i> Remove, replace or repair area of pavement sufficient to correct abrupt change in level. Contact responsible third Party to replace broken panel.</li> </ul>	PCODE <b>EF03NT</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation at double panel creates abrupt change in level exceeding 1/2" in accessible route.</li> <li>• <i>Proposed Solution:</i> Remove, replace or repair area of pavement sufficient to correct abrupt change in level. Contact responsible third Party to replace broken panel.</li> </ul>	PCODE <b>EF03NT</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>C.T.P.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign designating a permanent room or space does not include Grade 2 Braille.</li> <li>• <i>Proposed Solution:</i> Provide new compliant signage including California Grade 2 Braille.</li> </ul>	PCODE <b>SA07A</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>7.1</b>

Location: **Willits 400 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-22-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Otherwise compliant sign identifying permanent room or space not mounted 5' high to center on nearest adjacent wall, on latch side if a single door (located not to cause a Braille reader to stand within the door)</li> <li>• <i>As-is Measurement:</i> 65"</li> <li>• <i>Proposed Solution:</i> Relocate existing sign.</li> </ul>	PCODE <b>SA07</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign designating a permanent room or space does not include Grade 2 Braille.</li> <li>• <i>Proposed Solution:</i> Provide new compliant signage including California Grade 2 Braille.</li> </ul>	PCODE <b>SA07A</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Otherwise compliant sign identifying permanent room or space not mounted 5' high to center on nearest adjacent wall, on latch side if a single door (located not to cause a Braille reader to stand within the door)</li> <li>• <i>As-is Measurement:</i> 65"</li> <li>• <i>Proposed Solution:</i> Relocate existing sign.</li> </ul>	PCODE <b>SA07</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wall- and post-mounted cantilevered units: Knee space not provided at drinking fountain (27" high, 8" deep, 30" wide from front of drinking fountain).</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Provide new, accessible fountain.</li> </ul>	PCODE <b>IA02</b> ADAAG <b>4.15.5(1)</b> CSAS <b>1507.3.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,850	\$1,850	7.1

Location: **Willits 400 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-22-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 0.5"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$200	\$400	7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Multiple accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 188" x 122"</li> <li>• <i>Proposed Solution:</i> Barrier will be mitigated with the planned museum addition in 2001. Provide directional signage to accessible restrooms once construction is completed. Interim solution: Provide directional signage, and assistance when needed. to</li> </ul>	PCODE <b>WA01ANT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.1</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$200	\$200	7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Multiple accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 188" x 122"</li> <li>• <i>Proposed Solution:</i> Barrier will be mitigated with the planned museum addition in 2001. Provide directional signage to accessible restrooms once construction is completed. Interim solution: Provide directional signage, and assistance when needed. to</li> </ul>	PCODE <b>WA01ANT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.1</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$200	\$200	7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Path of travel less than 36" wide (32" allowed for a length of 24" max. at doorways).</li> <li>• <i>Proposed Solution:</i> Enlarge width to 36".</li> </ul>	PCODE <b>EF08ANT</b> ADAAG <b>4.3.3</b> CSAS <b>1133B.7.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exhibit display and accompanying text is not accessible.</li> <li>• <i>Proposed Solution:</i> Recommended: Install displays and text at 36"-39" height or angle display to be visible and accessible to persons in wheelchairs.</li> </ul>	PCODE <b>SA13NT</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Department Head</b>	1	JOB	\$90	\$90	1.1

Location: **Willits 189 N. Main Street**Bldg Name: **Main**Floor: **Bsmt**ID No: **10-25-1-0**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign by inaccessible route directing persons to an accessible route.</li> <li>• <i>Proposed Solution:</i> Provide directional sign at top.</li> </ul>	PCODE <b>SA20NT</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$170	\$170	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: Side slopes more than 1:10 (10%).</li> <li>• <i>As-is Measurement:</i> 30%</li> <li>• <i>Proposed Solution:</i> Modify curb ramp. Demolish side slopes and replace with 1:10 side slopes if 48" level top landing is provided.</li> </ul>	PCODE <b>EH05ANT</b> ADAAG <b>4.7.5</b> CSAS <b>1127B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 10%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp with handrails.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	30	SF	\$100	\$3,000	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates vertical change in level between 1/4" and 1/2" in accessible route.</li> <li>• <i>As-is Measurement:</i> 0.75"</li> <li>• <i>Proposed Solution:</i> Grind or fill pavement dislocation to create beveled transition.</li> </ul>	PCODE <b>EF03A</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	4	SF	\$21	\$84	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates vertical change in level between 1/4" and 1/2" in accessible route.</li> <li>• <i>As-is Measurement:</i> 0.75"</li> <li>• <i>Proposed Solution:</i> Grind or fill pavement dislocation to create beveled transition.</li> </ul>	PCODE <b>EF03A</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	4	LF	\$21	\$84	<b>9.1</b>

Location: **Ukiah 579 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-26-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li><i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>9.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li><i>As-is Measurement:</i> 15 lbs.</li> <li><i>Proposed Solution:</i> The following work has been completed: Deactivate existing closer and provide new door closer adjusted to accessible standards.</li> </ul>	PCODE <b>ID03ANT</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>N/A</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>1.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Double-Gate at the end of counter provides less than 32" clear opening width when fully opened.</li> <li><i>As-is Measurement:</i> 31"</li> <li><i>Proposed Solution:</i> Remove gate and trim. Remodel wall and counter as needed</li> </ul>	PCODE <b>ID22A</b> ADAAG <b>4.13.5</b> CSAS <b>1133B.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>9.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li><i>As-is Measurement:</i> 44"</li> <li><i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>9.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li><i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>

Location: **Ukiah 579 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-26-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Remove or relocate furniture or storage items.</li> </ul>	PCODE <b>ID14A</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No portable assistive listening system provided for small meeting room.</li> <li>• <i>Proposed Solution:</i> Share existing portable assistive listening system from other facility.</li> </ul>	PCODE <b>G101EREF</b> ADAAG <b>4.1.3 (19) (b)</b> CSAS <b>1104B.2</b> MoM <b>E. F.</b> O/R <b>County ADA Coordinator</b>		REF			<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Paper towel dispenser more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 47"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>E. F.</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Pair of doors on accessible route has less than 32" clear opening width with one leaf open 90°.</li> <li>• <i>As-is Measurement:</i> 27"</li> <li>• <i>Proposed Solution:</i> Provide new, unequal width door leaves in existing frame for pair of doors.</li> </ul>	PCODE <b>ID08AREF</b> ADAAG <b>4.13.4</b> CSAS <b>1133B.2.3.1</b>		REF			<b>9.1</b>



Location: **Ukiah 579 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-26-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 0.75"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02REF</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b>		REF			<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At facility with a smoke alarm system, visual signal (strobe) not provided at required type of common use area.</li> <li>• <i>Proposed Solution:</i> Provide combination visual / audible signal device connected to existing smoke alarm system. As an interim solution, advise staff to follow county emergency procedures regarding the evacuation of people with disabilities.</li> </ul>	PCODE <b>IC05NT</b> ADAAG <b>4.1.3(14) &amp; 4.28.3</b> CSAS <b>1114B.2.4</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>

Location: **Ukiah 579 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-26-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 114" x 68"</li> <li>• <i>Proposed Solution:</i> Remodel area to provide single-occupant accessible restroom.</li> </ul>	PCODE <b>WA01REF</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b>		REF			<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>9.1</b>

Location: **Ukiah 579 Low Gap Road**Bldg Name: **Main**Floor: **1**ID No: **9-26-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> FTD: 54"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>Proposed Solution:</i> Provide wheelchair clearance space in restroom. Remove partitions and remodel area as needed.</li> </ul>	PCODE <b>WC01NT</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>9.1</b>

Location: **Ukiah 579 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-26-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Self-closing faucet at accessible lavatory does not remain open for at least 10 seconds.</li> <li>• <i>Proposed Solution:</i> Adjust self-closing faucet at accessible lavatory.</li> </ul>	PCODE <b>WD07</b> ADAAG <b>4.19.5</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 90" x 65"</li> <li>• <i>Proposed Solution:</i> As an interim solution convert facility into an accessible unisex restroom until Women's is remodeled.</li> </ul>	PCODE <b>WA01NT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>9.1</b>

Location: **Ukiah 579 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-26-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 59" from back wall to front wall or door swing of toilet stall, or less than 56" if water closet is wall-hung (CA only: Less than 48" from front of water closet to door in front entry stall).</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Existing facility modification not feasible.</li> </ul>	PCODE <b>WB03REF</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.2</b>		REF			<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 24"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>Proposed Solution:</i> Provide wheelchair clearance space in restroom. Remove partition and remodel area as needed.</li> </ul>	PCODE <b>WC0INT</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li>• <i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>

Location: **Ukiah 579 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-26-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door opening less than 32" clear (CA only: ...or less than 34" at side entry door).</li> <li>• <i>As-is Measurement:</i> 23"</li> <li>• <i>Proposed Solution:</i> Remove stall. Remodel floor and walls as needed.</li> </ul>	PCODE <b>WB05AREF</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b>		REF			<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB06A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Self-closing faucet at accessible lavatory does not remain open for at least 10 seconds.</li> <li>• <i>Proposed Solution:</i> Adjust self-closing faucet at accessible lavatory.</li> </ul>	PCODE <b>WD07</b> ADAAG <b>4.19.5</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>9.1</b>

Location: **Ukiah 579 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-26-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Double-Gate at the end of counter provides less than 32" clear opening width when fully opened.</li> <li>• <i>As-is Measurement:</i> 31"</li> <li>• <i>Proposed Solution:</i> Remove gate and trim. Remodel wall and counter as needed</li> </ul>	PCODE <b>ID22A</b> ADAAG <b>4.13.5</b> CSAS <b>1133B.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 44"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door inaccessible due to threshold or step at door more than 1" high, up to 6" high.</li> <li>• <i>As-is Measurement:</i> 4"</li> <li>• <i>Proposed Solution:</i> Provide small portable ramp.</li> </ul>	PCODE <b>ID02BNT</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$375	\$375	<b>10.1</b>

Location: **Point Arena 255 Main Street #2**Bldg Name: **Main**Floor: **2**ID No: **8-382-1-2**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 18" from near side wall to center line of water closet (proposed new ADAAG: 16"-18").</li> <li>• <i>As-is Measurement:</i> 14"</li> <li>• <i>Proposed Solution:</i> Relocate existing water closet.</li> </ul>	PCODE <b>WB02C</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates vertical change in level between 1/4" and 1/2" in accessible route.</li> <li>• <i>Proposed Solution:</i> Grind or fill pavement dislocation to create beveled transition. Interim solution: Provide sign as itemized.</li> </ul>	PCODE <b>EF03ANT</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	12	SF	\$21	\$252	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29.5"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min`).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>10.1</b>



Location: **Ukiah 880 N. Bush Street**

Bldg Name: **Public Health Annex**

Floor: **1**

ID No: **9-35-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29.5"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29.5"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29.5"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29.5"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>10.1</b>

Location: **Ukiah 880 N. Bush Street**

Bldg Name: **Public Health Annex**

Floor: **1**

ID No: **9-35-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29.5"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29.5"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>

Location: **Ukiah 890 N. Bush Street**Bldg Name: **Public Health Office**Floor: **1**ID No: **9-36-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>

Location: **Ukiah 890 N. Bush Street**Bldg Name: **Public Health Office**Floor: **1**ID No: **9-36-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible parking space does not have painted 5' x 18' access aisle (van accessible aisle 8' x 18').</li> <li>• <i>Proposed Solution:</i> Provide striped access aisles adjacent to accessible parking spaces.</li> </ul>	PCODE <b>EA02B</b> ADAAG <b>4.6.3</b> CSAS <b>1129B.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	3	JOB	\$200	\$600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign for van parking provided.</li> <li>• <i>Proposed Solution:</i> Provide van sign.</li> </ul>	PCODE <b>EA07NT</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sign, wall mounted, for accessible parking space is not compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$175	\$175	<b>9.1</b>

Location: Ukiah 340 Mendocino Lake Drive

Bldg Name: Site

Floor: 1

ID No: 9-37-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At landing: Pavement dislocation creates abrupt change in level exceeding 1/2".</li> <li>• <i>As-is Measurement:</i> 0"-2"</li> <li>• <i>Proposed Solution:</i> Remove, replace or repair area of pavement sufficient to correct abrupt change in level.</li> </ul>	PCODE <b>EB04NT</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	22	SF	\$9	\$198	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table, and staff assistance as equivalent facilitation. Remodel counter when altering area.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>As-is Measurement:</i> 11"</li> <li>• <i>Proposed Solution:</i> Interim solution: Keep door fully open (90°) during business hours.</li> </ul>	PCODE <b>ID14BNT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$0		<b>9.1</b>

Location: Ukiah 340 Mendocino Lake Drive

Bldg Name: Main

Floor: 1

ID No: 9-37-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door inaccessible due to threshold or step at door more than 1" high, up to 6" high.</li> <li>• <i>As-is Measurement:</i> 2.5"</li> <li>• <i>Proposed Solution:</i> Remove existing paving at door and provide landing with edge ramping as needed.</li> </ul>	PCODE ID02A ADAAG 4.13.8 CSAS 1133B.2.4.1 MoM P. A. (Contractor) O/R Manager B&G 2	40	SF	\$12	\$480	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Staff restroom not accessible. No wheelchair accessible route to second floor.</li> <li>• <i>Proposed Solution:</i> Provide one accessible unisex restroom on ground floor for use by general public.</li> </ul>	PCODE WA01NT ADAAG 4.22 CSAS 1115B.7.2 MoM P. A. (Contractor) O/R Manager B&G 2	1	JOB	\$15,000	\$15,000	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Staff restroom not accessible. No wheelchair accessible route to second floor.</li> <li>• <i>Proposed Solution:</i> Interim solution: Provide temporary signage in lobby ("No public restroom provided in this building") until public restrooms are provided.</li> </ul>	PCODE WA01NT MoM P. M. O/R Department Head	1	JOB	\$20	\$20	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Second floor not wheelchair accessible.</li> <li>• <i>Proposed Solution:</i> Relocate meetings to accessible conference room on ground floor when needed.</li> </ul>	PCODE IN02NT ADAAG 4.32.3 & .4 CSAS 1122B.3 & 4 MoM P. M. O/R Department Head	1	JOB			9.1

Location: Ukiah 631 S. Orchard Avenue

Bldg Name: Main

Floor: 1

ID No: 9-363-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At push side of framed glass or panel door on accessible route, bottom 10" does not have a smooth, uninterrupted surface (required in CA only).</li> <li>• <i>Proposed Solution:</i> Remove door stopper.</li> </ul>	PCODE <b>ID06NT</b> CSAS <b>1133B.2.6</b> MoM <b>P. A.</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$50	\$50	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> This residential type, 2-story building is not accessible to people with mobility impairments due to its location at a hilly site.</li> <li>• <i>Proposed Solution:</i> Consider relocating the program to an accessible facility or advise staff to conduct house visits if needed (see also facility report # 372).</li> </ul>	PCODE <b>ID04NT</b> ADAAG <b>4.14.1</b> CSAS <b>1134B.2.1</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04B</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$175	\$175	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope not steep but greater than 1:20 (5.0 %) without handrails.</li> <li>• <i>As-is Measurement:</i> 6%</li> <li>• <i>Proposed Solution:</i> Provide steel handrails for ramp.</li> </ul>	PCODE <b>EB03</b> ADAAG <b>4.8.1*</b> CSAS <b>1133B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	40	LF	\$75	\$3,000	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	20	LF	\$95	\$1,900	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directions posted at inaccessible entrance.</li> <li>• <i>Proposed Solution:</i> Provide sign directing people to the accessible entrance.</li> </ul>	PCODE <b>SA18</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	1.1

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Site**

Floor: **1**

ID No: **9-38-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	10	LF	\$95	\$950	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Recommended guardrail (42" high) not provided at side of ramp or landing where drop-off to adjacent grade or floor exceeds 30" height (California building code requirement only).</li> <li>• <i>Proposed Solution:</i> Provide new guardrail, including handrail at ramp.</li> </ul>	PCODE <b>ED08</b> ADAAG <b>4.8.7</b> CSAS <b>CBC 509</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	15	LF	\$120	\$1,800	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$125	\$250	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 17 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>5.1</b>



Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 9 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 27"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01NT</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>5.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Front approach: less than 60" clear space perpendicular to closed door at swing side.</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Demolish partition and patch finishes.</li> </ul>	PCODE <b>ID15NT</b> ADAAG <b>Fig. 25</b> CSAS <b>1133B.2.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Finishes within medium sized restroom demolished during accessibility remodeling project.</li> <li>• <i>As-is Measurement:</i> 164" x 90"</li> <li>• <i>Proposed Solution:</i> Provide new tiled surfaces on portions of walls and floor as required by remodeling. Provide gypsum board finish as required and repaint walls and ceiling.</li> </ul>	PCODE <b>WA02A</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,000	\$4,000	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 32"</li> <li>• <i>Proposed Solution:</i> Provide new accessible stall and relocate urinal and lavatory.</li> </ul>	PCODE <b>WB06NT</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,500	\$2,500	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> 30" x 48" clear floor space in front of accessible urinal not provided.</li> <li>• <i>Proposed Solution:</i> Provide clear floor space in front of accessible urinal. Remodel restroom as needed.</li> </ul>	PCODE <b>WE04REF</b> ADAAG <b>4.18.3</b> CSAS <b>1115B.9.4</b>		REF			<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>5.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$50	\$100	<b>5.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Front approach: less than 60" clear space perpendicular to closed door at swing side.</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Demolish partition and patch finishes.</li> </ul>	PCODE <b>ID15NT</b> ADAAG <b>Fig. 25</b> CSAS <b>1133B.2.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 27"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 8 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>5.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Finishes within medium sized restroom demolished during accessibility remodeling project.</li> <li>• <i>As-is Measurement:</i> 164" x 90"</li> <li>• <i>Proposed Solution:</i> Provide new tiled surfaces on portions of walls and floor as required by remodeling. Provide gypsum board finish as required and repaint walls and ceiling.</li> </ul>	PCODE <b>WA02A</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,000	\$4,000	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 32"</li> <li>• <i>Proposed Solution:</i> Provide new accessible stall and relocate urinal and lavatory.</li> </ul>	PCODE <b>WB06</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> 30" x 48" clear floor space in front of accessible urinal not provided.</li> <li>• <i>Proposed Solution:</i> Provide clear floor space in front of accessible urinal. Remodel restroom as needed.</li> </ul>	PCODE <b>WE04</b> ADAAG <b>4.18.3</b> CSAS <b>1115B.9.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>5.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$50	\$150	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 48"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$50	\$150	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Front approach: less than 60" clear space perpendicular to closed door at swing side.</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Demolish partition and patch finishes.</li> </ul>	PCODE <b>ID15NT</b> ADAAG <b>Fig. 25</b> CSAS <b>1133B.2.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>2.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Front approach: less than 60" clear space perpendicular to closed door at swing side.</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Demolish partition and patch finishes.</li> </ul>	PCODE <b>ID15NT</b> ADAAG <b>Fig. 25</b> CSAS <b>1133B.2.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Finishes within medium sized restroom demolished during accessibility remodeling project.</li> <li>• <i>As-is Measurement:</i> 164" x 92"</li> <li>• <i>Proposed Solution:</i> Provide new tiled surfaces on portions of walls and floor as required by remodeling. Provide gypsum board finish as required and repaint walls and ceiling.</li> </ul>	PCODE <b>WA02A</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,000	\$4,000	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 18" from near side wall to center line of water closet (proposed new ADAAG: 16"-18").</li> <li>• <i>As-is Measurement:</i> 15"</li> <li>• <i>Proposed Solution:</i> Remove fixture at backwall. Middle fixture to remain.</li> </ul>	PCODE <b>WB02NT</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 18" from near side wall to center line of water closet (proposed new ADAAG: 16"-18").</li> <li>• <i>As-is Measurement:</i> 15"</li> <li>• <i>Proposed Solution:</i> Remove fixture at backwall. Middle fixture to remain.</li> </ul>	PCODE <b>WB02NT</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Finishes within medium sized restroom demolished during accessibility remodeling project.</li> <li>• <i>As-is Measurement:</i> 164" x 92"</li> <li>• <i>Proposed Solution:</i> Provide new tiled surfaces on portions of walls and floor as required by remodeling. Provide gypsum board finish as required and repaint walls and ceiling.</li> </ul>	PCODE <b>WA02A</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,000	\$4,000	<b>5.1</b>



Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 33"</li> <li>• <i>Proposed Solution:</i> Provide new accessible stall. Provide new accessible stall and relocate lavatory.</li> </ul>	PCODE <b>WB06</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Toilet stall less than 60" wide.</li> <li>• <i>As-is Measurement:</i> 33"</li> <li>• <i>Proposed Solution:</i> Provide new accessible stall. Provide new accessible stall and relocate lavatory.</li> </ul>	PCODE <b>WB06</b> ADAAG <b>4.17.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,500	\$1,500	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>5.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Flush Control: Operating handle not mounted toward wide side of stall, mounted more than 44" above floor and/or requires more than 5 lbs. force to operate.</li> <li><i>Proposed Solution:</i> Replace flush control with properly mounted accessible type.</li> </ul>	PCODE <b>WB10</b> ADAAG <b>4.16.5 &amp; 4.27.4</b> CSAS <b>1502.0</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>5.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li><i>As-is Measurement:</i> 28.5"</li> <li><i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>5.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li><i>As-is Measurement:</i> 28.5"</li> <li><i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>5.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li><i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>5.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li><i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>5.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Interior door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 46"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>5.1</b>

Location: **Ukiah 951 Low Gap Road**

Bldg Name: **Main**

Floor: **1**

ID No: **9-38-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 29"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	2	JOB	\$25	\$50	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Service Counter (Stand-up): Accessible section min. 36" length and 36" max. height (in CA: 28" to 34" high) not provided.</li> <li>• <i>As-is Measurement:</i> 41"</li> <li>• <i>Proposed Solution:</i> Provide auxiliary shelf, clipboard, or table as equivalent facilitation.</li> </ul>	PCODE <b>IN03</b> ADAAG <b>7.2(3)</b> CSAS <b>1122B.4</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$150	\$150	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Emergency door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>

Location: **Willits 1784/1788 S. Main Street** Bldg Name: **Portable** Floor: **1** ID No: **10-321-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware. Interim solution: Keep door fully open (90°) during business hours.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>Proposed Solution:</i> Change door swing. Interim solution: Keep door fully open (90°) during business hours.</li> </ul>	PCODE <b>ID14</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$460	\$460	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 26"</li> <li>• <i>Proposed Solution:</i> Provide new, larger sliding door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID0INT</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07REF</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Required in CA only: identification symbol centered 60" high on sanitary facility door not provided (women: 12" ø circle, men: 12" triangle, unisex: combined symbol).</li> <li>• <i>Proposed Solution:</i> Provide properly mounted sanitary facility symbol when altering area. If wheelchair accessible, include international symbol of accessibility on sign.</li> </ul>	PCODE <b>SA15</b> CSAS <b>1115B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>2.1</b>

Location: **Willits 1784/1788 S. Main Street**Bldg Name: **Portable**Floor: **1**ID No: **10-321-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Otherwise compliant sign identifying permanent room or space not mounted 5' high to center on nearest adjacent wall, on latch side if a single door (located not to cause a Braille reader to stand within the door)</li> <li>• <i>Proposed Solution:</i> Relocate existing sign.</li> </ul>	PCODE <b>SA07</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 28" from side of water closet to adjacent fixture.</li> <li>• <i>As-is Measurement:</i> 17"</li> <li>• <i>Proposed Solution:</i> Relocate water closet. Remodel restroom as needed.</li> </ul>	PCODE <b>WB0INT</b> ADAAG <b>Fig. 28c</b> CSAS <b>1115B.7.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,600	\$4,600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> CA only: In single-accommodation restroom less than 48" in front of water closet provided.</li> <li>• <i>As-is Measurement:</i> 37"</li> <li>• <i>Proposed Solution:</i> Remove storage cabinet to provide at least 48" in front of water closet (install overhead shelving for storage).</li> </ul>	PCODE <b>WB03AREF</b> CSAS <b>1115B.7.2</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door does not have accessible operating hardware (U-pull, flip-over or sliding lock).</li> <li>• <i>Proposed Solution:</i> Provide new accesible hardware.</li> </ul>	PCODE <b>WB05C</b> ADAAG <b>4.17.5</b> CSAS <b>1115B.7.1.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long.</li> <li>• <i>As-is Measurement:</i> 32"</li> <li>• <i>Proposed Solution:</i> Provide or relocate accessible side grab bar.</li> </ul>	PCODE <b>WB07AREF</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b>		REF			<b>8.1</b>

Location: **Willits 1784/1788 S. Main Street**

Bldg Name: **Portable**

Floor: **1**

ID No: **10-321-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No rear grab bar provided.</li> <li>• <i>Proposed Solution:</i> Provide rear grab bar.</li> </ul>	PCODE <b>WB07FREF</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>Proposed Solution:</i> Provide wheelchair clearance space in restroom. Interim solution: Until a full remodel is initiated, proceed with recommended readily achievable barrier removal.</li> </ul>	PCODE <b>WC01</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$12,000	\$12,000	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 26"</li> <li>• <i>Proposed Solution:</i> Remount compliant fixture at accessible height.</li> </ul>	PCODE <b>WD03A</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$900	\$900	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>2.1</b>

Location: **Willits 1784/1788 S. Main Street** Bldg Name: **Portable** Floor: **1** ID No: **10-321-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Hot or sharp-surfaced water/drain pipe not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover water/drain pipe.</li> </ul>	PCODE <b>WD05</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$100	\$100	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 54"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Gate does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</li> <li>• <i>Proposed Solution:</i> Provide new, 48" wide wood ramp with handrails [slope more than 1:20 (5.0%) needed].</li> </ul>	PCODE <b>EB01B</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	24	LF	\$210	\$5,040	<b>7.1</b>



Location: **Ukiah 10 Cherry Court**

Bldg Name: **Site**

Floor: **1**

ID No: **9-347-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior signage at inaccessible entrance (building "A") to provide direction to accessible entrance (building "B") is missing or noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide signage sufficient to guide persons to accessible entrances. Reschedule meeting to accessible building "B" if requested.</li> </ul>	PCODE <b>SA01</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$120	\$120	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to building "A" not accessible to persons in wheelchairs.</li> <li>• <i>Proposed Solution:</i> Advise staff to hold meetings in accessible building "B" if requested.</li> </ul>	PCODE <b>ID04NT</b> ADAAG <b>4.14.1</b> CSAS <b>1134B.2.1</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior door at entrance does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior door to deck has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	7.1

Location: **Ukiah 10 Cherry Court**

Bldg Name: **Building "B"**

Floor: **1**

ID No: **9-347-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Exterior door inaccessible due to threshold or step at door more than 1" high, up to 6" high.</li> <li>• <i>As-is Measurement:</i> 2.5"</li> <li>• <i>Proposed Solution:</i> Rebuild area of wood deck to provide compliant landing, matching floor level inside door.</li> </ul>	PCODE <b>ID02B</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	50	SF	\$12	\$600	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 28"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07REF</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b>		REF			<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 85" x 60"</li> <li>• <i>Proposed Solution:</i> Remove one fixture and remodel area to provide single-occupant accessible restroom.</li> </ul>	PCODE <b>WA01</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$9,000	\$9,000	<b>7.1</b>

Location: **Ukiah 10 Cherry Court**

Bldg Name: **Building "B"**

Floor: **1**

ID No: **9-347-2-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> CA only: Less than 32" from side of water closet to far side of stall wall or 28" to adjacent fixture.</li> <li>• <i>Proposed Solution:</i> Remove fixture adjacent to wall and provide new enclosure for accessible middle water closet.</li> </ul>	PCODE <b>WB01A</b> CSAS <b>1115B.7.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,000	\$2,000	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 18" from near side wall to center line of water closet (proposed new ADAAG: 16"-18").</li> <li>• <i>As-is Measurement:</i> 15"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet and relocate plumbing.</li> </ul>	PCODE <b>WB02REF</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b>		REF			<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE <b>WB07</b> ADAAG <b>4.17.6*</b> CSAS <b>1115B.8</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$125	\$250	<b>7.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No van parking provided (one in every 8 accessible spaces, but not less than one. 8' wide access aisle, 98" height clearance).</li> <li>• <i>Proposed Solution:</i> Provide van parking space(s) by restriping; provide van sign.</li> </ul>	PCODE <b>EA07</b> ADAAG <b>4.1.2(5)(b)</b> CSAS <b>1129B.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 43 spaces, only one accessible space is provided; 2 spaces required.</li> <li>• <i>As-is Measurement:</i> 43 T</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking space with signs including a minimum of one van space.</li> </ul>	PCODE <b>EA01B</b> ADAAG <b>4.1.2(5)*</b> CSAS <b>Tbl. 11B-6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>9.1</b>

Location: Ukiah 776 S. State Street, #102A

Bldg Name: Site

Floor: 1

ID No: 9-357-0-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li><i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE SA11 ADAAG 4.1.2(7)(d) CSAS 1117B.5.9 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$45	\$45	9.1
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li><i>As-is Measurement:</i> 12 lbs.</li> <li><i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	1.1
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li><i>As-is Measurement:</i> 1"</li> <li><i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE ID02 ADAAG 4.13.8 CSAS 1133B.2.4.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$200	\$200	9.1
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li><i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE SA12 ADAAG 4.1.2(7)(c) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	9.1
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li><i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE SA13 ADAAG 4.1.3(16)(a) CSAS 1117B.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$45	\$45	9.1

Location: **Ukiah 776 S. State Street, #102A**

Bldg Name: **Suite 102A**

Floor: **1**

ID No: **9-357-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 126" x 94"</li> <li>• <i>Proposed Solution:</i> Provide signage, directing persons in wheelchairs to the accessible public restroom.</li> </ul>	PCODE <b>WA01NT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>As-is Measurement:</i> 125" x 61"</li> <li>• <i>Proposed Solution:</i> Provide signage, directing persons in wheelchairs to the accessible public restroom.</li> </ul>	PCODE <b>WA01NT</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$250	\$250	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>3.1</b>

Location: **Ukiah 776 S. State Street, #102A**

Bldg Name: **Suite 102A**

Floor: **1**

ID No: **9-357-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li><i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>9.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> No portable assistive listening system provided for small meeting room.</li> <li><i>Proposed Solution:</i> Share existing portable assistive listening system from other facility.</li> </ul>	PCODE <b>G10IEREF</b> ADAAG <b>4.1.3 (19) (b)</b> CSAS <b>1104B.2</b> MoM <b>P. M.</b> O/R <b>County ADA Coordinator</b>		REF			<b>9.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li><i>As-is Measurement:</i> 30"</li> <li><i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>9.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li><i>As-is Measurement:</i> 30"</li> <li><i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>9.1</b>
	<ul style="list-style-type: none"> <li><i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li><i>As-is Measurement:</i> 30"</li> <li><i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>9.1</b>

Location: Ukiah 776 S. State Street, #102A

Bldg Name: Suite 102A

Floor: 1

ID No: 9-357-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Room with audible smoke alarm does not provide visual signal (strobe).</li> <li>• <i>Proposed Solution:</i> Provide combination visual / audible signal device. As an interim solution, advise staff to follow county emergency procedures regarding the evacuation of people with disabilities.</li> </ul>	PCODE <b>IC05A</b> ADAAG <b>4.28.3</b> CSAS <b>1114B.2.4</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$500	\$500	9.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Disabled persons must wheel or walk behind parked car(s) other than their own.</li> <li>• <i>Proposed Solution:</i> Relocate parking and provide curb ramp to accessible route.</li> </ul>	PCODE <b>EA03</b> ADAAG <b>Fig.9</b> CSAS <b>1129B.4.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$730	\$730	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Sidewalk: Pavement dislocation creates abrupt change in level exceeding 1/2" in accessible route.</li> <li>• <i>Proposed Solution:</i> Remove, replace or repair area of pavement sufficient to correct abrupt change in level. Coordinate with landlord.</li> </ul>	PCODE <b>EF03</b> ADAAG <b>4.5.2</b> CSAS <b>1133B.7.4</b> MoM <b>C.T.P.</b> O/R <b>General Service Director</b>	32	SF	\$45	\$1,440	10.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Landing at change of direction not at least 60"x60" (CA only: 72"x width of ramp runs).</li> <li>• <i>As-is Measurement:</i> 40"</li> <li>• <i>Proposed Solution:</i> Modify ramp bottom landing to 72" length.</li> </ul>	PCODE <b>EB08</b> ADAAG <b>4.8.4(3)</b> CSAS <b>1133B.5.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	40	SF	\$45	\$1,800	10.1

Location: **Willits 1155 S. Main Street**Bldg Name: **Site**Floor: **1**ID No: **10-366-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: No curb (2" minimum height) or wheel guide (centered approx. 3" above surface of ramp) at sides of ramp.</li> <li>• <i>As-is Measurement:</i> 4"</li> <li>• <i>Proposed Solution:</i> Lower wheel guide.</li> </ul>	PCODE <b>EB14NT</b> ADAAG <b>4.8.7</b> CSAS <b>1133B.5.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	28	LF	\$5	\$140	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: No curb (2" minimum height) or wheel guide (centered approx. 3" above surface of ramp) at sides of ramp.</li> <li>• <i>Proposed Solution:</i> Provide 2" minimum curb or wheel guide.</li> </ul>	PCODE <b>EB14</b> ADAAG <b>4.8.7</b> CSAS <b>1133B.5.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	7	LF	\$17	\$119	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wall mounted handrail gripping surface top not mounted between 34" and 38" above ramp surface or stair nosings.</li> <li>• <i>As-is Measurement:</i> 32"</li> <li>• <i>Proposed Solution:</i> Remount existing handrail.</li> </ul>	PCODE <b>ED02A</b> ADAAG <b>4.8.4(5) &amp; 4.9.4(5)</b> CSAS <b>1133B.4.2.1 &amp; B.5.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	50	LF	\$40	\$2,000	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrails not returned to wall or newel post.</li> <li>• <i>Proposed Solution:</i> Add handrail return.</li> </ul>	PCODE <b>ED13</b> ADAAG <b>4.9.4(6)</b> CSAS <b>1133B.4.2.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$230	\$230	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware. Coordinate with landlord.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway. Coordinate with landlord.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>1.1</b>



Location: **Willits 1155 S. Main Street**

Bldg Name: **Main**

Floor: **1**

ID No: **10-366-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Remove the international symbol of accessibility.</li> </ul>	PCODE <b>SA11NT</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at non-accessible room or space directing persons to an accessible that provides the same or equivalent service.</li> <li>• <i>Proposed Solution:</i> Provide directional sign to accessible unisex restroom.</li> </ul>	PCODE <b>SA19</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>3.1</b>

Location: **Willits 1155 S. Main Street**

Bldg Name: **Main**

Floor: **1**

ID No: **10-366-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Otherwise compliant sign identifying permanent room or space not mounted 5' high to center on nearest adjacent wall, on latch side if a single door (located not to cause a Braille reader to stand within the door)</li> <li>• <i>Proposed Solution:</i> Relocate existing sign.</li> </ul>	PCODE <b>SA07</b> ADAAG <b>4.30.6</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 43"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$50	\$150	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>As-is Measurement:</i> 25"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>10.1</b>

Location: **Willits 1155 S. Main Street**

Bldg Name: **Main**

Floor: **1**

ID No: **10-366-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Accessible faucet (lever-operated, push-type or electronically controlled) not provided at otherwise accessible lavatory.</li> <li>• <i>Proposed Solution:</i> Provide accessible faucet at accessible lavatory.</li> </ul>	PCODE <b>WD06</b> ADAAG <b>4.19.5</b> CSAS <b>1504.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 32" from side of water closet to far side of stall wall or 28" to adjacent fixture.</li> <li>• <i>As-is Measurement:</i> 12"</li> <li>• <i>Proposed Solution:</i> Remove adjacent urinal and partition wall. Remodel floor and walls as needed. Coordinate with landlord.</li> </ul>	PCODE <b>WB01ANT</b> ADAAG <b>Fig. 28c</b> CSAS <b>1115B.7.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,500	\$2,500	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 51"</li> <li>• <i>Proposed Solution:</i> Provide or relocate accessible side grab bar.</li> </ul>	PCODE <b>WB07ANT</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$150	\$150	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No rear grab bar provided.</li> <li>• <i>Proposed Solution:</i> Provide rear grab bar.</li> </ul>	PCODE <b>WB07F</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	<b>10.1</b>

Location: **Willits 1155 S. Main Street**Bldg Name: **Main**Floor: **1**ID No: **10-366-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$125	\$250	<b>10.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 1-25 spaces, the number of accessible spaces is less than required by code; 1 space required</li> <li>• <i>As-is Measurement:</i> 19 T</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking space with sign including a minimum of one van space. Coordinate provision with landlord.</li> </ul>	PCODE <b>EA01A</b> ADAAG <b>4.1.2(5)</b> CSAS <b>Tbl. 11B-6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>As-is Measurement:</i> 11%</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp with handrails. Interim solution: Conduct meetings in 311 or 317.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	70	SF	\$100	\$7,000	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directions posted at inaccessible entrance.</li> <li>• <i>Proposed Solution:</i> Provide sign directing people to accessible front entrance at 311.</li> </ul>	PCODE <b>SA18</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directions posted at inaccessible entrance.</li> <li>• <i>Proposed Solution:</i> Provide sign directing people to accessible entrance 311.</li> </ul>	PCODE <b>SA18</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directions posted at inaccessible entrance.</li> <li>• <i>Proposed Solution:</i> Provide sign directing people to accessible entrance 311.</li> </ul>	PCODE <b>SA18</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>1.1</b>

Location: **Ukiah 311/317/345 N. State Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-378-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$125	\$250	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> On wheelchair-accessible route, width of level and clear area on door swing side does not extend 18" past the strike side edge (CA only: 24" at exterior door).</li> <li>• <i>Proposed Solution:</i> Remove or relocate furniture or storage items.</li> </ul>	PCODE <b>ID14A</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at non-accessible room or space directing persons to an accessible that provides the same or equivalent service.</li> <li>• <i>Proposed Solution:</i> Provide directional sign.</li> </ul>	PCODE <b>SA19</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>3.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 Lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>8.1</b>

Location: Ukiah 311/317/345 N. State Street

Bldg Name: Main

Floor: 1

ID No: 9-378-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE SA12 ADAAG 4.1.2(7)(c) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	2	JOB	\$125	\$250	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 1"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE ID02 ADAAG 4.13.8 CSAS 1133B.2.4.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$200	\$200	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directions posted at inaccessible exit.</li> <li>• <i>Proposed Solution:</i> Provide sign directing people to accessible exit.</li> </ul>	PCODE SA18 ADAAG 35.163(b) CSAS 1117B.5.7 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$45	\$45	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 13 Lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	8.1

Location: Ukiah 311/317/345 N. State Street

Bldg Name: Main

Floor: 1

ID No: 9-378-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Kitchenette sink does not have knee space min. 27" high x 19" deep x 30" wide.</li> <li>• <i>Proposed Solution:</i> Remodel sink cabinet.</li> </ul>	PCODE IN06A ADAAG 4.24.3 CSAS 1117B.3 MoM P. A. (Contractor) O/R Manager B&G 2	1	JOB	\$1,850	\$1,850	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE SA11 ADAAG 4.1.2(7)(d) CSAS 1117B.5.9 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$45	\$45	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Grab bars not provided or are not code compliant.</li> <li>• <i>Proposed Solution:</i> Provide accessible grab bars.</li> </ul>	PCODE WB07 ADAAG 4.17.6* CSAS 1115B.8 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$300	\$300	3.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 55"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE WG01A ADAAG 28 CFR 35.133(a) CSAS 1115B.9.2 MoM P. A. (In-house) O/R Manager B&G 1	2	JOB	\$50	\$100	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE ID07 ADAAG 4.13.9 CSAS 1133B.2.5.1 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$125	\$125	3.1

Location: Ukiah 311/317/345 N. State Street

Bldg Name: Main

Floor: 1

ID No: 9-378-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Height of water closet seat less than 17" from floor.</li> <li>• <i>As-is Measurement:</i> 16"</li> <li>• <i>Proposed Solution:</i> Provide riser toilet seat (CA only: in alterations, riser seat may not be higher than 3").</li> </ul>	PCODE <b>WB08A</b> ADAAG <b>4.16.3</b> CSAS <b>1502.0</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$80	\$80	3.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Screws not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover sharp edges and screws.</li> </ul>	PCODE <b>WD05NT</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	3.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> In single-accommodation restroom less than 30"x48" clear at water closet provided.</li> <li>• <i>As-is Measurement:</i> 30" x 28"</li> <li>• <i>Proposed Solution:</i> Remove storage cabinet to provide at least 48" in front of water closet (install overhead shelving for storage).</li> </ul>	PCODE <b>WB03ANT</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	3.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Handrail not provided at stairs or ramp, required on both sides (not required at curb ramps or adjacent to seating areas).</li> <li>• <i>Proposed Solution:</i> Provide new handrail for each side including extensions.</li> </ul>	PCODE <b>ED01</b> ADAAG <b>4.8.5 &amp; 4.9.4</b> CSAS <b>1133B.4.1 &amp; B.5.5.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	8	LF	\$95	\$760	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	8.1



Location: **Ukiah 311/317/345 N. State Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-378-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Install off-set hinges to increase door opening to clear frame width (32" min.).</li> </ul>	PCODE <b>ID01A</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$500	\$500	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 0.75"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$200	\$200	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>

Location: **Ukiah 311/317/345 N. State Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-378-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Entrance to wheelchair accessible toilet or bathing facility not identified with the international symbol of accessibility when not all are accessible.</li> <li>• <i>Proposed Solution:</i> Provide sanitary facility sign that shows the international symbol.</li> </ul>	PCODE <b>SA11</b> ADAAG <b>4.1.2(7)(d)</b> CSAS <b>1117B.5.9</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 57"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	3	JOB	\$50	\$150	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 27.5"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware. Interim solution: Provide directional signage to accessible restroom.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Screws not insulated or covered.</li> <li>• <i>Proposed Solution:</i> Insulate or cover sharp edges and screws.</li> </ul>	PCODE <b>WD05NT</b> ADAAG <b>4.19.4</b> CSAS <b>1504.2.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>8.1</b>

Location: **Ukiah 311/317/345 N. State Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-378-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Lavatory: Self-closing faucet at accessible lavatory does not remain open for at least 10 seconds.</li> <li>• <i>Proposed Solution:</i> Replace self-closing faucet at accessible lavatory.</li> </ul>	PCODE <b>WD07A</b> ADAAG <b>4.19.5</b> CSAS <b>1504.2..1 C.P.C.</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> In single-accommodation restroom less than 30"x48" clear at water closet provided.</li> <li>• <i>As-is Measurement:</i> 38"</li> <li>• <i>Proposed Solution:</i> Remove storage cabinet to provide at least 48" in front of water closet (install overhead shelving for storage).</li> </ul>	PCODE <b>WB03ANT</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$250	\$250	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 1-25 spaces, the number of accessible spaces is less than required by code; 1 space required</li> <li>• <i>Proposed Solution:</i> See facility report # 383 for as-is measurement, solution, cost estimate, official responsible, and schedule.</li> </ul>	PCODE <b>EA01AREF</b> ADAAG <b>4.1.2(5)</b> CSAS <b>Tbl. 11B-6</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: No "Tow Away" sign at parking lot entrance (required in CA only).</li> <li>• <i>Proposed Solution:</i> See facility report # 383 for as-is measurement, solution, cost estimate, official responsible, and schedule.</li> </ul>	PCODE <b>EA04CREF</b> CSAS <b>1129B.5</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface of required maneuvering clearance at door slopes more than 1/4":12" (2.0%).</li> <li>• <i>Proposed Solution:</i> See facility report # 383 for as-is measurement, solution, cost estimate, official responsible, and schedule.</li> </ul>	PCODE <b>ID11REF</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4</b>		REF			<b>8.1</b>

Location: **Covelo 76300 Grange Street**

Bldg Name: **Main**

Floor: **1**

ID No: **2-381-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware. Consider moving program to accessible location. Coordinate with landlord.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$2,600	\$5,200	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$125	\$250	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>Proposed Solution:</i> See facility report # 383 for as-is measurement, solution, cost estimate, official responsible, and schedule.</li> </ul>	PCODE <b>WA01REF</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Single accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>Proposed Solution:</i> See facility report # 383 for as-is measurement, solution, cost estimate, official responsible, and schedule.</li> </ul>	PCODE <b>WA01REF</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.2</b>					<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> See facility report # 383 for as-is measurement, solution, cost estimate, official responsible, and schedule.</li> </ul>	PCODE <b>SA12REF</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b>		REF			<b>8.1</b>

Location: **Covelo 76300 Grange Street** Bldg Name: **Main** Floor: **1** ID No: **2-381-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directions posted at inaccessible entrance.</li> <li>• <i>Proposed Solution:</i> See facility report # 383 for as-is measurement, solution, cost estimate, official responsible, and schedule.</li> </ul>	PCODE <b>SA18REF</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Pair of doors on accessible route has less than 32" clear opening width with one leaf open 90°.</li> <li>• <i>Proposed Solution:</i> See facility report # 383 for as-is measurement, solution, cost estimate, official responsible, and schedule.</li> </ul>	PCODE <b>ID08AREF</b> ADAAG <b>4.13.4</b> CSAS <b>1133B.2.3.1</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>Proposed Solution:</i> See facility report # 383 for as-is measurement, solution, cost estimate, official responsible, and schedule.</li> </ul>	PCODE <b>ID02REF</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 1-25 spaces, the number of accessible spaces is less than required by code; 1 space required</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking space with sign including a minimum of one van space.</li> </ul>	PCODE <b>EA01A</b> ADAAG <b>4.1.2(5)</b> CSAS <b>Tbl. 11B-6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface of required maneuvering clearance at door slopes more than 1/4":12" (2.0%).</li> <li>• <i>As-is Measurement:</i> 12%</li> <li>• <i>Proposed Solution:</i> Demolish existing ramp and provide level landing (2% max) at door with sloped approach (5% max). Consider relocating program to accessible location. Coordinate with landlord.</li> </ul>	PCODE <b>ID11NT</b> ADAAG <b>4.13.6</b> CSAS <b>1133B.2.4</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	70	SF	\$45	\$3,150	<b>1.1</b>

Location: **Covelo 76300 Grange Street**

Bldg Name: **Main**

Floor: **1**

ID No: **2-383-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 25"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware. Consider relocating program to accessible location. Coordinate with landlord.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing sign designating permanent room or space is noncompliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant signage.</li> </ul>	PCODE <b>SAI3</b> ADAAG <b>4.1.3(16)(a)</b> CSAS <b>1117B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07REF</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b>		REF			8.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware. Consider relocating program to accessible location. Coordinate with landlord.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	3.1

Location: **Covelo 76300 Grange Street**

Bldg Name: **Main**

Floor: **1**

ID No: **2-383-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 32"</li> <li>• <i>Proposed Solution:</i> Provide or relocate accessible side grab bar.</li> </ul>	PCODE <b>WB07A</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 53"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Clear floor space, 30" x 48" in front of fixture, extending 19" max. under the lavatory, not provided (CA only: Less than 18" from side wall to centerline of lavatory).</li> <li>• <i>As-is Measurement:</i> 10"</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD01</b> ADAAG <b>4.19.3</b> CSAS <b>1504.2.1 C.P.C.</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No rear grab bar provided.</li> <li>• <i>Proposed Solution:</i> Provide rear grab bar.</li> </ul>	PCODE <b>WB07F</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>3.1</b>

Location: **Covelo 76300 Grange Street**Bldg Name: **Main**Floor: **1**ID No: **2-383-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 23"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE <b>WB02B</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>Proposed Solution:</i> Provide wheelchair clearance space in restroom. Remodel walls as needed. Coordinate with landlord.</li> </ul>	PCODE <b>WC01</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,200	\$1,200	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30"</li> <li>• <i>Proposed Solution:</i> Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Side grab bar less than 42" long, or starting less than 54" from rear wall (CA only: front end min 24" in front of water closet).</li> <li>• <i>As-is Measurement:</i> 32"</li> <li>• <i>Proposed Solution:</i> Provide or relocate accessible side grab bar.</li> </ul>	PCODE <b>WB07A</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>8.1</b>



Location: **Covelo 76300 Grange Street**Bldg Name: **Main**Floor: **1**ID No: **2-383-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 56"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Bottom of flat, not tilted mirror more than 40" above floor.</li> <li>• <i>As-is Measurement:</i> 50"</li> <li>• <i>Proposed Solution:</i> Relocate or provide new accessible mirror.</li> </ul>	PCODE <b>WG03</b> ADAAG <b>4.19.6</b> CSAS <b>1115B.9.1.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$75	\$75	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance under lavatory or lavatory counter front edge less than 29" high x 8" deep x 30" wide.</li> <li>• <i>Proposed Solution:</i> Provide new accessible lavatory. Remodel restroom as needed.</li> </ul>	PCODE <b>WD03</b> ADAAG <b>4.19.2</b> CSAS <b>1504.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,400	\$3,400	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No rear grab bar provided.</li> <li>• <i>Proposed Solution:</i> Provide rear grab bar.</li> </ul>	PCODE <b>WB07F</b> ADAAG <b>4.17.6</b> CSAS <b>1115B.8.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$170	\$170	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 18" from near side wall to center line of water closet (proposed new ADAAG: 16"-18").</li> <li>• <i>As-is Measurement:</i> 14"</li> <li>• <i>Proposed Solution:</i> Provide new accessible water closet and relocate plumbing.</li> </ul>	PCODE <b>WB02</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$4,600	\$4,600	<b>8.1</b>

Location: **Covelo 76300 Grange Street**Bldg Name: **Main**Floor: **1**ID No: **2-383-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Wheelchair clearance: Clear space, floor to 27" high with a diameter of 60", not provided (space 56" x 63" acceptable).</li> <li>• <i>Proposed Solution:</i> Provide wheelchair clearance space in restroom. Coordinate with landlord.</li> </ul>	PCODE <b>WC01</b> ADAAG <b>4.2.3</b> CSAS <b>1115B.7.1.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,200	\$1,200	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance.</li> </ul>	PCODE <b>SA12</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No directions posted at inaccessible entrance.</li> <li>• <i>Proposed Solution:</i> Provide sign directing people to accessible entrance.</li> </ul>	PCODE <b>SA18</b> ADAAG <b>35.163(b)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$45	\$45	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Existing threshold at door is between 3/4" and 1" or less than 3/4" but without a beveled edge at both sides.</li> <li>• <i>As-is Measurement:</i> 0.75"</li> <li>• <i>Proposed Solution:</i> Provide new or modified threshold with beveled edge at doorway.</li> </ul>	PCODE <b>ID02</b> ADAAG <b>4.13.8</b> CSAS <b>1133B.2.4.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$200	\$400	<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At parking lot with 26-50 spaces, the number of accessible spaces is less than required by code; 2 spaces required.</li> <li>• <i>Proposed Solution:</i> Provide required accessible parking spaces with signs including a minimum of one van space.</li> </ul>	PCODE <b>EA01BNT</b> ADAAG <b>4.1.2(5)*</b> CSAS <b>Tbl. 11B-6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$350	\$350	<b>5.1</b>

Location: **Ukiah 107 S. State Street**Bldg Name: **Site**Floor: **1**ID No: **9-361-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Signage: Sign (post or wall mounted), for accessible parking space is missing or non-compliant.</li> <li>• <i>Proposed Solution:</i> Provide compliant parking sign.</li> </ul>	PCODE <b>EA04BNT</b> ADAAG <b>4.6.4</b> CSAS <b>1129B.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$250	\$250	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible building entrance when not all are accessible not identified with a sign showing the international symbol of accessibility.</li> <li>• <i>Proposed Solution:</i> Provide building entrance sign that shows international symbol at accessible entrance (facing outside).</li> </ul>	PCODE <b>SA12NT</b> ADAAG <b>4.1.2(7)(c)</b> CSAS <b>1117B.5.7</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door on accessible route has less than 32" clear opening width when 90° open (CA only:...or has leaf size less than 36" wide or 80" high).</li> <li>• <i>As-is Measurement:</i> 30.5"</li> <li>• <i>Proposed Solution:</i> Door is operated by staff only. Provide new, larger door and frame with new accessible hardware.</li> </ul>	PCODE <b>ID01</b> ADAAG <b>4.13.5</b> CSAS <b>1003.3.1.3a</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$2,600	\$2,600	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide lever handle or other accessible hardware at staff operated public door.</li> </ul>	PCODE <b>ID07</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$125	\$125	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 15 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$25	\$25	<b>2.1</b>

Location: Ukiah 107 S. State Street

Bldg Name: Main

Floor: 1

ID No: 9-361-1-1

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Stall door to accessible compartment not self closing.</li> <li>• <i>Proposed Solution:</i> Adjust or install hinge closer.</li> </ul>	PCODE WB05B ADAAG 4.22.4 CSAS 1115B.7.1.4 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$100	\$100	2.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SD: 43"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE WG01A ADAAG 28 CFR 35.133(a) CSAS 1115B.9.2 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$50	\$50	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 21"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE WB02B ADAAG 4.17.3 CSAS 1115B.7.1.3 MoM P. A. (In-house) O/R Manager B&G 2	1	JOB	\$1,000	\$1,000	5.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 12 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE ID03 ADAAG 4.13.10 & 11 CSAS 1133B.2.5 MoM P. A. (In-house) O/R Manager B&G 1	1	JOB	\$25	\$25	2.1

Location: **Ukiah 107 S. State Street**

Bldg Name: **Main**

Floor: **1**

ID No: **9-361-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Front approach: Required clear space perpendicular to closed door at swing side not provided.</li> <li>• <i>As-is Measurement:</i> 42"</li> <li>• <i>Proposed Solution:</i> Remove or relocate storage items or furniture.</li> </ul>	PCODE <b>ID15ANT</b> ADAAG <b>Fig. 25</b> CSAS <b>1133B.2.4.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> PTD: 44"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>5.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 19.5"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE <b>WB02B</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$600	\$600	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> At push side of framed glass or panel door on accessible route, bottom 10" does not have a smooth, uninterrupted surface (required in CA only).</li> <li>• <i>Proposed Solution:</i> Remove door stopper when altering area. Provide rubber wedge.</li> </ul>	PCODE <b>ID06A</b> CSAS <b>1133B.2.6</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$75	\$75	<b>9.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Witness stand does not have at least one accessible wheelchair space within witness area.</li> <li>• <i>Proposed Solution:</i> Modify witness stand to provide proper knee clearance.</li> </ul>	PCODE <b>JA03NT</b> ADAAG <b>11.2.1(2)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1		\$800	\$800	<b>4.1</b>

Location: **Ukiah 860 N. Bush Street**Bldg Name: **Site**Floor: **1**ID No: **9-49-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Accessible parking space has slope greater than 1/4":12" (2%).</li> <li>• <i>Proposed Solution:</i> See report for facility # 28 for all parking and additional site issues.</li> </ul>	PCODE <b>EA05REF</b> ADAAG <b>4.6.3</b> CSAS <b>1129B.4.4</b>		REF			<b>8.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at non-accessible room or space directing persons to an accessible that provides the same or equivalent service.</li> <li>• <i>Proposed Solution:</i> Provide directional sign to indicate location of accessible restroom in Public Defender's office.</li> </ul>	PCODE <b>SA19</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$90	\$90	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> No sign at non-accessible room or space directing persons to an accessible that provides the same or equivalent service.</li> <li>• <i>Proposed Solution:</i> Provide directional sign to indicate location of accessible restroom in Public Defender's office.</li> </ul>	PCODE <b>SA19</b> ADAAG <b>35.163(b)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$90	\$90	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open door and/or door closing time of less than 3 seconds.</li> <li>• <i>As-is Measurement:</i> 6 lbs.</li> <li>• <i>Proposed Solution:</i> Adjust regular door closer to accessible standards (5 lbs for interior or 8.5 lbs for exterior doors).</li> </ul>	PCODE <b>ID03</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$40	\$40	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Main entrance and drop-box not designated with appropriate sign.</li> <li>• <i>Proposed Solution:</i> Provide signs reading "If you are disabled and need assistance during regular business hours, you may signal for such assistance by beeping your horn two short times."</li> </ul>	PCODE <b>SA17</b> ADAAG <b>35.163(a)</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	2	JOB	\$110	\$220	<b>1.1</b>

Location: **Fort Bragg 790 S. Franklin**

Bldg Name: **Site**

Floor: **1**

ID No: **3-7-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Public entrance not accessible to disabled persons.</li> <li>• <i>Proposed Solution:</i> As an interim solution install door bell at an accessible location to ring for assistance.</li> </ul>	PCODE <b>ID04A</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Public entrance not accessible to disabled persons.</li> <li>• <i>Proposed Solution:</i> As an interim solution install door bell at an accessible location to ring for assistance.</li> </ul>	PCODE <b>ID04A</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Intentionally blank.</li> <li>• <i>Proposed Solution:</i></li> </ul>	PCODE <b>N/A</b> MoM <b>N/A</b>					<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> More than 18" from near side wall to center line of water closet.</li> <li>• <i>As-is Measurement:</i> 20.5"</li> <li>• <i>Proposed Solution:</i> Fur out sidewall with 60" x 60" panel to provide 18" dimension. Install grab bar and recess toilet paper dispenser.</li> </ul>	PCODE <b>WB02B</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.1.3</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>6.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Public entrance not fully accessible to disabled persons due to a 4.6% slope at door landing.</li> <li>• <i>Proposed Solution:</i> As an interim solution install door bell at an accessible location to ring for assistance.</li> </ul>	PCODE <b>ID04A</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Less than 59" from back wall to front wall (CA only: Less than 48" from front of water closet to facing wall).</li> <li>• <i>As-is Measurement:</i> 52"</li> <li>• <i>Proposed Solution:</i> Remove storage cabinet to provide at least 48" in front of water closet (install overhead shelving for storage).</li> </ul>	PCODE <b>WB03NT</b> ADAAG <b>4.17.3</b> CSAS <b>1115B.7.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	<b>4.1</b>

Location: **Point Arena 24000 S. Highway 1**Bldg Name: **Site**Floor: **1**ID No: **8-20-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Curb ramp: Less than 48" level space at top and 1:12 flared sides not provided.</li> <li>• <i>As-is Measurement:</i> 2"</li> <li>• <i>Proposed Solution:</i> Bevel transition with asphalt.</li> </ul>	PCODE <b>EH05CNT</b> ADAAG <b>4.7.5; Fig.12(a)</b> CSAS <b>1127B.5.4</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Book deposit handle or deposit slot mounted higher than 54" above floor or walkway where side approach is possible.</li> <li>• <i>As-is Measurement:</i> 56"</li> <li>• <i>Proposed Solution:</i> Modify/remount book deposit unit at accessible height. Interim solution: Modify return policy for people using wheelchairs.</li> </ul>	PCODE <b>BE04</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.5</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$1,000	\$1,000	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Dispensers in sanitary facilities, such as for towels, soap, sanitary napkins, seat covers, etc., and waste receptacles more than 40" from floor to highest operating slot or control.</li> <li>• <i>As-is Measurement:</i> SCD: 43"</li> <li>• <i>Proposed Solution:</i> Relocate existing restroom accessories.</li> </ul>	PCODE <b>WG01A</b> ADAAG <b>28 CFR 35.133(a)</b> CSAS <b>1115B.9.2</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$50	\$50	<b>3.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Multiple accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>Proposed Solution:</i> As an interim solution install directional signage to accessible restrooms, located in the Library building next door, until museum addition is completed. Advise staff to provide assistance when needed and obtain Library key for any afterhours</li> </ul>	PCODE <b>WA01A</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.1</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$200	\$200	<b>2.1</b>



Location: **Willits 400 E. Commercial Street**Bldg Name: **Main**Floor: **1**ID No: **10-22-1-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Multiple accommodation restroom not accessible; multiple compliance violations.</li> <li>• <i>Proposed Solution:</i> As an interim solution install directional signage to accessible restrooms, located in the Library building next door, until museum addition is completed. Advise staff to provide assistance when needed and obtain Library key for any afterhours</li> </ul>	PCODE <b>WA01A</b> ADAAG <b>4.22</b> CSAS <b>1115B.7.1</b> MoM <b>E. F.</b> O/R <b>Department Head</b>	1	JOB	\$200	\$200	<b>2.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Book deposit handle or deposit slot mounted higher than 54" above floor or walkway where side approach is possible.</li> <li>• <i>As-is Measurement:</i> 57"</li> <li>• <i>Proposed Solution:</i> Modify return policy for people using wheelchairs.</li> </ul>	PCODE <b>BE04NT</b> ADAAG <b>4.2.6</b> CSAS <b>1118B.5</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	<b>1.1</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide accessible locking device at entry door (flip-latch ok) when converting restroom into single accommodation.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$250	\$250	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Door does not have accessible operating hardware.</li> <li>• <i>Proposed Solution:</i> Provide accessible locking device at entry door (flip-latch ok) when converting restroom into single accommodation.</li> </ul>	PCODE <b>ID07NT</b> ADAAG <b>4.13.9</b> CSAS <b>1133B.2.5.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 1</b>	1	JOB	\$250	\$250	<b>1.2</b>
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Doors do not automatically stop and reopen when obstructed.</li> <li>• <i>Proposed Solution:</i> Provide opening device with sensors at 5" and 29" height.</li> </ul>	PCODE <b>IK02A</b> ADAAG <b>4.10.6</b> MoM <b>P. A. (Contractor)</b> O/R <b>General Service Director</b>	1	JOB	\$7,000	\$7,000	<b>5.1</b>

Location: **Ukiah 880 N. Bush Street**

Bldg Name: **Site**

Floor: **1**

ID No: **9-35-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Surface of required maneuvering clearance at door slopes more than 1/4":12" (2.0%).</li> <li>• <i>Proposed Solution:</i> As an interim solution install door bell at an accessible location to ring for assistance.</li> </ul>	PCODE <b>ID04ANT</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$300	\$300	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</li> <li>• <i>Proposed Solution:</i> As an interim solution advise staff to schedule meetings at an accessible location (e.g. main building)</li> </ul>	PCODE <b>EB01BNT</b> ADAAG <b>4.1.1</b> CSAS <b>1127B.1</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Excessive force required to open exterior swing door.</li> <li>• <i>As-is Measurement:</i> 10 lbs.</li> <li>• <i>Proposed Solution:</i> Adjustment to lower push force is not possible due to strong wind gusts at this location. Instead advise staff to provide assistance.</li> </ul>	PCODE <b>ID03REF</b> ADAAG <b>4.13.10 &amp; 11</b> CSAS <b>1133B.2.5</b> MoM <b>P. M.</b> O/R <b>Department Head</b>		REF			1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Adequate top and bottom landings not provided at existing ramp.</li> <li>• <i>Proposed Solution:</i> Demolish existing and provide new ramp.</li> </ul>	PCODE <b>EB07AREF</b> CSAS <b>1133B.5.4.2</b>		REF			7.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Public entrance not accessible to disabled persons.</li> <li>• <i>Proposed Solution:</i> Install door bell at accessible location adjacent to entrance and advise staff.</li> </ul>	PCODE <b>ID04</b> ADAAG <b>4.14.1</b> CSAS <b>1134B.2.1</b> MoM <b>P. A. (In-house)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$150	\$150	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> CA only: In single-accommodation restroom less than 48" in front of water closet provided.</li> <li>• <i>Proposed Solution:</i> Remove storage cabinet to provide at least 48" in front of water closet.</li> </ul>	PCODE <b>WB03AREF</b> CSAS <b>1115B.7.2</b>		REF			10.1

Location: Ukiah 199 S. School Street

Bldg Name: Main

Floor: 1

ID No: 9-364-1-2

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<p>• <i>As-Built Description:</i> No sign at non-accessible restroom directing persons to an accessible that provides the same or equivalent service.</p> <p>• <i>Proposed Solution:</i> Provide directional sign to the accessible restroom in Public Defender's offices on first floor.</p>	<p>PCODE SA19</p> <p>ADAAG 35.163(b)</p> <p>MoM P. A. (In-house)</p> <p>O/R Manager B&amp;G 1</p>	1	JOB	\$90	\$90	2.1
	<p>• <i>As-Built Description:</i> Ramp needed to provide disabled access at steps or change of level along path of travel.</p> <p>• <i>Proposed Solution:</i> Due do narrow sidewalk a ramp can not be provided. Instead advise staff to schedule meeting at an accessible location if needed, or consider moving to a more accessible location.</p>	<p>PCODE EB01ANT</p> <p>ADAAG 4.1.1</p> <p>CSAS 1127B.1</p> <p>MoM P. M.</p> <p>O/R Department Head</p>	1	JOB	\$75	\$75	1.1
	<p>• <i>As-Built Description:</i> At parking lot with 1-25 spaces, the number of accessible spaces is less than required by code; 1 space required</p> <p>• <i>Proposed Solution:</i> Provide required accessible parking space with sign including a minimum of one van space.</p>	<p>PCODE EA01A</p> <p>ADAAG 4.1.2(5)</p> <p>CSAS Tbl. 11B-6</p> <p>MoM P. A. (In-house)</p> <p>O/R Manager B&amp;G 2</p>	1	JOB	\$225	\$225	8.1
	<p>• <i>As-Built Description:</i> Public entrance not accessible to disabled persons.</p> <p>• <i>Proposed Solution:</i> Consider relocating the program to an accessible facility or advise staff to conduct house visits if needed (see also facility report # 372).</p>	<p>PCODE ID04NT</p> <p>ADAAG 4.14.1</p> <p>CSAS 1134B.2.1</p> <p>MoM P. M.</p> <p>O/R Department Head</p>	1		\$75	\$75	1.1
	<p>• <i>As-Built Description:</i> Public entrance not accessible to disabled persons.</p> <p>• <i>Proposed Solution:</i> As an interim solution, advise staff to conduct house visits if needed.</p>	<p>PCODE ID04NT</p> <p>ADAAG 4.14.1</p> <p>CSAS 1134B.2.1</p> <p>MoM P. M.</p> <p>O/R Department Head</p>	1	JOB	\$75	\$75	1.1

Location: **Willits 72 W. Commercial Avenue**

Bldg Name: **Site**

Floor: **1**

ID No: **10-374-0-1**

Item	Existing Architectural Barrier and Proposed Solution	Codes / Mitigation Info	Qty	Unit	Cost	Total	YR
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Public entrance not accessible to disabled persons.</li> <li>• <i>Proposed Solution:</i> As an interim solution, advise staff to conduct program at an accessible location or to schedule house visits if needed. Coordinate with landlord.</li> </ul>	PCODE <b>ID04NT</b> ADAAG <b>4.14.1</b> CSAS <b>1134B.2.1</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$75	\$75	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Ramp: Slope greater than 1:12 (8.3%).</li> <li>• <i>Proposed Solution:</i> As an interim solution conduct meetings in 311 or 317.</li> </ul>	PCODE <b>EB02</b> ADAAG <b>4.8.2</b> CSAS <b>1133.B.5.3</b> MoM <b>P. M.</b> O/R <b>Department Head</b>	1	JOB	\$100	\$100	1.1
	<ul style="list-style-type: none"> <li>• <i>As-Built Description:</i> Public entrance not accessible to disabled persons.</li> <li>• <i>Proposed Solution:</i> Modify entrance to be accessible. Grade entrance area at 5% max. slope, and provide level landing at doors. Consider relocating program to an accessible location.</li> </ul>	PCODE <b>ID04NT</b> ADAAG <b>4.14.1</b> CSAS <b>1134B.2.1</b> MoM <b>P. A. (Contractor)</b> O/R <b>Manager B&amp;G 2</b>	1	JOB	\$3,000	\$3,000	1.1

**Total Costs for Facility 379 1450 Knob Hill Drive \$984,904.00**